

DIMENSION BID

CTS TASK SHEET

Title	Risk Assessment Exercise				
Target Population	Field Engineers & Field Specialists				
This requirement is applicable to:	✓	JFE		FST	EOT
	✓	FE1	✓	FS1	EO1
	✓	FE2	✓	FS2	EO2
			✓	FS3	EO3
					✓

Objective:

The objective of this task is to train the employees on how to apply the principles of Risk Management to an actual operational risk situation in CT operations.

Tasks:

- Identify operational risks in a job at location
- Write a risk management plan to safely operate in the face of the identified risk
- Gain an expert comment on the risk whenever required and obtain the appropriate management approval to perform the job.

Please attach a risk management plan as an evidence.

Note:

- Exemptions are exclusively used to obtain "permission" for operations that violated the conditions of safety standard.
- Exemptions are required to be created, documented and communicated across the team to increase awareness on that particular risks.

REQUIRED EVIDENCE:

- 1 Risk Management Plan

OVERALL SCORE	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2


MENTOR / ASSESSOR's Comments & Recommendation:			
<i>Objective met. Task completed</i>			
Signature	<i>[Signature]</i>	Assessment Date	<i>15/10/2021</i>
Name	<i>KUNG WEE HAN</i>	Position	<i>TA</i>

DIMENSION BID

CTS TASK SHEET

--	--	--	--

FSM / OM Comments & Recommendation:
Task completed

Signature		Assessment Date	15/10/24
Name	RIDWAN AZIZAN	Position	FSM

No.	Key Risk	Causes/Consequences	Existing Mitigation	L	I	Current RR	New Mitigations	Action Party	Due Date	L	I	Target RR	Remark	
1 PROJECT TEAM RISK														
1	Failure to get required personnel into the country due to Visa issues	Causes	Late submission or government rejection	Unlikely	Moderate	L				Unlikely	Moderate	L		
		Consequences	Unable to get required personnel to site to perform their job				a. Consider remote support b. Consider capable local contractor to support							
2 TECHNICAL / TECHNOLOGY														
General Risk														
2	HSE incidents on the rig during drilling campaign	Causes	Lack of understanding of the area of responsibility when incident occur.	Unlikely	Moderate	L				Unlikely	Moderate	L		
			Incident not follow up properly from previous wells/operations				Share Safety Alert/HSE case lesson learnt among crew onboard during daily/weekly meeting							
			Poor HSE practice and enforcement				a. HSE awareness campaign on the rig b. To implement Wells HSE Plan (Inculcate safety culture among all personnel) c. Frequent monitoring/dedicated PCSB SSE d. Review the requirement for double-crew readiness (third-party), and ensure extra personnel for dual derrick activity e.g. extra crane operator during top hole section							
			Poor housekeeping				Frequent monitoring/dedicated PCSB SSE							
			Inexperience manpower				Implementation of CCC (competency card)							
			Fatigue due to long working hours				To implement Wells HSE Plan, i.e. Hearts & Minds (Inculcate safety culture among all personnel)							
			Improper handover between tour change				Drilling to monitor implementation of toolbox meeting/JHA/safety meeting/Risk Identification/Stop work policy (Normal SOP)							
			Crew morale due to the last well in rig sequence.				Implement HSE recognition/incentive scheme							
			Lack of communication between crew				a. Ensure Accountability Flowchart been reviewed with relevant personnel and action as required. B. To include task/Safety Monitor in list of Role Requirement for HSE procedure "Mechanical Lifting and Hoisting Standard "							
			Equipment failure				Collaborate with OEM to identify potential limits/alarms if excessive pressure occurs when extending racker arms laterally.							
			Lack of situational awareness				a. "Line of Fire" awareness and enhancement of "Situational Awareness" to the crew through heart & Mind b. Emphasis on the needs of comprehensive ToolBox Talk covering all potential hazard, not limited to high consequence hazard							
			Fall from height				a. Proper PPE, i.e., Hard Hat with chin strap fully fastened b. Proper equipment layout and escape route identification. c. Ensure guardrail to be more than 200mm horizontal distance of the edges of the scaffolding platform. d. Ensure 3-point contact for personnel movement up/down scaffolding							
			Congested area				e. Ensure escape route / access ladder available for safe evacuation. f. Where there is possibility of serious harm from a fall less than 2 meters, fall protection (Body Harness) is needed. Consideration should also be given to situations where a person may slide down on inclines surface before reaching a point at which a fall can occur.							
			Lifting activity				Compliance to PTW & Lifting plan							
3	Unsafe working condition at Rig Floor and Cantilever deck	Causes	Multiple equipment stackup (CT stack up, Slickline stack up and Pumping stack up during pumping job / tag top of RCP) with Multiple lifting activities	Possible	Moderate	M	a. Lifting plan with sequence b. Agreed footprint of the equipment on the rig floor and cantilever	a. Zaeem DB & Agus SLB b. Zaeem DB, Agus SLB, Farhan, DSV, Rig OIM	a. 30 Sep 2023 b. 1 Sep 2023	Unlikely	Moderate	L		
			Improper/insufficient PPE while working at height				a. Proper PPE, i.e., Hard Hat with chin strap fully fastened c. Ensure guardrail to be more than 200mm horizontal distance of the edges of the scaffolding platform. d. Ensure 3-point contact for personnel movement up/down scaffolding e. Ensure escape route / access ladder available for safe evacuation. g. Where there is possibility of serious harm from a fall less than 2 meters, fall protection (Body Harness) is needed. Consideration should also be given to situations where a person may slide down on inclines surface before reaching a point at which a fall can occur. h. Ensure compliance to JHA and PTW							
		Consequences	Fall from height				Ensure medic aware on the complexity of the operation	Kessler (HSE), DSV, Rig OIM	30 Sep 2023					
Cementing														
4	Failure to bump top cementing plug	Causes	Incorrect displacement calculations	Possible	Moderate	M	a. Drop calibration plug to confirm the accurate displacement volume b. Use extra fins on the wiper plug to reduce the failure of the fins	a. Myat, DSV b. Myat	a. During operation b. 1 Sep 2023	Unlikely	Moderate	L		
			Loading of cement plugs in cement head improperly				a. Have good QAQC on plug selection , storage & handling b. Ensure servicing of Cementing head / lock pin , stopper before job. c. DSV to witness loading of plug (no more than 48 hours before job)							
			Higher TOC than desired				a. Ensure to prepare for additional bits to drill out cement via CT							
		Consequences	Requirement of slickline plug to set the WAB				a. To rig up slickline and standby during cementing job for contingency run	a. Kuswanto Geowell, DSV	a. During operation					
			Potentially lower TOC behind casing				a. Perf and remedial work to be considered							

2	Fracturing the cement behind tubing during pumping operation	Causes	Uncontained fracture propagation	a. To design cement UCS higher than formation UCS b. To start pumping job once the target cement UCS has been achieved	Possible	Moderate	M				Possible	Moderate	M				
			Inflexible cement	To ensure cement is sufficiently flexible to absorb fracturing pressure without cement sheath failure.													
			Micro annulus behind tubing	To install WAB in 9-5/8" casing													
			Sustained casing pressure	To install WAB in 9-5/8" casing													
Pumping																	
5	Premature screenout	Causes	Tortuosity	a. Optimized pumping schedule and add 0.5 PPA	Unlikely	Moderate	L				Unlikely	Moderate	L				
			Pump failure	a. QA/QC surface & down hole equipment at workshop and perform rig survey. b. Dry run the whole system at base & onsite.													
			Incompetent personnel	a. Ensure experience personnel (CV review)													
			Large tubing volume causing roping effects	a. Conduct pumping hydraulic simulation to rule out roping during the main job b. Increase viscosity and pumping rate (40W gel and go to 16 bpm if necessary)													
				a. During tubing volume displacement, pump with 5 bpm or less so that any fracture creation is limited in size. b. Once tubing volume displacement completed, pump at least 16 bpm to avoid roping effect													
Consequences	Sand production		a. Agus SLB	a. During operation													
	Production deferrment		b. Agus SLB	b. During Operation													
	Facility damage																
	Loss of short string (upper zone)																
	Cost impact																
6	Acid handling	Causes	Improper handling (Transportation, storage, lifting, mixing, pumping, return, and etc)	a. Ensure adequate soda ash for neutralization process b. To ensure following the acid handling procedure including SDS Tagging and spill recovery c. Ensure personnel handling the acid are trained	Unlikely	Moderate	L				Unlikely	Moderate	L				
			HSE issue -Personnel injury, chemical spill and asset damage	a. To ensure strictly follow the acid handling procedure b. Ensure seamless communication between offshore & office team. Activate ERP. d. Ensure medic available onboard. e. To ensure the required equipment is available onboard (Eyewash station) and located near acid working f. Strictly follow PPE procedures													
7	Proppant flowback	Causes	Flow rate exceed the critical flow rate	Utilized Resin Coated Proppant (RCP) to bind and hold the proppant in place within the fracture.	Possible	Moderate	M				Unlikely	Moderate	L				
			Low formation UCS (low fracture closure pressure (FCP)														
			Multi fractures - fractures with less/different proppant packing will be easier for proppant to flowback (not packing uniformly)														
			RCP failure (not fully cured)	To model RCP curing time and properties with lab test													
			No screen to hold the proppant in place	Utilized Resin Coated Proppant (RCP) typed to bind and hold the proppant in place within the fracture													
			High production gas flow velocity	To control the drawdown at min sand failure rate (MSR) area													
			Require high rate to push dart at especially in high angle	Check fracture extension rate during step rate test, used as guideline													
			Sand control not achieved (sand production)														
Consequences	Unropped near wellbore sand face		To consider installing the TT sand screen during intervention phase	Suman	During production												
	Overflushing existing frac below when pushing dart	Pump minimum rate during dart displacement															
8	Coil tubing run issue	Causes	Coil tubing plugging	a. Do proper QA/QC tools and equipment and have upfront agreement of QA/QC requirement with contractor (by third party QA/QC engineer 3-4 weeks prior mobilization) b. Contractor have to follow the requirement in the maintenance manual/reference c. Perform SID discussion with Rig Team prior CT job.	Possible	Major	H				Unlikely	Major	M				
			Problem with measuring depth tool	a. To have proper QA/QC prior mobilization b. Contractor to provide back up measuring depth system at Rig c. To have pre-inspection prior to run													
Consequences	Broken BHA	a. Proper QA/QC prior to mobilization b. Obtain COC of BHA from contractor															
	Corroded/pitting CT	Optimize acidizing program	a. Proper QA/QC prior to mobilization b. To have WT inspection and not exceed fatigue time of CT prior mobilization c. To have back up coil tubing as per contract d. To consider CT real time thickness monitoring e. To consider new coil tubing f. To ensure CT equipment meet industry standard	a. Zaeem DB, Mifdhal b. Zaeem DB, Mifdhal c. Zaeem DB d. Zaeem DB e. Zaeem DB f. Zaeem DB, Mifdhal	a. 15 Oct 2023 b. 15 Oct 2023 c. 15 Oct 2023 d. During operation e. 15 Oct 2023 f. 15 Oct 2023												
Consequences	CT stuck	a. Utilize hydraulic shifting tool b. Use agitator and lubricant c. To have sufficient centralization in BHA d. Pre-modification of BHA conducted in workshop, not at site e. To have coil tubing fishing package ready															
	Personnel injury	a. PPE provided & fire extinguisher b. Rig to be inform & prepare for fire water pump															
9	CT No return at the surface	Causes	Loss circulation/return	a. Introduce nitrogen to lighten fluid column & increase AV b. Increase the pumping rate	Possible	Major	H				Unlikely	Major	M				
			Clogged nozzle orifice	a. Monitor circulation pressure as indication for friction at nozzle b. Install downhole filter as part of BHA configuration													
			Premature burst of rupture disc	a. Monitor circulation pressure as indication for friction at nozzle b. Establish differential pressure calculation for rupture disc													
			Insufficient annular velocity between completion tubing and CT	a. Introduce nitrogen to lighten fluid column b. Perform penetration for sand interval in low interval as reference to Basic Sediment Water (BSW) at surface. c. Introduce lifting gel in sequence during cleanout process d. Increase the pumping rate b. To perform cleanout simulation using (CIRCA) being performed and confirm ability to reach target depth												Zaeem DB, Farhan	15 Oct 2023

		Consequences	Coil Tubing stuck/ Fish UH	a. Ensure sufficient circulation bottoms up and monitor closely BSW at surface b. Check for any anomaly on the weight for dragging, set down and overpull during cleanup process c. Ensure sufficient circulation and return for a specific depth such as tubing ID reduction, inclination d. To pickup coil regularly during RH and injection e. To follow coil stuck release procedure f. To perform CT conveyance simulation and Tubing Forces Analysis using certified software to identify potential held up depth due to coil limitation				Prepare sufficient friction reducer as additive to be pumped when encountered lockup	Zaeem DB	During operation			
10	Coil tubing parted (Infill 5 - Limitless)	Causes	5. Corroded/pitting CT	a. Proper QA/QC prior to mobilization b. Optimize acidizing program c. To have WT inspection and not exceed fatigue time of CT prior mobilization d. To have back up coil tubing as per contract e. To ensure CT equipment meet industry standard	Unlikely Major	M		Planning a. To consider CT real time thickness monitoring b. To consider new coil tubing c. To ensure CT equipment meet industry standard	1. Zaeem DB 2. Zaeem DB 3. Zaeem DB, Mifdhal	1. During operation 2. 15 Oct 2023 3. 15 Oct 2023	Unlikely Major	M	
			Bolt or any object stuck at the injector gripper block (PCINO - Bukit Tua CTU Incident)	a. Proper QA/QC and maintenance record prior to mobilization b. To continuously monitor coiled tension during POOH c. Ensure to have coil life/coil fatigue ratio in good condition - min. 80%									
		Coiled tubing fishing	Ensure CT fishing package readily available onboard										
		HSE exposure	Medic available onboard at all time										
		Consequences	Prolonged operation										
11	Coil Tubing Stuck (Infill 5 - Limitless)	Causes	1. insufficient Annular Velocity	Use nitrified during clean out	Possible Major	H		a. Consider to use taper reel coil tubing - depend on availability b. Ensure to have coil life/coil fatigue ratio is in good condition - min. 80% c. Use bigger coil tubing size (2" if possible)	1. Zaeem DB 2. Zaeem DB, Mifdhal 3. Zaeem DB, Farhan	1. 15 Oct 2023 2. 15 Oct 2023 3. 15 Oct 2023	Unlikely Major	M	
			2. Improper Hivis fluid train	a. Run sufficient volume Hivis fluid train b. To perform lab test (Hivis with RCP)									
			3. Pumping and circulation interruption during clean out	a. Ensure back up pump is readily available (cement unit and rig pump) b. Dry Run the whole system at base & onsite. c. Coil tubing pump unit to have sufficient plunger size, therefore the pumping operation can be conducted in full lock up position									
		Consequences	1. Require fishing operation 2. Lost the well	Ensure CT fishing package readily available onboard N/A									
12	Coil tubing improper cleanout (Infill 5 - Limitless)	Causes	1. Coil tubing plugging	a. Do proper QA/QC for tools and equipment b. Contractor have to follow the requirement in the maintenance manual/reference c. Perform SID discussion with Rig Team prior CT job. d. Perform break circulation every certain depth using filtered/clean brine	Possible Moderate	M	Planning a. To have upfront agreement on QA/QC requirement with contractor (by third party QA/QC engineer 3-4 weeks prior mobilization)	a. Zaeem DB, Mifdhal	15 Sep 2023	Possible Moderate	M		
			3. Problem with measuring depth tool due to depth correlation malfunction	a. To have proper QA/QC prior mobilization Operation b. To have pre-inspection prior to run c. Always perform real-time depth check between digital and manual depth counter at the reel d. For cleanout / tagging reference, always flag the coil as depth reference.				a. Zaeem DB	15 Sep 2023				
			Improper cleanout pumping design, i.e. insufficient annular velocity, poorly design of hivis pill, improper BHA milling tool	a. To achieve minimum annular velocity 150 ft/min and to confirm by simulation b. To have sufficient hivis pill onboard 3 Dedicated nitrogen unit onboard c. To check and validate milling BHA, downhole mud motor specification									
		Consequences	6. Crew competency	a. To follow CCC system b. Review and screen crew CV/resume c. Stipulate the crew requirement in the contract									
			Prolonged operation	a. Resequence activities / well if possible to avoid wait on equipment									
Upper Completion													
13	Erosion of completion accessories	Causes	Pumping proppant inside completion tubing		Possible Moderate	M		a. To check the pumping parameters and RCP characteristics b. To check track record on frac job thru completion tubing c. Proper cleanout procedure during proppant cleanout	a. Hassimi SLB, Agus SLB b. Hassimi SLB c. Zaeem DB	a. 30 Sep 2023 b. 30 Sep 2023 c. 30 Sep 2023	Possible Moderate	M	
			Proppant pass thru / stuck inside the TRSV internal profile										
		Consequences	Safety valve unable to closed	To prepare safety valve exercise tool									
Limitless System													
14	Risk related to New Technology Limitless Fracturing System (Infill 5) - Unable to communicate to reservoir	Causes	Limitless frac sleeve does not open after dropping dart	a. To RH shifting tool via CT to manually shift open the frac sleeve	Possible Moderate	M		a. To prepare contingency frac sleeve to provide communication between reservoir and perform frac job b. To prepare contingency wireline (eline) perforation to provide communication between reservoir and perform frac job a. Acid available to accelerate the dissolution (to confirm via lab test) b. To prepare backup dart on board	a. Farhan b. Farhan	a. 30 Sep 2023 b. 30 Sep 2023	Possible Moderate	M	
			Dart degradation period short vs time required to execute the job until complete	Conduct dissolution test of the dart									
		Not able to open Toe sub											
		Consequences	No production from the target sand Unable to have seal off on the zone below Unable to land dart on frac sleeve	To RH shifting tool via CT to manually shift open the frac sleeve									
		Consequences	Prepare sufficient friction reducer as additive to be pumped when encountered lockup To prepare backup dart on board	Zaeem DB Sabri PG	During operation During operation								
		Consequences	Unable to land dart on frac sleeve	To prepare contingency wireline perforation	Farhan	30 Sep 2023							
15	Incompatible Limitless Surface stack up	Causes	Stack up connections does not fit with each other	a. Check availability of connection and discuss alternatives available b. Perform fit test prior to job to ensure it is compatible. c. To have an agreed surface stack up drawing by all parties involved (with the details regarding ID, OD, length, connection type and any other that's required detail.)	Possible Minor	L					Possible Minor	L	
			Unable to make up the surface equipment	Drift test using dummy dart with actual surface stack up									
		Consequences	Additional operation standby time										