


MIT Programming (EMITE)

By Clement Emang

Introduction to MIT

- Multifinger Imaging tool (MIT) is designed to provide the most accurate tubing caliper measurements.
- The data allows for 3 dimensional imaging and the calculation of rates of corrosion or scale deposition
- Dimension bid has 2 types of MIT, MIT24F & MIT40F



Tool Specification

Mechanical	MIT24F	MIT40F
Outside Diameter	1-11/16"	2-3/4"
Make up Length	50.6"	54.4"
Housing Material	Inconel 718 / Stainless Steel 17-4	
Finger Lengths	7"	7" and 10"
Number of Fingers	24F	40F
Radial Accuracy	±0.02"	±0.025" (7") ±0.03" (10")
Radial Resolution	0.003"	0.005" (7") 0.007" (10")
Measurement Range	1-3/4" (Min) 7" (Max)	2.75" (Min) 10" (Max)
Circumferential Spacing	0.23" (Min) 0.92" (Max)	0.25" (Min) 0.92" (Max)
Finger Tip Radius	0.05"	0.06"
Finger Tip Width	0.063"	0.04"
Finger Contact Force	0.75lbs (Min) 1.25lbs (Max)	
Logging Speed	30ft/min (Min) 60ft/min (Max)	
Environmental		
Pressure Ranges	Up to 15,000 psi	Up to 20,000 psi
Temperature Rating	177°C (351°F)	
Electronic		
Current Consumption	Logging <30mA Motor <400mA	

WELL INFO

- Well schematic
- Well history
- OHGR
- Tubing Tally
- Pressure and Temperature

MIT Toolstring


➤ Standard MIT toolstring for memory job consist of:-

1. ULTRAWIRE MEMORY TOOL, UMT
2. PRODUCTION KNUCKLE JOINT, PKJ
3. PRODUCTION ROLLER CENTRALISER, PRC
4. MULTIFINGER IMAGING TOOL, MIT
5. PRODUCTION ROLLER CENTRALISER, PRC
6. BULLNOSE WITH TERMINATOR, BUL

MIT CHECKLIST

MIT SSP CHECKLIST	
At Base: Design & Prepare	☐ Client has provided the well information, confirmed the number of run, logging, interval and signed the work program.
Design	☐ Confirm the operation is within tool specifications.
	☐ Client already been informed on the limitation of the tools, equipment, well (condition and etc).
	☐ Ensure availability of the required tool configurations.
Prepare	☐ Discuss with CMO/PM on the availability of the MIT Tools.
	☐ For a client, discuss with AS/TSU or GE on the availability and functionality.
	☐ Prepare all the tools and accessories as per maintenance manual. Verify with the lab side on the maintenance.
	☐ Ensure all the consumables, spare parts, hardware, and engineering tools are already in the package.
	☐ Prepare Service Software (Refer to Do-Check Checklist).
	☐ Perform MIT Check (Refer to Do-Check Checklist).
At Well Site: Execute	☐ Confirm well and hole properties with Wireline Supervisor. Review well history.
	☐ Make sure the well is stable and has been shut in for specific duration depending on the job program.
Rig Up	☐ Ensure tubing connection is conducted prior to start MIT Tools.
	☐ Perform MIT Check (Refer to Do-Check Checklist).
	☐ Prepare Sequence of Events (SOE) corresponding to the designed logging interval.
	☐ Program UNIT and download accordingly.
	☐ Make-up MIT toolstring as per sequence.
	☐ Ensure MIT for S-Chart from S-Chart to MIT Tools.
	☐ Make-up battery and record MIT insulation time.
Run	☐ Run tool string (CSP for MIT is at target at tubing head flange (THF)).
	☐ Perform MIT Caliper survey run as per SOP.
	☐ Run with average speed of 20m/min to set depth.
	☐ POCOT to surface at 20m/min, not exceeding 30 mins.
	☐ Clean the tool string to ensure when it hangs out from lubrication.
Post Job	☐ Log down toolstring and retrieve MIT Tools.
	☐ Download data and perform data QA/QC as per SOP.
	☐ Perform after job Calibration as per SOP.
	☐ Perform post job maintenance on MIT Tools.
	☐ Submit the Data Log Report and Data to Client and Log Analyst.
Return to Base: Close	☐ Average de-magnetization of the equipment back to base.
	☐ Complete Post Job Maintenance and Reporting.
	☐ Submit any lessons learnt and improvement suggestion to CSMA.
	☐ Allowed debriefing with DSA.
Name:	
Date:	

MIT OP-CHECK CHECKLIST	
RPS SmartView	☐ Computer operating system no older than Windows 2000, 32bit for XP and 64bit for Win 7.
Software	☐ Correct Version and System Licensing Software is installed. Firmware Software is optional.
	☐ Ensure correct Version Key License entered.
	☐ No error while launching and operating the software.
Lithium Battery	☐ Check MIT Tool have valid date calibration.
	☐ Check the battery condition needed.
De-passivate	☐ Check the battery voltage using multimeter reading should be >3.5V.
	☐ De-passivate battery (if the voltage less than 3.4V).
	☐ Prepare the battery if the voltage reading is still below than 3.4V (minimum requirement is 3.4V).
MIT Tools	☐ For DTR, check the D-cell battery power and replace if it is low.
Bench Test	☐ Connect MIT Tools with laptop through USB A/B/A200 and launch Sonnet Ultrawire Licensing and Acquisition.
	☐ Check communication between laptop with MIT DTR. Make sure no error while communicating.
	☐ Synchronize the DTR time with laptop. Recommended to synchronize with IR personal watch.
	☐ Ensure correct allocated wheel circumference entered in DTR. Check the unit used same with wireline unit.
	☐ Test DTR and Encoder by raising the shaft.
	☐ Test an encoder and spinner to angle drive on wireline unit. Ensure encoder is correct position to avoid jam named.
	☐ Ensure the correct serial number and layout added in toolstring configuration.
	☐ Check the functionality of the MIT Tools as per SOP and verify the output.
	☐ Program the MIT Tools for calibration as per SOP.
	☐ Hook-up battery to the MIT Tools. Ensure the sound 'Bip' at the MIT is observed. Fingers is opening.
	☐ Perform MIT Calibration as per SOP.
	☐ Supply ultrawire/sonnet unit on MIT Tools.
	☐ Download data from UNIT and perform calibration test as per SOP.
	☐ Perform QA/QC based on the results obtained.
	☐ Record and document the bench test results.
Name:	
Date:	

MIT FIT CHECKLIST	
OBJECTIVE	☐ To conduct Post Inspection of Tool (MIT) prior to performing job.
	☐ To identify any unacceptable damage after run.
TOOL DIAGRAMS	
PRE-JOB	☐ Make sure the selected MIT Tool tagged green. Ready to GO! (not using already completed maintenance process).
	☐ Perform physical check on the tool received. Perform continuity and leak test.
	☐ Inspect the O-ring condition. Replace if necessary. Ensure to use HMR O-ring for size walls.
	☐ Apply O-ring grease.
	☐ Use air gun or WD-40 and spray the sensor to clean any dirt and debris.
	☐ De-passivate battery and bench test MIT Tools (Refer to Do-Check Checklist).
	☐ Test every tool and equipment such as job test cover to ensure the compatibility and in good condition.
	☐ Record tool and battery serial number.
	☐ Perform Field Calibration and Lubricating bench test.
POST JOB	☐ Clean the tool before disconnecting toolstring. Ensure the MIT Tools is clean from debris, dirt, and grease.
	☐ Observe for any unacceptable damage.
	☐ Inspect O-rings condition. Replace if needed.
	☐ Clean O-ring groove.
	☐ Perform after job calibration.
	☐ Fill up Tool Condition Report and MIT Battery Tracking Form.
Name:	
Date:	

PRE CALIBRATION

- To calibrate MIT finger before the run
- Make sure that the finger are all functioning
- Can be done separately from the program

MIT PROGRAMMING

- To estimate the duration of run
- Time management
- Make sure to put extra 10/15 min for each section(open/close) to ensure that the finger is fully open or fully close.
- Make sure to set 'setup' after 'open'

POST CALIBRATION

- To determine the offset of the finger after logging by comparing it with the Pre-calibration
- Finger offset should be less than 0.002
- Make sure the finger is clean (without any debris) before starting the post calibration
- Can be done separately from the program

➤ Below are the list of data to be send to Log Analyst after each run

1. .psc
2. .24f
3. .db
4. Field Quicklook with corrected log in .pdf

EXAMPLE OF JOB

MIT-NO REPEAT SECTION

MEMORY MIT PROGRAM NO REPEAT SECTION (Corrosion/Scale Monitoring Tool)

Well Name: **B-025** DATE: **30-Jun-14**

Depth resolution = **0.002 in**
= **2.032 mm**

Tool Type (34 or 40 only) = **34**

***Changeable Items are BOLD and COLOURED BLUE**

24-Bit/16" Tool: 2441.22 Bytes/s 73 Readings/sec
40-Bit/18" Tool: 4009.08 Bytes/s 52 Readings/sec

VARIABLES	
Main Log Bot Depth:	11467 ft
Main Log Top Depth:	3300 ft
R.H.M. Speed:	2.20 ft/min
Logging Speed:	30 ft/min
Tool Data Rate:	2441.22 Bytes/s

Job Sequence	Program	Divisor	Position	Time mins	Bytes	Total Mem	Cumulative Mins	Cumulative Bytes	Real Time	Action
Tool Check/Pre Op. Cal.	M	20	Open	10.0	101,432	101,432	0.0	0.0	2:00:00 AM	Tool Opens
Start Rig Up	N	73	Closed	30.0	23,387	124,819	10.0	124,819	2:10:00 AM	Tool Closes
R.H.M.	N	73	Closed	96.0	266,839	491,658	40.0	491,658	2:40:00 AM	Start R.H.M.
R.H.M. Insurance (Spare)	N	73	Closed	15.0	41,854	533,512	134.0	533,512	2:40:00 AM	Start R.H.M.
OPEN	M	1	Open	3.0	608,728	1,142,240	137.0	1,142,240	2:43:00 AM	Time Tool Opens
Main Log	M	1	Open	370.0	72,076,404	73,218,644	140.0	73,218,644	2:46:00 AM	Start Main Log
M/L Insurance (Spare)	M	1	Open	15.0	3,049,432	76,268,076	155.0	76,268,076	2:46:00 AM	Start Main Log
CLOSE	N	73	Closed	3.0	9,339	76,277,415	158.0	76,277,415	2:49:00 PM	Time Tool Closes
POOH	N	73	Closed	3.0	9,339	76,286,754	161.0	76,286,754	2:52:00 PM	Start POOH
Start Rig Down	N	73	Closed	0.0	0	76,286,754	161.0	76,286,754	2:52:00 PM	Rig Down
Post Survey Calibration	M	20	Open	0.0	0	76,286,754	161.0	76,286,754	2:52:00 PM	Time Tool Opens
End of Job				343.0	79,238,832	79,238,832	343.0	79,238,832	2:53:00 PM	Tool Closes / End

****Memory Size Maybe Exceeded - Check by Programming Tool****
Equipment Cleaning, Download and Data Verification + Pasting: **1 hour**

Start Time (HH:MM:SS)	End Time (HH:MM:SS)	Profile Length (mins)	Profile Type	Rate	UNIT	MIT
2:00:00 AM	2:03:00 AM	3.0	Open	1	0	1.0
2:03:00 AM	2:10:00 AM	7.0	Log Open	1	0.02	0.02
2:10:00 AM	2:13:00 AM	3.0	Close	1	0.02	0.02
2:13:00 AM	2:15:00 AM	2.0	Log Close	1	0.02	0.02
2:15:00 AM	2:18:00 AM	3.0	Open	1	0.02	0.02
2:18:00 AM	2:20:00 AM	2.0	Log Open	1	0.02	0.02
2:20:00 AM	2:23:00 PM	3.0	Close	1	0.02	0.02
2:23:00 PM	2:43:00 PM	20.0	Log Close	1	0.02	0.02
2:43:00 PM	2:45:00 PM	2.0	Open	1	0.02	0.02
2:45:00 PM	2:48:00 PM	3.0	Log Open	1	0.02	0.02
2:48:00 PM	2:53:00 PM	5.0	Close	1	0.02	0.02

Tool Memory Size: KB
Available Memory in Bytes: 87107840

Open	7.0	MIT
Log Open	138.0	MIT
Close	3.0	MIT
Log Close	288.0	MIT
Open	6.0	MIT
Log Open	138.0	MIT
Close	3.0	MIT
Log Close	288.0	MIT

New Dimension
Your Integrated Solutions Partner

STEP BY STEP

Results:

As a result, take total profile length (hours) and total current used for calculation so that we know how much power has been used. Every battery has their own available power. By considering total current used and self drain, it can compute total power left. From there we know either that batteries is sufficient enough or not to use for the job.

Total Profile Length (hrs)

Thank you !

Questions and Answering Session

Prepared by, 

Name: Clement Emang Yusup Ngau
Designation: Junior Field Engineer
Date: 1/1/2024

Verified by,

Verified by,

Name : Faris M. Firdaus
Designation : Field Service Manager
Date :

Name: Mohd Zahir Bin Abdul Manan
Designation: Operation Manager
Date: