# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

| Name | SHAHRIL IZHAM BIN ALIAS | COB Date | 19/4/2024 |
|---|---|---|---|
| Position | EQUIPMENT OPERATOR TRAINEE | RTB Date | 17/5/2024 |
| Client | PCSB | Location | DULANG |
| Platform | DULANG CHARLIE | Well | C-15L |
| Assessed By | Name: Zainuddin | Position: CT1 Spv |

**RATING LEGEND:**

**STRONG** — Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

**ADEQUATE** — Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good

**IMPROVEMENT NEEDED** — Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

| Assessment Criteria | Rating (Please √ where appropriate) | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
| **Safety Awareness (20%)** | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 |
| a. Usage of Personal Protective Equipment | | √ | | | | | | | |
| b. Participation in UAUC | | √ | | | | | | | |
| c. Understanding of PTW System | | √ | | | | | | | |
| d. Worksite House Keeping | | √ | | | | | | | |
| **Work Performance (20%)** | | | | | | | | | |
| e. Iniatiative and Creativity | | | √ | | | | | | |
| f. Decision Making Capability | | | √ | | | | | | |
| g. Understanding of Job Scope | | | √ | | | | | | |
| h. Tools Inventory and Reporting | | | √ | | | | | | |
| i. Work Quality | | | √ | | | | | | |
| j. Reporting | | | √ | | | | | | |
| k. Punctuality and Time Keeping | | √ | | | | | | | |
| l. Teamwork | | √ | | | | | | | |
| m. Communication | | √ | | | | | | | |
| n. Leadership Skills | | | √ | | | | | | |
| o. Adaptability to Work Environment/Surrounding | | | √ | | | | | | |
| p. Attitude | | | √ | | | | | | |
| q. Discipline | | | √ | | | | | | |

**REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:**

Keep it good work

| Assessed By [Supervisor] | *(signature)* |
|---|---|
| Name | Zainuddin Jaacob |
| Date | 16/5/24 |

# DIMENSION BID

## COILED TUBING  PERFORMANCE ASSESSMENT FEEDBACK

PART 2. To be completed by Employee and Assessor [WEIGHT: 60%]

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| 1. Pre-Job Preparation | 1.Attend pre-job meeting before mob<br>2.Prepare e-ptw<br>3.Attend toolbox meeting conduct by wss and all intervention crew on board | Good |

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | (7) | 6 | 5 | 4 | 3 | 2 |

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| 2. Surface Equipment Rig-up | 1.Assist crew for heavy lifting and rearrange equipment and spot at the right place<br>2.Assist  crew to rig-up treating iron<br>3.Assist crew to rig-up 4" LP hoses from fst to batch mixer and single pump.<br>4.Rearrange wilden pump and rig up spring hose from sea deck to batch mixer<br>5.Spot floodlight and line up socket to junction box. | Good |

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | (8) | 7 | 6 | 5 | 4 | 3 | 2 |

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| 3. Tools / Equipment Preparation | 1.Perfome EMC1 for all equipment<br>2.Start up and run all equipment for few minutes.<br>2.Connect air hose from air compressor to all equipment.<br>3.Top up diesel to all equipment everyday before start operation. | Good |

| Rating (by Operator) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | (7) | 6 | 5 | 4 | 3 | 2 |

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| 4. Equipment | **4.1  Batch Mixer**<br>1.Assist batch mixer operator to connect hydraulic hose<br>2.Assist crew to troubleshoot batch mixer because it cannot be started<br>3.Assist crew to rearrange chemicals and put some on batch mixer tank<br>4.Assist batch mixer operator for mixing 15% HCL for 10 barrels.<br>5.Assist batch mixer operator open up butter fly valve for transfer to single pump. | Good |

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | (7) | 6 | 5 | 4 | 3 | 2 |

| Employee was able to OPERATE the equipment: | Under Supervision | ✓ | |
|---|---|---|---|
| | Standalone | | |

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| | **4.2 Pump Unit**<br>1. Assist pump operator to rig-up single pump<br>2. Assist pump operator to connect hydraulic hose<br>3. Assist pump operator to install universal shaft<br>4. Assist pump operator to function test pumping unit<br>5. Assit pump operator to line up from single pump to kill port | Good |

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | (7) | 6 | 5 | 4 | 3 | 2 |

| Employee was able to OPERATE the equipment: | Under Supervision | ✓ |
|---|---|---|
| | Standalone | |

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| | **4.3 Nitrogen Pump unit & Nitrogen Tank** | Good |

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 |

| Employee was able to OPERATE the equipment: | Under Supervision | |
|---|---|---|
| | Standalone | |

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| | **4.4 Power Pack** | Good |

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 |

| Employee was able to OPERATE the equipment: | Under Supervision | |
|---|---|---|
| | Standalone | |

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| | **4.5 Control Cabin** | |

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 |

| Employee was able to OPERATE the equipment: | Under Supervision | |
|---|---|---|
| | Standalone | |

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor (WEIGHT: 60%)

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| | 4.6 CT Reel | |

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 |

| Employee was able to OPERATE the equipment: | Under Supervision | |
|---|---|---|
| | Standalone | |

| Type of Task | Tasks Performed | Assessor Comment |
|---|---|---|
| | 4.7 Injector Head | |

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 |

| Employee was able to OPERATE the equipment: | Under Supervision | |
|---|---|---|
| | Standalone | |

4.8 Pressure Control Equipment
1. Assist crew to rig-up single BOP with necessary lenght of riser on top of the wellhead is correct
2. Assist crew to hook up BOP hoses.

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 |

| Employee was able to OPERATE the equipment: | Under Supervision | |
|---|---|---|
| | Standalone | |

4.9 Basic BHA Components

| Rating (by SUPERVISOR) | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
|---|---|---|---|---|---|---|---|---|---|
| | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 |

| Employee was able to OPERATE the tools: | Under Supervision | |
|---|---|---|
| | Standalone | |

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

| Type of Task | Tasks Performed | Assessor Comment | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| **5. Job Supervision** (if applicable) *Please complete this section if you perform any supervisory role during operation* | | | | | | | | | | |
| | | | STRONG | | | ADEQUATE | | | IMPROVEMENT NEEDED | | |
| | Rating (by SUPERVISOR) | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 |
| | Please ✓ accordingly to confirm the role of the employee during operation | Full Supervisor | | | | | | | | |
| | | 2nd / Night Supervisor | | | | | | | | |

# DIMENSION BID

| DATE | Assignment/Summary Job/Duration | Supervisor's Feedback<br>(Please indicate if employee is able to execute the job UNDER SUPERVISION or STANDALONE) |
|---|---|---|
| | Mobilized from KSB to DULANG on 19 April 2024. When arrived at location, procced to heavy lifting ctu equipment and start rig-up equipment and surface rig-up. Split crew after completed rig-up. I was assigned as helper on night shift<br><br>On well C-15L, we are perfom sand cleanout untill MA Plug SSD#4 at depth 2,257m MDTHF. After finish first sand cleanout, we are perfome second sand cleanout until EOT at depth 2,323m MDTHF. During this, I was assigned to assisted batch mixer operator to mixing 15% HCL for 10 barrels. | He can stand alone with out supervision. One of Candidate with future Bright. |

Please tick (✓) category of services performed:

| Standard Services: | | | Advanced Services | | |
|---|---|---|---|---|---|
| Wellbore Cleanout | | | CT Fishing | | |
| CT Cementing | | | CT Miling | | |
| Nitrogen Operations | | | CT Logging | | |
| Pumping Services | / | | CT Perforation | | |