

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	ZAINUDDIN YAACOB	COB Date	24-8-24
Position	GEO	RTB Date	29-8-24
Client	PCSB	Location	DL-A
Platform	DULANG A	Well	A7
Assessed By	Name: M. TAUFIQ	Position:	CT SUPV

RATING LEGEND:

STRONG Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

ADEQUATE Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good

IMPROVEMENT NEEDED Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
---------------------	-------------------------------------	--	--	--	--	--	--	--	--

Safety Awareness (20%)

- a. Usage of Personal Protective Equipment
- b. Participation in UAUC
- c. Understanding of PTW System
- d. Worksite House Keeping

	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
a. Usage of Personal Protective Equipment	✓								
b. Participation in UAUC		✓							
c. Understanding of PTW System		✓							
d. Worksite House Keeping		✓							


Work Performance (20%)

- e. Initiative and Creativity
- f. Decision Making Capability
- g. Understanding of Job Scope
- h. Tools Inventory and Reporting
- i. Work Quality
- j. Reporting
- k. Punctuality and Time Keeping
- l. Teamwork
- m. Communication
- n. Leadership Skills
- o. Adaptability to Work Environment/Surrounding
- p. Attitude
- q. Discipline

	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
e. Initiative and Creativity		✓							
f. Decision Making Capability		✓							
g. Understanding of Job Scope		✓							
h. Tools Inventory and Reporting		✓							
i. Work Quality		✓							
j. Reporting			✓						
k. Punctuality and Time Keeping		✓							
l. Teamwork		✓							
m. Communication		✓							
n. Leadership Skills		✓							
o. Adaptability to Work Environment/Surrounding		✓							
p. Attitude		✓							
q. Discipline		✓							

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

Assign as night supervisor during working period and able to stand alone to perform CT operation.

Assessed By [Supervisor]	
Name	M. TAUFIQ
Date	1-9-24

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment
1. Pre-Job Preparation	<ul style="list-style-type: none"> - Attend morning and toolbox meeting with NISS on board - Attend pre job meeting - pre-check/EMC all CTU equipment 	Done
Rating (by SUPERVISOR)		
STRONG		ADEQUATE
10	(9)	8
7	6	5
4	3	2
2. Surface Equipment Rig-up	<ul style="list-style-type: none"> - Assist crew to rig up surface line including NS line - Rig up A0 hose - Rig up water injection line - spot and arrange fluid light, CC and tool container electric cable to junction box - Rig up wilder pump 	Done
Rating (by SUPERVISOR)		
STRONG		ADEQUATE
10	(9)	8
7	6	5
4	3	2
3. Tools / Equipment Preparation	<ul style="list-style-type: none"> - Perform EMC1 on CC, Stripper, Single and Comb BOP, CT reel, CIP, injector head, JF and power pack - prepare down hole tool 	Done
Rating (by Operator)		
STRONG		ADEQUATE
10	(9)	8
7	6	5
4	3	2
4. Equipment	<p>4.1 Batch Mixer</p> <ul style="list-style-type: none"> - prepare and get ready for milling operation 	Done
Rating (by SUPERVISOR)		
STRONG		ADEQUATE
10	(9)	8
7	6	5
4	3	2
Employee was able to OPERATE the equipment:		
Under Supervision		<input type="checkbox"/>
Standalone		<input checked="" type="checkbox"/>

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment									
	4.2 Pump Unit - Get ready to perform while milling operation	Done									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	(9)	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:					Under Supervision						
					Standalone			/			
	4.3 Nitrogen Pump unit & Nitrogen Tank - Assist crew to rig up line - Assist crew to rig up cyrogenic hose - Assist cool down N2 if required	Done									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	(9)	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:					Under Supervision						
					Standalone			/			
	4.4 Power Pack - Perform EMC 1	Done									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	(9)	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:					Under Supervision						
					Standalone			/			
	4.5 Control Cabin - set up job file - Communicate with toolman inside CC during milling job - update job ticket - update chemical	Done									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	(9)	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:					Under Supervision						
					Standalone			/			

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment									
	4.6 CT Reel • Perform EMC 1	Done									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	(9)	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:		Under Supervision			Standalone						
					/						
	4.7 Injector Head - Top up injector oil - Top up injector gear oil - Perform EMC 1	Done									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	(9)	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:		Under Supervision			Standalone						
					/						
	4.8 Pressure Control Equipment - Function test all BOPs - Function test stripper - Perform EMC 1	Done									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	(9)	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:		Under Supervision			Standalone						
					/						
	4.9 Basic BHA Components • Prepare BHA - Make up BHA	Done									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	(9)	8	7	6	5	4	3	2	
Employee was able to OPERATE the tools:		Under Supervision			Standalone						
					/						

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK


PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment								
5. Job Supervision (if applicable) Please complete this section if you perform any supervisory role during operation	Night Supu	Done								
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Please ✓ accordingly to confirm the role of the employee during operation				Full Supervisor					
				2nd / Night Supervisor			/			

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3: To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback (Please indicate if employee is able to execute the job <u>UNDER SUPERVISION</u> or <u>STANDALONE</u>)
24/8/24	<p>Perform milling job on well A7</p> <ul style="list-style-type: none"> - I was assigned as night shift Super to perform milling operation. - Communicate all the time with toolman on board - 	<p>Stand alone</p> 

Please tick (✓) category of services performed:

Standard Services:

- Wellbore Cleanout
- CT Cementing
- Nitrogen Operations
- Pumping Services

Advanced Services

- CT Fishing
- CT Milling
- CT Logging
- CT Perforation