

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	Muhamad Abdul Latif Bin Mohd	COB Date	17.03.2024
Position	Senior Slickline Assistant I	RTB Date	27.03.2024
Client	Carigali Hass	Location	SY-A
Platform	Suriya	Well	SYA-19
Assessed By	Name: Shahrizan Sapari Position: Senior General Slickline Operator		

RATING LEGEND:

STRONG	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
ADEQUATE	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
IMPROVEMENT NEEDED	Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
---------------------	-------------------------------------	--	--	--	--	--	--	--	--

Safety Awareness (20%)

- a. Usage of Personal Protective Equipment
- b. Participation in ACT
- c. Understanding of PTW System
- d. Worksite House Keeping

	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
a. Usage of Personal Protective Equipment	/								
b. Participation in ACT		/							
c. Understanding of PTW System		/							
d. Worksite House Keeping		/							

Work Performance (20%)

- e. Initiative and Creativity
- f. Decision Making Capability
- g. Understanding of Job Scope
- h. Tools Inventory and Reporting
- i. Work Quality
- j. Reporting
- k. Punctuality and Time Keeping
- l. Teamwork
- m. Communication
- n. Leadership Skills
- o. Adaptability to Work Environment/Surrounding
- p. Attitude
- q. Discipline

e. Initiative and Creativity	/								
f. Decision Making Capability	/								
g. Understanding of Job Scope	/								
h. Tools Inventory and Reporting	/								
i. Work Quality	/								
j. Reporting	/								
k. Punctuality and Time Keeping	/								
l. Teamwork	/								
m. Communication	/								
n. Leadership Skills	/								
o. Adaptability to Work Environment/Surrounding	/								
p. Attitude	/								
q. Discipline	/								

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

Carried out all task as of Senior Assistant 1 was done successfully, able to received instruction execute as per plan with minimum supervisio

Small area need to improvement for the next level.

Suggest to move to the next level as a candidate Training Slickline Operator and take advantage to familiar with down hole equipment and RSU Operating

Assessed By [Operator]	Sahrizan Bin Sapari
Name	Muhamad Abdul Latif Bin Mohd
Date	27.03.2024

Doc.Ref.No.: SLS-FORM-13
 Revision No.: 03
 Effective Date: 22/05/2023
 (Rev.02,Dated:14/06/19-OBSOLETE)

CONTROLLED COPY

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment									
1. Pre-Job Preparation	<ul style="list-style-type: none"> - Toolbox meeting with team and WSS. - Review JHA and review job program - Get confirmation of size tree cap connection. - TBT with crew about work planning. 	All done follow by the instruction and planning, also good act for preparation as what operation need.Minor area need to do small improvement.									
		10	9	8	7	6	5	4	3	2	
2. Surface Equipment Rig-up	<ul style="list-style-type: none"> - Continue pressure test lower section of PCE 500 to 2000psi. - Rig up 70ft Telescopic Mast. - Connect 4 section 5 1/2" lubricator in vertical position. - Perform strength test 0.125" ZERON wire. Maximum breaking point @ 3100lbs. - Pressure test full section of PCE 500/2000psi. - Connect HMV & LV manifold. Cycle LV and get hyd. return 250ml. - Power up offshore cabin office. 	Good preparation of surface equipment and PCE prior and after execute the job.									
		10	9	8	7	6	5	4	3	2	
3. Tools / Equipment Preparation	<ul style="list-style-type: none"> - Prepare tool string for first run of TCC. - Prepare tool string configuration :- 2.50" Rope Socket + swival joint + Accelerator + 5ft Normal Stem + 3ft Normal Stem + Peak Power jar (700lbs) + 30" mechanical Jar + 4.60" Fluted Drift. - Setting power jar 700lbs and function test it. - Make up new rope socket and connect all tool string configuration. - Prepare 4.60" wire scratcher 										
		10	9	8	7	6	5	4	3	2	
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>	During ripup 70ft telescopic Mast. Observed no power supply. Crew open the rely box and reset all rely have. Successful .	Good action to troubleshooting the 70ft Mast.									
		10	9	8	7	6	5	4	3	2	
5. Downhole Tools Servicing/Redressing/Maintenance	<ul style="list-style-type: none"> - Re-setting the 2.50" EAJ to 700lbs for every run. - Check the wire scratcher OD 4.60". 	Good preparation , function test before run the tools									
		10	9	8	7	6	5	4	3	2	

Doc.Ref.No.: SLS-FORM-13

Revision No.: 03

Effective Date: 22/05/2023

(Rev.02,Dated:14/06/19-OBSOLETE)

CONTROLLED COPY

Type of Task	Tasks Performed	Assessor Comment																											
6. Tools Inventory & Reporting	- Perform all inventory of tools we have and get the WSS signature.	All done follow by the instruction																											
	<table border="1"> <tr> <th rowspan="2">Rating (by Operator)</th> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>										Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																						
	10	9	8	7	6	5	4	3	2																				
7. Equipment Operation	[Operator to rate TSA / SA / SSA competency in operating the equipment]																												
	<table border="1"> <tr> <th rowspan="2">Rating (by Operator)</th> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2									
	Rating (by Operator)		STRONG			ADEQUATE			IMPROVEMENT NEEDED																				
		10	9	8	7	6	5	4	3	2																			
	Power Pack	/																											
	Air Compressor	/																											
	GenSet	/																											
	Control Panel	/																											
	Test Pump	/																											
	Pressure Control Equipment	/																											
Mast	/																												
Weight & Measuring Devices	/																												
Downhole Tools	/																												
Total										0	81	0	0	0	0	0	0	0	0										
Comments by Operator <i>[please specify competency gaps / area of improvement]</i> Minor area need improvement , the rest done good.																													
EXECUTE THE WELL SERVICES OPERATION (IF ANY) (Operating Winch)																													
Date / Location / Well No. / Job Type	Activity Summary	Toolstring Configuration																											
20.02.2024 / SYA / SYA-19 / Set KX Valve	<ul style="list-style-type: none"> -RIH 4.60" Fluted drift to tag top of RPT profile. -RIH 4.60" wire Scratcher. - RIH Nom.5.0" RXN running tool c/w KX Valve to set at RPT profile. - RIH Sim running tool c/w 4.45" LBGH to set at top of KX Valve. 	2.50" Rope Socket + swival joint + Accelerator + 5ft Normal Stem + 3ft Normal Stem + Peak Power jar (700lbs) + 30" mechanical Jar...																											
<table border="1"> <tr> <th rowspan="2">Rating (by Operator)</th> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2										
Rating (by Operator)		STRONG			ADEQUATE			IMPROVEMENT NEEDED																					
	10	9	8	7	6	5	4	3	2																				
Comments by Operator <i>[please specify competency gaps / area of improvement]</i> Minor area need improvement, the rest done good.																													

Doc.Ref.No.: SLS-FORM-13
 Revision No.: 03
 Effective Date: 22/05/2023
 (Rev.02,Dated:14/06/19-OBSOLETE)

CONTROLLED COPY

