

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	Malkyzidek Yehu Jerry	COB Date	31/02/23
Position	Slickline assistant	RTB Date	21/02/23
Client	SEAH	Location	North Sabah
Platform	SFT-B	Well	SF32,SF38
Assessed By	Name: AWANG Position: SLICKLINE OPERATOR		

Assessment Criteria	Rating (Please V where appropriate)
---------------------	-------------------------------------

Safety Awareness

a. Usage of Personal Protective Equipment

b. Participation in ACT

c. Understanding of PTW System

d. Worksite House Keeping

Work Competency

a. Pre-Job Preparation

b. Surface Equipment Rig-up Process

c. Tools/Equipment Preparation

d. Equipment Problem Trouble Shooting Capability

e. Downhole Tools Servicing/Redressing/Maintenance

f. Initiative and Creativity

g. Decision Making Capability

h. Understanding of Job Scope

i. Tools Inventory Preparation & Reporting

j. Work Quality

k. Reporting

Others

a. Punctuality and Time Keeping

b. Teamwork

c. Communication

d. Leadership Skills

e. Adaptability to Work Environment/Surrounding

f. Attitude

g. Discipline

OVERALL PERFORMANCE

☒ Excellent
 ☐ Very Good
 ☐ Good
 ☐ Satisfactory
 ☐ Poor

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

He have qualification to be a senior wireline tech is able to adapt the job easy

he skill and knowledge can be further upon with more exper to the field tool preparation for each job is handled according to the job demanded

Assessed By :

Name :

AWANG

Date :

21/2/2023

Agreed By :

Name :

Malkyzidek Yehu Jerry

Date :

21/2/23

CONTROLLED COPY

Doc.Ref.No.: SLS-FORM-13

Revision No.: 02

Effective Date: 14/06/19

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment
1. Pre-Job Preparation	(APPLY PTW, GET AGT APPROVER, GET APPROVE PTW ONSITE, DISCUSS ABOUT JHA, GET THE WELL HANDOVER FROM OPERATION, TOOLBOX TALK AMONG CREW. (-) CHECK ALL HOSES WAS TIGHT AND SECURE (-) ENSURE ALL TOOLS BEING PREPARED PRIOR TO JOB BEING PERFORM (-) BARRICADE WORKSITE & WELLHEAD AREA BEFORE PERFORME RIGGING UP (-) CHECK WELL CONDITION TO KNOW IF THERES POTENTIAL PASSING ON VALVE (-) WALK THE LINE BEFORE START RIGGING UP AND IDENTIFY ANY HAZARD	
2. Surface Equipment Rig-up	A) MAKE UP PCE EQUIPMENT B) PUT GREASE ON ALL LUB CONNECTION BEFORE CONNECTING IT C) CHECK O-RING BEFORE MAKE UP THE LUBRICATOR D) CHECK ANY DAMAGE ON ALL LUB THREAD E) HOOK UP ALL HOSES & CHECK ALL HOSES FOR ANY DAMAGE BEFORE USE F) CHECK ALL PCE EQUIPMENT VALIDITY BEFORE USE G) MAKE UP ROPE SOCKET H) ENSURE ALL SHACKLE SECURE WITH SAFETY PIN	
3. Tools / Equipment Preparation	A) SERVICE & FUNCTION TEST TOOL BEFORE USING IT B) STANBY FKE INSERT VALVE PULLING AND RUNNING TOOLS C) CHECK ANY THREAD DAMAGE ON TOOLS BEFORE/AFTER USE, ALSO CHECK THE SHEAR PIN ON PULLING TOOL D) FILE ANY TOOLS THAT HAVE SHARP EDGES TO PREVENT FROM BEING CUT E) CLEAN ANY TOOL THAT IS STUCK DUE TO WAX F) STANBY WIRE SCRATCHER AND INVENTORY TOOLS IF NECESSARY	
4. Equipment	4.1 PP (-) CHECK RADIATOR WATER (-) CHECK HYDRAULIC LEVEL CHECK (-) TOP UP FUEL IF NEEDED (-) CHECK ENGINE OIL LEVEL (-) CHECK IF TEMP LEVEL IS WORKING (-) CLEAN FLAME TRAP IF NEEDED (-) PRESSURE GAUGE FOR PUMP IS WORKING WELL (-) CHECK ALL CONNECTING & HOSES IF ANY LEAK	
4.2 AC		
4.3 GS		

CONTROLLED COPY

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment
Assessor's Evaluation:	4.4 CP -FLUSHING SSV LINE & SCSSV BEFORE HOOK UP HOSES -OPERATE THE CP(SSV 3000PSI)(SCSSV 3800PSI) -FUNCTION TEST CP (PUMP) -CHECK CP HOSES IF ANY DAMAGE -TOP UP HYDRAULIC IF NEEDED -CHECK HOSES CONNECTION IF THERE ANY LEAK	
	4.5 TP -HOOK UP THE HOSES -OPERATE THE TEST PUMP -CHECK HOSES IF ANY DAMAGE -CHECK TP HOSES IF THERE ANY LEAK DURING PRESSURE UP	
	Level of Skill & Knowledge ☒ Awareness ☐ Basic ☐ Broad ☐ Detail	
	Assessor's Evaluation:	4.6 PCE -PERFORM HYDROTEST -IDENTIFY TYPE OF CONNECTION & MAKE UP -PUT GREASE ON ALL THREAD LUBRICATOR -CHECK O-RING CONDITION -OPERATE & FUNCTION TEST THE BOP -MAKE SURE ALL PCE IS VALID -FUNCTION TEST ALL PCE (BOP,QTS,BALL VALVE) -CHANGE SBX PACKING
Level of Skill & Knowledge ☐ Awareness ☐ Basic ☐ Broad ☐ Detail		
4.7 Mast		
Level of Skill & Knowledge ☐ Awareness ☐ Basic ☐ Broad ☐ Detail		
Assessor's Evaluation:	4.8 WEIGHT & MEASURING DEVICES -FLUSH HOSE AND PUMP W15 FLUID -CHECK ODOMETER CONDITION -SPRAY ODOMETER CABLE WITH WD40 TO PREVENT FROM CORROSION	
	Level of Skill & Knowledge ☐ Awareness ☒ Basic ☐ Broad ☐ Detail	
	4.9 Downhole Tools -CHECK & SERVICE DHT -PINNING & FUNCTION TEST DHT -MAKE UP TOOLSTRING -PREPARE AND CHANGE DAMAGE SPARE PART ON DAMAGE DHT -CHECK ANY FAULTY ON DHT THAT BEING USED -ENSURE ALL THREADED TOOLS BEING SECURE TIGHTLY	
	Level of Skill & Knowledge ☐ Awareness ☒ Basic ☐ Broad ☐ Detail	

JOB DETAIL:

DATE	WELL NO.	JOB TYPE	STATUS (COMPLETE / INCOMPLETE)
7/2/2023	SF32	TCC	COMPLETE
9/2/2023	SF38	FISHING JOB	INCOMPLETE

Doc.Ref.No.: SLS-FORM-13

Revision No.: 02

Effective Date: 14/06/19

CONTROLLED COPY

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment