

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	MUHAMMAD ALIFF BIN ZULKEFLI	COB Date	17-Apr-24
Position	EQUIPMENT OPERATOR 2	RTB Date	07-Mei-24
Client	PCSB	Location	ANGSI
Platform	ANGSI BRAVO	Well	B 17S
Assessed By	Name: MOHD HAZWAN	Position:	SUPERVISOR PUMPING

RATING LEGEND:

STRONG	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
ADEQUATE	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
IMPROVEMENT NEEDED	Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)
---------------------	-------------------------------------

Safety Awareness (20%)

- a. Usage of Personal Protective Equipment
- b. Participation in UAUC
- c. Understanding of PTW System
- d. Worksite House Keeping

STRONG			ADEQUATE			IMPROVEMENT NEEDED		
10	9	8	7	6	5	4	3	2
✓		4						
		✓						
		✓						
	✓							

Work Performance (20%)

- e. Initiative and Creativity
- f. Decision Making Capability
- g. Understanding of Job Scope
- h. Tools Inventory and Reporting
- i. Work Quality
- j. Reporting
- k. Punctuality and Time Keeping
- l. Teamwork
- m. Communication
- n. Leadership Skills
- o. Adaptability to Work Environment/Surrounding
- p. Attitude
- q. Discipline

	✓							
			✓					
	✓							
		✓						
	✓							
	✓							
✓								
✓								
		✓						
		✓						
✓								
✓								

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

Person always shows a strong work ethic during on duty not good & keep it up.

Done & completed assessment.

Assessed By [Supervisor]	<i>[Signature]</i>
Name	MUHD HAZWAN BIN ABDUL HAMID
Date	7/5/2024

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
1. Pre-Job Preparation	1. Attend toolbox and morning meeting with CSR. 2. Pre-check/EMC1 all PUMPING equipment before run the job. 3. Assisted crew in lifting all pumping equipment and spot unit. 4. Pre-check/EMC1 all pumping equipment before run the job. 5. Prepare supporting document prior load out. 6. Split crew to day and night shift after complete rig up pumping equipment.	<i>Done & Completed</i>																		
	Rating (by SUPERVISOR)											STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2										
2. Surface Equipment Rig-up	1. Rig up 4" hose from FST to batch mixer and single pump . 2. Spot/arrange flood light, control cabin and tool container electric cable to junction box. 3. Rig up water injection line from wel to fluid storage tank. 4. Rig up wilden pump, 2" spring hose and air hose	<i>Done & Completed</i>																		
	Rating (by SUPERVISOR)											STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2										
3. Tools / Equipment Preparation	1. Installing air hose from compressor to SP02, BMX02 and wilden pump . 2. Perform EMC1 on Air Compressor and Genset for pre job. 3. Fuel up all pumping equipment. 4. Redress 2x1 plug valve	<i>Done & Completed</i>																		
	Rating (by Operator)											STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2										
4. Equipment	4.1 Batch Mixer 1. Assist operator to mix gel 50bbl and soda ash 35bbl 2. Function test C-pump and actuator of batch mixer 3. Assist Batch Mixer Operator to mix chemical. 4. Assist to mix TIW on fluid storage tank	<i>Done & Completed person can handle and run unit properly</i>																		
	Rating (by SUPERVISOR)											STRONG			ADEQUATE			IMPROVEMENT NEEDED		
												10	9	8	7	6	5	4	3	2
Employee was able to OPERATE the equipment:					Under Supervision															
					Standalone															

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment									
	4.2 Pump Unit 1.Connect hydraulic hose. 2.Install universal shaft. 3.Greasing shaft. 4.Replace rubber insert and packing plunger. 5.Rig up pumping line to ct reel and kill line to bop. 6.Priming pump before start pumping.	person can handle unit and run the unit properly perform & completed									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:					Under Supervision						
					Standalone						
	4.3 Nitrogen Pump unit & Nitrogen Tank										
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:					Under Supervision						
					Standalone						
	4.4 Power Pack										
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:					Under Supervision						
					Standalone						
	4.5 Control Cabin										
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:					Under Supervision						
					Standalone						

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment								
	4.6 CT Reel									
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the equipment:				Under Supervision					
					Standalone					
	4.7 Injector Head									
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the equipment:				Under Supervision					
					Standalone					
	4.8 Pressure Control Equipment									
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the equipment:				Under Supervision					
					Standalone					
	4.9 Basic BHA Components									
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the tools:				Under Supervision					
					Standalone					

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed						Assessor Comment		
5. Job Supervision (if applicable) <i>Please complete this section if you perform any supervisory role during operation</i>									
Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
Please ✓ accordingly to confirm the role of the employee during operation							Full Supervisor:		
							2nd / Night Supervisor:		

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3: To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback (Please indicate if employee is able to execute the job <u>UNDER SUPERVISION</u> or <u>STANDALONE</u>)
05-Mei-24	Perform pumping operation acid wash Angsi well B17S. Perform bullheading injectivity test and record result. After complete injectivity test and good result to continues perform solvent and tubing pickling pumping and soak 2 hours. Mixing hcl 15% main treatment and to pumping. After mixing and pumping main treatment and continues mixing main treatment standalone acid system (sas) and to pumping. MASTP 1200PSI. After all complete activity process injectivity test and record result and comparing result before and after pumping main treatment.	personnel give full commitment during on job good job! keep it up

Please tick (✓) category of services performed:

Standard Services:

- Wellbore Cleanout
- CT Cementing
- Nitrogen Operations
- Pumping Services

Advanced Services

- CT Fishing
- CT Milling
- CT Logging
- CT Perforation