

# DIMENSION BID

## SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	MUHAMMAD AQISH BIN ZAINUDIN	COB Date	02.07.2024
Position	TRAINEE SLICKLINE ASSISTANT	RTB Date	30.07.2024
Client	SEA HIBISCUS	Location	SAINT JOSEPH
Platform	SJIT-F	Well	SJ-601S, SJ-603L, SJ-609C, SJ-609A, SJ-608A
Assessed By	Name: <u>Heddy Joseph</u>	Position:	<u>Slickline Operator</u>

### RATING LEGEND:

<b>STRONG</b>	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
<b>ADEQUATE</b>	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
<b>IMPROVEMENT NEEDED</b>	Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)							
	STRONG			ADEQUATE			IMPROVEMENT NEEDED	
	10	9	8	7	6	5	4	3

### Safety Awareness (20%)

- a. Usage of Personal Protective Equipment
- b. Participation in ACT
- c. Understanding of PTW System
- d. Worksite House Keeping

			✓						
			✓						
			✓						
			✓						

### Work Performance (20%)

- e. Initiative and Creativity
- f. Decision Making Capability
- g. Understanding of Job Scope
- h. Tools Inventory and Reporting
- i. Work Quality
- j. Reporting
- k. Punctuality and Time Keeping
- l. Teamwork
- m. Communication
- n. Leadership Skills
- o. Adaptability to Work Environment/Surrounding
- p. Attitude
- q. Discipline

			✓						
			✓						
			✓						
			✓						
			✓						
		✓							
			✓						
			✓						
			✓						
			✓						

### REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

Good Team work and keen to improved skill and knowledge on slickline ops.  
keep it up.

Assessed By (Operator)	
Name	<u>Heddy Jan Joseph.</u>
Date	<u>20/07/2024</u>

# DIMENSION BID

## SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment								
1. Pre-Job Preparation	A) Perform pre checklist on all equipment. B) To check all hoses was tight and secure. C) Ensure all tools being prepared prior to job being perform. D) Ensure all pressure hose from powerpack to RSU being secure with web check. E) Barricade worksite & wellhead area before perform rigging up.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
2. Surface Equipment Rig-up	A) Make up PCE. B) Put grease on all lubricator connection before connecting it. C) Check O-Ring before make up the lubricator, change it if damaged. D) Discard/cut wire if needed. E) Check any damage on all tub thread. F) Hook up all hoses & check all hoses for any damage before use. G) Check all PCE equipment validity before use.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
3. Tools / Equipment Preparation	A) Service & function test tool before using it. B) Check connection for all tools before run in hole. C) Check any thread damage on tools before/after use. D) File any tools that have sharp edges to prevent from being out. E) Clean any tool that already been use. F) Inventory tools in toolbox. G) Checking all size of tools is suitable to use.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>	Found out 3" GS pulling tool retainer was broken. After new retainer arrived from shore, immediately service and makeup the GS pulling tool and function test it. Problem was solved successfully.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2

Type of Task	Tasks Performed	Assessor Comment									
5. Downhole Tools Servicing/Redressing/Maintenance	a) Make up drift 2.735" with tandem. b) Make up 2.5" RS pulling tool c) Make up drift 2.867" with tandem d) Redress 2" 58 pulling tool e) Service 3" and 2.5" wire scratcher wires. f) Makeup, redress and service 3" GS pulling tool										
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	



