

D. Rig up Wireline Surface Equipment

a. List out all surface equipment (Surface and Pressure Gauge)

1. Stuffing box ✓
2. Blow out preventor (BOP) ✓
3. Lubricator ✓
4. Ball valve ✓
5. Quick test sub ✓ (QTS)
6. Generator set
7. Power pack
8. Cross over
9. Lubricator clamp
10. Wireline winch
11. Wireline mast
12.
13.

b. Describe how to connect lubricator section

i) Horizontal

- Lay down using trolley and stand using string or rope to connect lubricator to PCE

ii) Vertical


- properly to perfectly connect pin to box to union to avoid damaging the O-ring


 GAZALI MEHRY
 Operation Manager
 Dimension Bid (M) Sdn Bhd
 (East Malaysia Operation)

1/2/2022

Note: Provide drawing and parts description on separate paper/page

c. Sketch the equipment required while rigging up from x-mas tree until stuffing box



Note: Provide drawing and parts description on separate paper/page

[Signature]
GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)

4/8/2022

d. What should weight indicator attached with? ✓

- Hay pulley

e. What is the meaning of rigging up and rigging down?

- Rigging up state to prepare equipment of SE and PCE

- Rig down state for dismantle equipment for end of operation

f. What is power pack hose size used at Dimension Bid?

- Supply = 1" ✓

- Return = 1 1/4" ✓

g. What are the safety precautions required upon completed hook up hydraulic hose to RSU

- Make sure the connection is tight ✓

- Make sure the lock ring in place ✓

h. List out the safety precaution while rigging up and rigging down

- Fully PPE ✓

- Lifting procedure ✓

- Rig up and rig down procedure ✓

Note: Provide drawing and parts description on separate paper/page



GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)

1/3/2022



