

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	MOHD BURHAN BIN YUSOF	COB Date	09-Jun-24
Position	EQUIPMENT OPERATOR 2	RTB Date	03-Jul-24
Client	PCSB	Location	Tiong B
Platform	TIONG	Well	B01
Assessed By	Name: ENSKU NAZRI BIN ENSKU JALIL Position: PUMPING SUPERVISOR		

RATING LEGEND:

STRONG Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

ADEQUATE Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good

IMPROVEMENT NEEDED Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
---------------------	-------------------------------------	--	--	--	--	--	--	--	--


Assessment Criteria	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
Safety Awareness (20%)									
a. Usage of Personal Protective Equipment		✓							
b. Participation in UAUC			✓						
c. Understanding of PTW System			✓						
d. Worksite House Keeping		✓							

Assessment Criteria	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
Work Performance (20%)									
e. Initiative and Creativity			✓						
f. Decision Making Capability				✓					
g. Understanding of Job Scope			✓						
h. Tools Inventory and Reporting				✓					
i. Work Quality		✓							
j. Reporting				✓					
k. Punctuality and Time Keeping		✓							
l. Teamwork		✓							
m. Communication			✓						
n. Leadership Skills			✓						
o. Adaptability to Work Environment/Surrounding				✓					
p. Attitude	✓								
q. Discipline	✓								

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

- Good knowledge on equipment given to operate

- Good communication and teamwork during operation

Assessed By [Supervisor]	
Name	ENSKU NAZRI B. CHE ENSKU JALIL
Date	03 JULY 2024

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																												
1. Pre-Job Preparation	1. Attend toolbox and morning meeting with CSR. 2. Assisted crew in lifting all Pumping equipment and spot unit. 3. Pre-check/EMC1 all Pumping equipment before the job.	Good.																												
	<table border="1"> <tr> <td rowspan="2">Rating (by SUPERVISOR)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>											Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
	10	9	8	7	6	5	4	3	2																					
2. Surface Equipment Rig-up	1. Rig up pumping surface line From Pump unit to Pumping Tee Geowell 2. Assist crew to rig up BMX Line to Pump unit 3. Rig up 4" hose from Tank to BMX and Pump unit. 4. Spot Flood light, container electric cable to junction box. 5. Rig up wilden pump, 2" spring hose and air hose from sea deck to main deck.	can make decision to line up pumping line to well.																												
	<table border="1"> <tr> <td rowspan="2">Rating (by SUPERVISOR)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>											Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
	10	9	8	7	6	5	4	3	2																					
3. Tools / Equipment Preparation	1. Install air hose from compressor to SINGLE PUMP, BMX and wilden pump. 2. Perform EMC1 on SINGLE PUMP, BMX, Genset, Acomp for pre job. 3. Perform pressure test on pumping line 4. Fuel up all CTU equipment. 5. Assist crew Prepared chemical on top of BMX tank for mixing activity.	<ul style="list-style-type: none"> - can operate - good preparation - Teamwork during rigup. 																												
	<table border="1"> <tr> <td rowspan="2">Rating (by Operator)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>											Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
	10	9	8	7	6	5	4	3	2																					
4. Equipment	4.1 Batch Mixer 1. Install guard rail. 2. Rig up hydraulic hose from BM power pack to BM tank. 3. Rig up 4" hose for overboard line. 5. Visually check for any oil leakage at BMX engine and hdraulic line. 6. Function test for BMX, agitator and c-pump working properly. 7. Start and run BMX for mixing activity.	<ul style="list-style-type: none"> - can stand alone operate BMX without supervision. - Team work during rigup. 																												
	<table border="1"> <tr> <td rowspan="2">Rating (by SUPERVISOR)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>											Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
	Rating (by SUPERVISOR)												STRONG			ADEQUATE			IMPROVEMENT NEEDED											
10		9	8	7	6	5	4	3	2																					
Employee was able to OPERATE the equipment:				Under Supervision																										
				Standalone			✓																							

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment									
	4.2 Pump Unit 1. Function test and make sure all hydraulic hose connected and does not have any leakage (EMC1). 2. Assemble pump shaft 3. Check OPSD functionality. 5. Always monitor pumping pressure while pumping. 6. Always alert on panel control indicator while performing pumping to avoid worse damage to single pump.	- Can stand alone operate single pump without supervision. - Good communication during pumping operation.									
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
	Employee was able to OPERATE the equipment:				Under Supervision						
					Standalone						
	4.3 Nitrogen Pump unit & Nitrogen Tank										
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
	Employee was able to OPERATE the equipment:				Under Supervision						
					Standalone						
	4.4 Power Pack										
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
	Employee was able to OPERATE the equipment:				Under Supervision						
					Standalone						
	4.5 Control Cabin										
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
	Employee was able to OPERATE the equipment:				Under Supervision						
					Standalone						

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment								
	4.6 CT Reel									
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the equipment:				Under Supervision					
					Standalone					
	4.7 Injector Head									
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the equipment:				Under Supervision					
					Standalone					
	4.8 Pressure Control Equipment									
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the equipment:				Under Supervision					
					Standalone					
	4.9 Basic BHA Components									
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the tools:				Under Supervision					
					Standalone					

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed						Assessor Comment		
5. Job Supervision (if applicable) <i>Please complete this section if you perform any supervisory role during operation</i>									
Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
Please <input checked="" type="checkbox"/> accordingly to confirm the role of the employee during operation				Full Supervisor					
				2nd / Night Supervisor					

