



D. Rig up Wireline Surface Equipment

- a. List out all surface equipment (Surface and Pressure Gauge)

1.	Generator Set
2.	Air Compressor
3.	Power Pack
4.	Wireline couch
5.	Master Curve Line
6.	Puffing Box
7.	Lubricator
8.	Cross over
9.	Pop
10.	QTS
11.	Ball Valve
12.	
13.	

- b. Describe how to connect lubricator section

- i) Horizontal



* Lay down using trolley and stand using strap or rope to connect lubricator to other ACE.

- ii) Vertical

* Align the pin to box perfectly to avoid damaging the O-Ring.


GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)

20/10/21



Note: Provide drawing and parts description on separate paper/page

17/12/21

GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)



d. What should weight indicator attached with?

* Load cell / heavy pulley

e. What is the meaning of rigging up and rigging down?

* Rig up → Prepare equipment for operation (set & PLE)
* Rig down → Disassemble equipment ready for demob / move to other location.

f. What is power pack hose size used at Dimension Bid?

1 inch - apply
1 1/2 inch - return

g. What are the safety precautions required upon completed hook up hydraulic hose to RSU

* Make sure connection is tight.
* Make sure the locking ring is place.

h. List out the safety precaution while rigging up and rigging down

* full PPE
* follow procedure
* Read manual.

Note: Provide drawing and parts description on separate paper/page

GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)

17/12/21