

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	MUHAMMAD ALIFF BIN ZULKEFLI	COB Date	17-Mei-24
Position	EQUIPMENT OPERATOR 2	RTB Date	12-Jun-24
Client	PCSB	Location	DULANG
Platform	DULANG CHARLIE	Well	D 06S
Assessed By	Name: MOHD SUKRI IS AWANG	Position:	SUPERVISOR COIL TUBING

RATING LEGEND:

STRONG	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
ADEQUATE	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
IMPROVEMENT NEEDED	Performance did not consistently meet expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
Safety Awareness (20%)	10	9	8	7	6	5	4	3	2
a. Usage of Personal Protective Equipment	✓								
b. Participation in UAUC			✓						
c. Understanding of PTW System			✓						
d. Worksite House Keeping		✓							
Work Performance (20%)									
e. Initiative and Creativity		✓							
f. Decision Making Capability			✓						
g. Understanding of Job Scope			✓						
h. Tools Inventory and Reporting			✓						
i. Work Quality			✓						
j. Reporting			✓						
k. Punctuality and Time Keeping			✓						
l. Teamwork		✓							
m. Communication			✓						
n. Leadership Skills			✓						
o. Adaptability to Work Environment/Surrounding			✓						
p. Attitude			✓						
q. Discipline		✓							

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

* Overall good

Assessed By (Supervisor)	MOHD SUKRI IS AWANG
Name	MOHD SUKRI IS AWANG
Date	12 JUNE 2024

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment									
1. Pre-Job Preparation	1. Attend toolbox and morning meeting with CSR. 2. Pre-check/EMC1 all CTU equipment before run the job. 3. Assisted crew in lifting all CTU equipment and spot unit. 4. Pre-check/EMC1 all CTU equipment before run the job. 5. Prepare supporting document prior load out. 6. Split crew to day and night shift after complete rig up CTU equipment.	* Done									
		Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED
		10	9	8	7	6	5	4	3	2	
2. Surface Equipment Rig-up	1. Rig up 4" hose from FST to batch mixer and single pump . 2. Rig up treating iron from single pump to combi bop . (Kill line port) 3. Assist Cetco to rig up line flowback to overboard line and flowline well 4. Spot/arrange flood light, control cabin and tool container electric cable to junction box. 5. Rig up water injection line from wel to fluid storage tank. 6. Rig up wilden pump, 2" spring hose and air hose	* Done									
		Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED
		10	9	8	7	6	5	4	3	2	
3. Tools / Equipment Preparation	1. Installing air hose from compressor to SP02, BMX02 and wilden pump 2. Perform EMC1 on Air Compressor and Genset for pre job. 3. Fuel up all CTU equipment. 4. Redress 2x1 plug valve	* Done									
		Rating (by Operator)			STRONG			ADEQUATE			IMPROVEMENT NEEDED
		10	9	8	7	6	5	4	3	2	
4. Equipment	4.1 Batch Mixer 1. Assist operator to mix gel 50bbl and soda ash 35bbl 2. Function test C-pump and actuator of batch mixer 3. Assist Batch Mixer Operator to mix chemical. 4 Assist to mix TIW on fluid storage tank 5. Assist chemical specialist Hazwan on preparation of Pickling acid. 6. Assist cementer mix cement	* Done									
		Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:					Under Supervision			Standalone			

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment											
<p>4.2 Pump Unit</p> <p>1. Connect hydraulic hose. 2. Install universal shaft. 3. Greasing shaft. 4. Replace rubber insert and packing plunger. 5. Rig up pumping line to CT reel and kill line to bop. 6. Priming pump before start pumping. 7. Standalone pump for pumping cement.</p>	<p>* Done</p>												
	Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED			
				10	9	8	7	6	5	4	3	2	
	Employee was able to OPERATE the equipment: <table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>										Under Supervision		Standalone
Under Supervision													
Standalone													
<p>4.3 Nitrogen Pump unit & Nitrogen Tank</p> <p>1. Assist crew to rig up 2" HP treating line to CT reel and include bleed off line. 2. Assist crew to rig up cryogenic hose from N2 tank to inlet and outlet line on NCV.</p>	<p>* Done</p>												
	Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED			
				10	9	8	7	6	5	4	3	2	
	Employee was able to OPERATE the equipment: <table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>										Under Supervision		Standalone
Under Supervision													
Standalone													
<p>4.4 Power Pack</p> <p>1. Assist to rig up hydraulic power hose to Injector Head. 2. Assist to rig up hose from CTU Power Pack to Control Cabin</p>	<p>* Done</p>												
	Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED			
				10	9	8	7	6	5	4	3	2	
	Employee was able to OPERATE the equipment: <table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>										Under Supervision		Standalone
Under Supervision													
Standalone													
<p>4.5 Control Cabin</p> <p>1. Assist crew rig up hydraulic hose and connected to CT Reel, Injector Head and BOP.</p>	<p>* Done</p>												
	Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED			
				10	9	8	7	6	5	4	3	2	
	Employee was able to OPERATE the equipment: <table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>										Under Supervision		Standalone
Under Supervision													
Standalone													

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment										
<p>4.6 CT Reel</p> <p>1. Assist to connect hydraulic hose from control cabin. 2. Assist crew to flag coil at target depth 3. Assist crew to install crash guard on CIDF reel. 4. Rig up swivel in reel. 5. Assist crew install CT Drum into cidf. 6. Assist crew to install horse head at CIDF</p>	<p>* Done</p>											
	Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
				10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the equipment:			Under Supervision								
<p>4.7 Injector Head</p> <p>1. Assist crew to install injector head on top of jacking frame. 2. Assist crew to install goose neck on top of injector head. 3. Assist crew to install auxiliary hose at injector head. 4. Assist crew to stab in coil to injector head. 5. Assist crew top up Injector Lube Oil before start job</p>	<p>* Done</p>											
	Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
				10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the equipment:			Under Supervision								
<p>4.8 Pressure Control Equipment</p> <p>1. Assist to connect hydraulic hose from Control Cabin to SBOP and Combi. 2. Assist crew to redress Combi Bop . Clean up blind sheer and pipe slip. 3. Assist crew replace rubber stripper</p>	<p>* Done</p>											
	Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
				10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the equipment:			Under Supervision								
<p>4.9 Basic BHA Components</p> <p>1. Assist crew to make up BHA. 2. Assist CT Supervisor to prepare BHA to be use during job. 3. Use nozzle single bore.</p>	<p>* Done</p>											
	Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
				10	9	8	7	6	5	4	3	2
	Employee was able to OPERATE the tools:			Under Supervision								

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed		Assessor Comment						
5. Job Supervision (if applicable) <i>Please complete this section if you perform any supervisory role during operation</i>	1. Conduct short briefing to new incomer prior to rig up treating iron,bmx,single pump and widen pump. 2. Conduct training for new incomer how to prepare permit,certificate on site. 3. Conduct training to equipment operator training and JFE to operate single pump and BMX. 4. Assist and monitor new incomer EOT/JFE to preparation chemical before mixing. 5. Conduct training to EOT to disassemble fluid end at single pump,swivel and plug valve.		* Done						
Rating (by SUPERVISOR)	STRONG		ADEQUATE			IMPROVEMENT NEEDED			
	10	9	8	7	6	5	4	3	2
Please ✓ accordingly to confirm the role of the employee during operation			Full Supervisor						
			2nd / Night Supervisor						

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3: To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback (Please indicate if employee is able to execute the job <u>UNDER SUPERVISION</u> or <u>STANDALONE</u>)
20-Mei-24	Perform ctu zone shut off well D 06S. Perform injectivity test after slickline tubing punch. After injectivity test continues to clean out to target depth 2139m Ca plug. CT run set cement retainer at 2107m and perform cementing 27 bbls. After cementing ct run for cleanout until top of cement retainer at 2107m.	✓ Done

Please tick (✓) category of services performed:

Standard Services:

Wellbore Cleanout
CT Cementing
Nitrogen Operations
Pumping Services

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Advanced Services

CT Fishing
CT Milling
CT Logging
CT Perforation

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>