



**SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK**

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment
1. Pre-Job Preparation	Morning briefing by Supervisor on site and Operator. Talk about safety and job plan to ensure all crew aware about hazard on worksite. Using full PPE during working (Safety Helmet, Safety Glasses, Hand Gloves, Safety Boots)	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
2. Surface Equipment Rig-up	Reposition Equipment (Power Pack, Reel Skid Unit, Lubricator Skid, BOP skid, SWCP, Wireline Mast). Make up PCE on surface. PCE configuration 5.00"-4 Box x 3.50" - 9.20# JFE Bear Pin, 5.75"-4 Box x 5". 4 Pin, 3" Ball Valve + 3" PIT + 3" Dual Ram BOP + 3" Quick Test Sub + 8ft x 4 Lubricator + 3" Stuffing Box.	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
3. Tools / Equipment Preparation	Prepare tool strings. 1.7/8" Rope Socket, 1.7/8" Swivel Joint, 1.7/8" x 3ft Normal Stem, 5ft Normal Stem, 1.7/8" Knuckle Joint, 1.7/8" 30 Stroke Link Jar. Prepare Tools. 2.720" Nipple Less Drift,	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
4. Equipment	<b>4.1 PP</b> Check water coolant level/radiator. Check diesel oil/tank level. Check hydraulic oil tank/level. Check flame trap condition and clean up the flame trap by using degreaser. Check hydraulic hose connection/Fitting. Check hydraulic pump/rpm cable/gauge.	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<b>4.2 AC</b>	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<b>4.3 GS</b>	

# SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<b>4.4 CP</b> Check connection if any leaks. Function test whole system/function test pressure test line. Top-up hydraulic oil. Check pressure gauge. Check control line manifold complete with pressure gauge.	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<b>4.5 TP</b> Function test whole system. Check pressure gauge. Check leaking. Check main air supply regulator.	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<b>4.6 PCE</b> Carried out hydro test of full length of PCE. Check o-ring. Check thread connection. Change packing, Lower Gland, BOP Plunger on SBX Check validity of PCE. Function test BOP.	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<b>4.7 Mast</b>	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<b>4.8 Weight &amp; Measuring Devices</b> Check counter deep and cable. Check measuring wheel. Check hay pulley. Check foot block. Check odometer. Pump w15 fluid	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<b>4.9 Downhole Tools</b> Make up 1.7/8" Rope Socket.	
Assessor's Evaluation:	<b>Level of Skill &amp; Knowledge</b> <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	

## JOB DETAIL:

DATE	WELL NO.	JOB TYPE	STATUS (COMPLETE / INCOMPLETE)
21.03.2023	Well 105	Set 2.720" SIM PEAK Plug	completed
01.04.2023	Well 116	Set 2.813" x-selective test tool	completed

**SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK**

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment