

ENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment									
2- Job Preparation	1 Always do routine check on power pack such as diesel engine oil, coolant, and hydraulic fluid level. 2 Do rope socket 1 7/8" 3 Check service tools and replace shear pin with new ones if shear pin on tools shear. 4 Pump swcp mv. scssv to open actuator and trcssv 5 learn how to changeout stuffing box packing, and upper gland and lower gland from 0.125" to 0.108"										
	Rating (by Operator)	10	9	8	7	6	5	4	3	2	
Surface Equipment Rig	1. learn how to rig up using gantry crane. 2. gain more knowledge the position of wireline e Equipment at wireline deck										
	Rating (by Operator)	10	9	8	7	6	5	4	3	2	
3. Tools / Equipment Preparation	1. learn how to pinning FRC JAR DOWN & FRC JAR UP 2. learn how to setting peak jar. 3. make a preparation of tools for next rih. 4. tighten crossover connect with service tools before RIH tools.										
	Rating (by Operator)	10	9	8	7	6	5	4	3	2	
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>	NA										
	Rating (by Operator)	10	9	8	7	6	5	4	3	2	
5. Downhole Tools Servicing/Redressing/Maintenance	1. learn how to redress FRC JAR DOWN & UP. 2. learn how to check condition of shear pin either half shear of shear.										
	Rating (by Operator)	10	9	8	7	6	5	4	3	2	

Type of Task	Tasks Performed	Assessor Comments								
6. Tools Inventory & Reporting	1. Always do the inventory to make sure all tools is available to use for wireline activity.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2

7. Equipment Operation	[Operator to rate TSA / SA / SSA competency in operating the equipment]									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Power Pack	/								
	Air Compressor									
	GenSet									
	Control Panel	/								
	Test Pump	/								
	Pressure Control Equipment	/								
	Mast									
	Weight & Measuring Devices									
	Downhole Tools	/								
	Total	0	0	0	0	0	0	0	0	0
	Comments by Operator [please specify competency gaps / area of improvement]									
	Always want to learn new tool for him. recommended to expose new operation.									

EXECUTE THE WELL SERVICES OPERATION (IF ANY)										
(Operating Winch)										
Date / Location / Well No. / Job Type	Activity Summary	Toolstring Configuration								
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Comments by Operator [please specify competency gaps / area of improvement]									

