

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	AHMAD SHAZMEER BIN MOHAMAD	COB Date	22.12.2023
Position	EQUIPMENT OPERATOR TRAINEE	RTB Date	4.1.2024
Client	PCSB	Location	RDPA
Platform	RESAK	Well	A-17
Assessed By	Name: MAT NOR HISSAM		Position: COILED TUBING SUPERVISOR

RATING LEGEND:

STRONG Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

ADEQUATE Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good


IMPROVEMENT NEEDED Performance did not consistently meet expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)									
	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
	10	9	8	7	6	5	4	3	2	1
Safety Awareness (20%)										
a. Usage of Personal Protective Equipment	✓									
b. Participation in UAUC		✓								
c. Understanding of PTW System		✓								
d. Worksite House Keeping			✓							
Work Performance (20%)										
e. Initiative and Creativity			✓							
f. Decision Making Capability				✓						
g. Understanding of Job Scope				✓						
h. Tools Inventory and Reporting										
i. Work Quality			✓							
j. Reporting										
k. Punctuality and Time Keeping		✓								
l. Teamwork		✓								
m. Communication		✓								
n. Leadership Skills			✓							
o. Adaptability to Work Environment/Surrounding		✓								
p. Attitude		✓								
q. Discipline		✓								

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

Assign as PTW applicant and BMX operator during working period.

Able to stand alone operator BMX for normal operation.

Assessed By [Supervisor]	
Name	Mat Nor Hissam
Date	3/1/2024.

Doc Ref No : CTS-FORM-90
 Revision No : 01
 Effective Date : 21/08/2023
 (Rev.00, Dated: 22/09/19-OBSOLETE)

CONTROLLED COPY

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK PART 2. To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
1. Pre-Job Preparation	1) Attend platform coordination meeting. 2) Meeting with WSS and all crew discuss for next planning Safety sharing by crew. 3) Revalidate E-PTW. 4) Do EMC1 for pre-job.	Done																		
	Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
2. Surface Equipment Rig-up	1) Assist crew to skid well from A-09 to A-17. 2) Assist crew to rig up pumping surface line from SP01 to coil reel and killport to combi BOP. 3) Assist crew to rig up N2 line from NCV to CT Reel. 4) Rig up 4'hose from fluid storage tank to SP01. 5) Rig up 4'hose from BMX tank to SP01. 6) Open hatch cover, rig up well head X-over, single BOP.	Good Job																		
	Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
3. Tools / Equipment Preparation	1) Installing air hose from compressor to SP01, BMX01 and wilden pump. 2) Perform EMC1 on Air Compressor and Gensel for pre job. 3) Function test spin cap nozzle and break BHA. 4) Break surface filter line and clean surface filter.	Good Job																		
	Rating (by Operator) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
4. Equipment	4.1 Batch Mixer 1) Mix 100 TSW inside FST. 2) Spot chemical basket on maindeck. 3) Assist to mix TIW. 4) Mix GEL 300bbl into BMX tank. 5) Mix 200bbl pre flush solven. 6) Mix 40bbl main treatment 15% HCL.	Good assist -																		
	Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
	STRONG			ADEQUATE			IMPROVEMENT NEEDED													
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:	<table border="1"> <tr> <td>Under Supervision</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>Standalone</td> <td><input type="checkbox"/></td> </tr> </table>	Under Supervision	<input checked="" type="checkbox"/>	Standalone	<input type="checkbox"/>															
Under Supervision	<input checked="" type="checkbox"/>																			
Standalone	<input type="checkbox"/>																			

Doc.Ref.No.: CTS-FORM-90
 Revision No.: 01
 Effective Date: 21/08/2023
 (Rev.00,Dated:22/09/19-OBSOLETE)

CONTROLLED COPY

2

Scanned with CamScanner

Scanned with CamScanner

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK PART 2 To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
	4.2 Pump Unit 1) Assist crew to rig up surface pumping line. 2) Assist crew to change spring and rubber seal fluid end. 3) Pressure test pumping line at 5000psi for 3minutes. 4) Flushing coil with 26bbbl.	Good assist																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	(7)
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>Standalone</td> <td><input type="checkbox"/></td> </tr> </table>	Under Supervision	<input checked="" type="checkbox"/>	Standalone	<input type="checkbox"/>														
Under Supervision	<input checked="" type="checkbox"/>																			
Standalone	<input type="checkbox"/>																			
	4.3 Nitrogen Pump unit & Nitrogen Tank 1) Assist crew to rig up 2" HP Treating line to CT Reel and include bleed off line. 2) Assist crew to rig up cryogenic hose from N2 tank to inlet and outlet line on NCV.	Good assist																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	(5)
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>Standalone</td> <td><input type="checkbox"/></td> </tr> </table>	Under Supervision	<input checked="" type="checkbox"/>	Standalone	<input type="checkbox"/>														
Under Supervision	<input checked="" type="checkbox"/>																			
Standalone	<input type="checkbox"/>																			
	4.4 Power Pack 1) Assist to rig up hydraulic power hose to injector head. 2) Assist to rig up hose from CTU Power Pack to Control Cabin. 3) Disconnect C/BOP and SBOP hose and roll into control cabin.	Good assist																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	(5)
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>Standalone</td> <td><input type="checkbox"/></td> </tr> </table>	Under Supervision	<input checked="" type="checkbox"/>	Standalone	<input type="checkbox"/>														
Under Supervision	<input checked="" type="checkbox"/>																			
Standalone	<input type="checkbox"/>																			
	4.5 Control Cabin 1) Assist crew to rig up hydraulic hose and connected to CT Reel, Injector Head and BOP.	Good assist																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	(7)
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>Standalone</td> <td><input type="checkbox"/></td> </tr> </table>	Under Supervision	<input checked="" type="checkbox"/>	Standalone	<input type="checkbox"/>														
Under Supervision	<input checked="" type="checkbox"/>																			
Standalone	<input type="checkbox"/>																			

Doc Ref. No. CTS-FORM-90
 Revision No.: 01
 Effective Date: 21/08/2023
 (Rev.00, Dated. 22/09/19-OBSOLETE)

CONTROLLED COPY

3

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK PART 2 To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
	4.6 CT Reel 1) Assist crew install CT Drum into CIDF. 2) Assist crew to connect all hydraulic hose from control cabin. 3) Mixing corroded inhibitor with diesel and pour into the tank of CIDF. 4) Spray CI at coil to avoid from rusty.	Good assist.																		
Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		Under Supervision <input type="checkbox"/> Standalone <input checked="" type="checkbox"/>																		
	4.7 Injector Head 1) Assist to step in CT Injector Head	Good assist.																		
Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		Under Supervision <input type="checkbox"/> Standalone <input checked="" type="checkbox"/>																		
	4.8 Pressure Control Equipment 1) Assist to connect hydraulic hose from Control Cabin to SBOP and Combl.	Good -																		
Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		Under Supervision <input type="checkbox"/> Standalone <input checked="" type="checkbox"/>																		
	4.9 Basic BHA Components 1) Assist crew make up connector and BHA. 2) Assist crew pull test and pressure test CT connector. 3) Assist CT Supervisor to prepare BHA to be use during job.	Good assist.																		
Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the tool:		Under Supervision <input type="checkbox"/> Standalone <input checked="" type="checkbox"/>																		

Doc Ref No : CTS-FORM-90
 Revision No.: 01
 Effective Date: 21/08/2023
 (Rev.00,Dated.22/09/19-OBSOLETE)

CONTROLLED COPY

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment								
5. Job Supervision (if applicable) Please complete this section if you perform any supervisory role during operation										
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Please ✓ accordingly to confirm the role of the employee during operation				Full Supervisor			2nd / Night Supervisor		

Doc Ref No.: CTS-FORM-90
 Revision No.: 01
 Effective Date: 21/08/2023
 (Rev.00, Dated: 22/09/19-OBSOLETE)

CONTROLLED COPY

5


Scanned with CamScanner

Scanned with CamScanner

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3 To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback <small>(Please indicate if employee is able to execute the job UNDER SUPERVISION or STANDALONE)</small>
24 DEC 2023 to 4 JAN 2024	CTU activities : Scale Cleanout. - To perform CT scale cleanout from slickline HUD - Pressure test SPIN CAP NOZZLE - Pull test connector BHA.	- Good training - Good teamwork - Able to stand alone operate BHA. 

Please tick (✓) category of services performed:

Standard Services:	Wellbore Cleanout <input checked="" type="checkbox"/>	Advanced Services	CT Fishing <input type="checkbox"/>
	CT Cementing <input type="checkbox"/>		CT Milling <input type="checkbox"/>
	Nitrogen Operations <input type="checkbox"/>		CT Logging <input type="checkbox"/>
	Pumping Services <input type="checkbox"/>		CT Perforation <input type="checkbox"/>

Doc. Ref No : CTS-FORM-90
 Revision No. : 01
 Effective Date: 21/08/2023
 (Rev.00,Dated.22/09/19-OBSOLETE)

CONTROLLED COPY