









DIMENSION BID

Slickline Assistant Onshore On-the-Job Training Record

Trainee's Name:	MUHAMMAD ARMIN RIFA'I BIN ANWAR	Job Title:	TSA
Month:	0905	Training Period:	


No.	Main Tasks (please describe)	Training Date	Training Time		Total Hours	PR*	Signature	
			From	To			Trainee	Instructor
1.	- Assist mechanic servicing AC#11.	30/7/2023	8:00am	5:00pm				
2.	- Proceed Servicing AC#11 and Gonset # 05	31/7/2023	8:00am	5:00pm				
3.	- Assist mechanic servicing gonset # 05 - Change wire to braided and 0.125 to flyline unit.	31/8/2023	8:00am	5:00pm				

DIMENSION BID

4.	- Assist PCE for servicing hydraulic pump from CP #03.	2/8/2023	8:00am	5:00pm		AKMS	
5.	pressure - Assist PCE pressure test low tongue valve - Service and washdown lubricator skid.	3/8/2023	8:00am	5:00pm		AKMS	

Total Hours

* Performance Rating (PR): S - Strong A - Adequate NI - Improvement Needed

Approved by:		
Designation	FSM	
Date	6/19/23	

Overall Assessment:
 - understand 10 ton valve attached to PIT -
 - Able to explain 10 ton valve connection - hammer with

30 July 2023 to 3 August 2023 (MUHAMMAD ARMIN RIFQI BIN ANUAR)

-Assist mechanic for servicing Air compressor#11

FUNCTION:Supply compressed air to control panel

- *Change fuel filter
- *Change oil filter
- *Change air filter
- *Radiator hose
- *Change oil engine

-Setup supervisor cabin for inspection

-Assist mechanic servicing Genset#05

FUNCTION:Converts the power of mechanical energy to electrical energy

- *Change oil engine
- *Change fuel filter
- *Change oil filter

-Change wire braided and 0.125 to flyline unit

FUNCTION:To turn the wire drum to lower and rise tools strings in the wells that require wireline servicing

-Assist PCE for servicing hydraulic pump from Control Panel#03

FUNCTION:Pump hydraulic to equipment

- *Redress O ring and dismantle the whole components of pump.
- *Cleanup the component and perform visual check of the component profile.
- *Assemble with new original o ring kit and rebuild the whole components
- *Assist pce to function test pump and assemble at the control panel



-Assist PCE for pressure test Low Torque Valve

FUNCTION:To control the flow by opening and closing



-Assist PCE for service and washdown lubricator skid

FUNCTION:To provide a space for the tool to be contained in under pressure, when opening and closing the wellhead.