



D. Rig up Wireline Surface Equipment

a. List out all surface equipment (Surface and Pressure Gauge)

1. Generator
2. Air compressor
3. Power Pack
4. Reel strid unit
5. stuffing box
6. hydraulic mast
7. Lubricator
8. Cross over
9. BOP
10. QTS
11. Ball valve
12. SWOP
13. Hay pulley


b. Describe how to connect lubricator section

i) Horizontal

- lay down using trolley and stand using sling or rope to connect lubricator to other DCE

ii) Vertical

- Align the pin to box perfectly to avoid damaging the ring


GAZALI MEHRY
 Operation Manager
 Dimension Bid (M) Sdn Bhd
 (East Malaysia Operation)



d. What should weight indicator attached with?

- Load cell

- Hoop pulley

e. What is the meaning of rigging up and rigging down?

Rig up : prepare equipment for operation.

Rig down : Disassemble equipment ready for demob / move to other location.

f. What is power pack hose size used at Dimension Bid?

1" : supply

1 1/2" : Return.

g. What are the safety precautions required upon completed hook up hydraulic hose to RSU

- make sure connection is properly connected

- no leaking

- make sure the lock ring is in place.

h. List out the safety precaution while rigging up and rigging down

- Full PPE

- Follow procedure

- No rushing

- Tool box talk before start job


Note: Provide drawing and parts description on separate paper/page

GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)

19/9/22

Note: Provide drawing and parts description on separate paper/page

c. Sketch the equipment required while rigging up from x-mas tree until stuffing box



Note: Provide drawing and parts description on separate paper/page

[Signature]
GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)

6/9/22



