



SLICKLINE ASSISTANT WORKBOOK

NAME	Hamizan Bin Awang
DATE OF JOIN	18/07/2022
CONTACT NO.	013 903 7625
RECEIVED DATE	8/8/2022
DATE COMPLETED	


GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)

1/12/22



D. Rig up Wireline Surface Equipment

a. List out all surface equipment (Surface and Pressure Gauge)

1. Air compressor
2. Power pack
3. Reel skid unit
4. Hydra wireline mast
5. stuffing box
6. Lubricator
7. BOP tree
8. crossover
9. ATS
10. Ball valve
11. SWCP
12. Hay pulley
13. Generator

b. Describe how to connect lubricator section

i) Horizontal

- Lay down using trolley and stand using sling or rope & connect lubricator to other PCE.

ii) Vertical

- Align the pin to box perfectly to avoid damaging the o-ring.


[Signature]
GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)

01/12/22

Note: Provide drawing and parts description on separate paper/page

- c. Sketch the equipment required while rigging up from x-mas tree until stuffing box

Stuffing Box



[Signature]
GAZALI MEHRY
 Operation Manager
 Dimension Bid (M) Sdn Bhd
 (East Malaysia Operation)

01/12/22



d. What should weight indicator attached with?

- load cell.
- Heavy pulley.

e. What is the meaning of rigging up and rigging down?

- rigging up means we assemble the PCE.
- rigging down means we disassemble the PCE.

f. What is power pack hose size used at Dimension Bid?

- 1" Power supply
- 1 1/4" Return

g. What are the safety precautions required upon completed hook up hydraulic hose to RSU

- make sure ~~the~~ connection is properly connected.
- no leaking
- make sure the lock ring is in place.

h. List out the safety precaution while rigging up and rigging down

- follow procedure
- Full PPE.
- Toolbox talk before start job.
- NO rushing.

Note: Provide drawing and parts description on separate paper/page


GAZALI MEHRY
Operation Manager
Dimension Bid (M) Sdn Bhd
(East Malaysia Operation)

01/12/22