

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	Mansyur Bin Wahyuddin	COB Date	27.5.24
Position	Slickline assistant 3	RTB Date	11.6.24
Client	Hibiscus	Location	SFDP-A
Platform	South Furious	Well	SF 10S / SF 11L
Assessed By	mohd jaidun	Position:	SLICKLINE OPERATOR

RATING LEGEND:

STRONG Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

ADEQUATE Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good


IMPROVEMENT NEEDED Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
Safety Awareness (20%)									
a. Usage of Personal Protective Equipment	✓								
b. Participation in ACT	✓								
c. Understanding of PTW System	✓								
d. Worksite House Keeping	✓								
Work Performance (20%)									
e. Initiative and Creativity		✓							
f. Decision Making Capability		✓							
g. Understanding of Job Scope		✓							
h. Tools Inventory and Reporting		✓							
i. Work Quality	✓								
j. Reporting		✓							
k. Punctuality and Time Keeping	✓								
l. Teamwork	✓								
m. Communication		✓							
n. Leadership Skills			✓						
o. Adaptability to Work Environment/Surrounding		✓							
p. Attitude	✓								
q. Discipline	✓								

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

- He can work independent with less supervision, good attitude able to work under pressure.

- I fully support for him going to next level.

Assessed By [Operator]	
Name	Mohd Jaidun
Date	11/6/2024

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment																										
1. Pre-Job Preparation	A. Conducted Permit to work and Tool box Talk. B. pre-Job briefing on operation. C. Walk around and ensure all potential hazard has been eliminated at the work site area. D. List down the equipment SN on site and validation. E. Check and ensure all the equipment based on check list. F. Prepared the DHT based on program/operation. G. Perform housekeeping before while and after operation.																											
	<table border="1"> <tr> <td rowspan="2">Rating (by Operator)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2								
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																					
	10	9	8	7	6	5	4	3	2																			
2. Surface Equipment Rig-up	A. Hook up the equipment hoses and ensure whip check attached. B. Ensure all PCE thread in good condition and apply grease before make up. C. Ensure O-ring attached and undamaged. D. Ensure all the Equipment Earthing cable installed E. Change stuffing Box packing if needed. F. Ensure The PCE equipment operated while and perform function test. G. Install anchor at the right point and ensured all shackle attached with safety pin. H. Perform function test on SWCP& Leak test on Hoses. I. Check and ensure the weight indicator operated well.																											
	<table border="1"> <tr> <td rowspan="2">Rating (by Operator)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2								
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																					
	10	9	8	7	6	5	4	3	2																			
3. Tools / Equipment Preparation	A. Prepared the DHT based on program/operation. B. Ensured the DHT operated well and suitable size used. C. Ensured the DHT correct pin install. Change if needed. D. Perform Function test and simulation test on surface. E. Service tools before and after operation. F. Ensure all connection tightened before operation.																											
	<table border="1"> <tr> <td rowspan="2">Rating (by Operator)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2								
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																					
	10	9	8	7	6	5	4	3	2																			
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>																												
	<table border="1"> <tr> <td rowspan="2">Rating (by Operator)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2								
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																					
	10	9	8	7	6	5	4	3	2																			
5. Downhole Tools Servicing/Redressing/Maintenance	A. Perform simulation test on surface on DHT and Ensure operated well. B. Make up Tools based on program. C. Ensure the tools used suitable. D. Pinning DHT and change packing for safety valve/plug if needed. E. Check and clean tools after operation. F. Ensure all cross over and DHT part connection tighten G. Function test safety valve flipper																											
	<table border="1"> <tr> <td rowspan="2">Rating (by Operator)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2								
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																					
	10	9	8	7	6	5	4	3	2																			

Type of Task	Tasks Performed	Assessor Comment								
6. Tools Inventory & Reporting	A. monitored the Tools movement and updated in inventory. B. Check and Ensure equipment list on site followed based on document given. C. Prepared Documentation for operation program given/material request/COG D. Done the Company Daily operation report/ daily equipment check list.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
7. Equipment Operation	[Operator to rate TSA / SA / SSA competency in operating the equipment]									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Power Pack		✓							
	Air Compressor									
	GenSet									
	Control Panel	✓								
	Test Pump		✓							
	Pressure Control Equipment		✓							
	Mast		✓							
Weight & Measuring Devices		✓								
Downhole Tools		✓								
Total		0	0	0	0	0	0	0	0	0
Comments by Operator [please specify competency gaps / area of improvement]										
EXECUTE THE WELL SERVICES OPERATION (IF ANY) (Operating Winch)										
Date / Location / Well No. / Job Type	Activity Summary	Toolstring Configuration								
8/6/2024/ SFDPA/ SF11L/ SET Px Prong	RIH 2" SB WITH PX PRONG FOR PX PLUG AT 2974FT WLD.	1.7/8" Tool string ROPE SOCKET SWIVEL JOINT NORMAL STEM 5FT KNUCKLE JOINT HYDRAULIC JAR 2" SB PX PRONG								
		STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
Comments by Operator [please specify competency gaps / area of improvement]										

Type of Task	Tasks Performed		Assessor Comment
JOB DETAIL:			
DATE	WELL NO.	JOB TYPE	STATUS (COMPLETE / INCOMPLETE)
27-31/5/24	SF 10S	TCC SGS FGS	COMPLETED
1-9/6/24	SF 11L	ZONE CHANGE/ TIC / SET PLUG	COMPLETED

To be completed by verifier (FSM)

SUMMARY OF OVERALL PERFORMANCE

		Weight	Score	
			Total	%
A	Safety Awareness	20	#REF!	#REF!
B	Work Performance	20	#REF!	#REF!
C	Technical Skills	60	52	44.571
	1. Pre-Job Preparation	8		
	2. Surface Equipment Rig-up	7		
	3. Tools / Equipment Preparation	8		
	4. Equipment Problem Troubleshooting	9		
	5. Downhole Tools Servicing/Redressing/Maintenance	6		
	6. Tools Inventory & Reporting	7		
	7. Equipment Operation	7		
D	TOTAL (A+B+C)	100		#REF!