

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	AHMAD HULAIF AIMAN BIN AHMAD HAMINIZA	COB Date	23/6/2024
Position	EQUIPMENT OPERATOR TRAINEE	RTB Date	16/7/2024
Client	PCSB	Location	ANGSI
Platform	ANGSI B	Well	B115
Assessed By	Name: ROSMAN BIN MAT DAN		Position: PUMPING SUPERVISOR

RATING LEGEND:


- STRONG** Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
- ADEQUATE** Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
- IMPROVEMENT NEEDED** Performance did not consistently meet expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
Safety Awareness (20%)									
a. Usage of Personal Protective Equipment	/								
b. Participation in UAUC		/							
c. Understanding of PTW System		/							
d. Worksite House Keeping			/						
Work Performance (20%)									
e. Initiative and Creativity			/						
f. Decision Making Capability			/						
g. Understanding of Job Scope			/						
h. Tools Inventory and Reporting			/						
i. Work Quality			/						
j. Reporting									
k. Punctuality and Time Keeping	/								
l. Teamwork	/								
m. Communication	/								
n. Leadership Skills			/						
o. Adaptability to Work Environment/Surrounding	/								
p. Attitude	/								
q. Discipline	/								

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

Able to operate BMY unit stand alone and without supervision.

Still learn about pump unit

Assessed By [Supervisor]	
Name	ROSMAN BIN MAT DAN
Date	15/7/24

Doc. Ref. No.: CTS-FORM-90

CONTROLLED COPY

Revision No.: 01

Effective Date: 21/08/2023

(Rev.00,Dated:22/09/19-OBSOLETE)

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																				
1. Pre-Job Preparation	1. Attend toolbox and morning meeting with WSS. 2. Pre-check/EMC1 all pumping equipment before run the job. 3. Prepare E-Ptw for each work to be performed.	Good.																				
											Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2												
2. Surface Equipment Rig-up	1. Prepare surface line up to water injection well. 2. Arrange pumping equipment at maindeck. 3. Prepare high pressure hose and treating iron for pumping activity. 4. Layout high pressure hose from maindeck to production deck. 5. Prepare treating iron to rig up form light weight pump.	Good.																				
											Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2												
3. Tools / Equipment Preparation	1. Prepare fitting connection. 2. Lay down spring hose and rigup to Single Pump and Lightweight pump. 3. Check all connection at pumping line to prevent from leaking during pumping operation.	Good.																				
											Rating (by Operator)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2												
4. Equipment	4.1 Batch Mixer 1. Check unit before start the batch mixer unit. 2. Operate Batch Mixer to mix SISQ treatment. 3. Check all the butterfly valve functioning well or not and open butterfly valve after mixing for start pumping on well.	Good.																				
											Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
											10	9	8	7	6	5	4	3	2			
Employee was able to OPERATE the equipment:					Under Supervision			<input type="checkbox"/>														
					Standalone			<input checked="" type="checkbox"/>														

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment									
	4.2 Pump Unit 1. Assist crew to rig up surface pumping line. 2. Assist pump operator to open up butterfly valve and plug valve during job. 3. Assit crew to function test on pumping unit.	Good Assit and still learning.									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:		Under Supervision			Standalone						
	4.3 Nitrogen Pump unit & Nitrogen Tank	—									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:		Under Supervision			Standalone						
	4.4 Power Pack	—									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:		Under Supervision			Standalone						
	4.5 Control Cabin	—									
Rating (by SUPERVISOR)		STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:		Under Supervision			Standalone						

Doc.Ref.No.: CTS-FORM-90

Revision No.: 01

Effective Date: 21/08/2023

(Rev.00,Dated:22/09/19-OBSOLETE)

CONTROLLED COPY

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																				
4.6 CT Reel																						
											Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
											10	9	8	7	6	5	4	3	2			
											Employee was able to OPERATE the equipment:						Under Supervision					
						Standalone																
4.7 Injector Head																						
											Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
											10	9	8	7	6	5	4	3	2			
											Employee was able to OPERATE the equipment:						Under Supervision					
						Standalone																
4.8 Pressure Control Equipment																						
											Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
											10	9	8	7	6	5	4	3	2			
											Employee was able to OPERATE the equipment:						Under Supervision					
						Standalone																
4.9 Basic BHA Components																						
											Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
											10	9	8	7	6	5	4	3	2			
											Employee was able to OPERATE the tools:						Under Supervision					
						Standalone																

Doc.Ref.No.: CTS-FORM-90

Revision No.: 01

Effective Date: 21/08/2023


(Rev.00,Dated:22/09/19-OBSOLETE)

CONTROLLED COPY

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3: To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback (Please indicate if employee is able to execute the job <u>UNDER SUPERVISION</u> or <u>STANDALONE</u>)
23/6/2024 to 16/7/2024	<p style="text-align: center;">ACID WASH & SISQ TREATMENT</p> <p>The objective of this job is to perform near wellbore acid wash of 135L via bullheading to tackle mainly on calcite scale issue. This treatment is including tubing pickling prior main treatment pumping (15%). After this job done, I've learn about pumping SISQ treatment and learn to operate batch mixer.</p>	<p>Able to operate BMX without supervision.</p> <p style="text-align: right;"> ROMAN MAT DATU</p>

Please tick (✓) category of services performed:

Standard Services:

- Wellbore Cleanout
- CT Cementing
- Nitrogen Operations
- Pumping Services

Advanced Services

- CT Fishing
- CT Milling
- CT Logging
- CT Perforation