

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK (PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment									
1. Pre-Job Preparation	A) PERFORM PRE CHECKLIST ON ALL EQUIPMENT B) TO CHECK ALL HOSES WAS TIGHT AND SECURE C) ENSURE ALL TOOLS BEING PREPARED PRIOR TO JOB BEING PERFORM D) ENSURE ALL PRESSURE HOSE FROM PP TO RSU BEING SECURE WITH WEB CHECK E) BARRICADE WORKSITE & WELLHEAD AREA BEFORE PERFORME RIGGING UP F) CHECK WELL CONDITION TO KNOW IF THERES POTENTIAL PASSING ON VALVE G) WALK THE LINE BEFORE START RIGGING UP AND IDENTIFY ANY HAZARD H) TOOLBOX MEETING BEFORE PROCEED TO JOB										
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
2. Surface Equipment Rig-up	A) MAKE UP PCE B) PUT GREASE ON ALL LUB CONNECTION BEFORE CONNECTING IT C) CHECK O-RING BEFORE MAKE UP THE LUBRICATOR D) DISCARD WIRE IF NEEDED E) CHECK ANY DAMAGE ON ALL LUB THREAD F) HOOK UP ALL HOSES & CHECK ALL HOSES FOR ANY DAMAGE BEFORE USE G) CHECK ALL PCE EQUIPMENT VALIDITY BEFORE USE H) MAKE UP ROPE SOCKET I) ENSURE ALL SHACKLE SECURE WITH SAFETY SLING										
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
3. Tools / Equipment Preparation	A) SERVICE & FUNCTION TEST TOOL BEFORE USING IT B) PINNING QXE RUNNING TOOLS C) CHECK ANY THREAD DAMAGE ON TOOLS BEFORE/AFTER USE D) FILE ANY TOOLS THAT HAVE SHARP EDGES TO PREVENT FROM BEING CUT E) CLEAN ANY TOOL THAT IS STUCK DUE TO WAX F) INVENTORY TOOLS IF NECESSARY										
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>	N/A										
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	
5. Downhole Tools Servicing/Redressing/Maintenance	A) SERVICE DHT & FUNCTION TEST B) PINNING & FUNCTION TEST DHT C) MAKE UP TOOLSTRING D) PRPEARE AND CHANGE DAMAGE SPARE PART ON DAMAGE DHT E) CHECK ANY FAULTY ON DHT THAT BEING USED F) ENSURE ALL SHARP EDGES BEING FILE TO PREVENT FROM HAND CUT G) ENSURE ALL THREADED TOOLS BEING SECURE TIGHTLY										
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
		10	9	8	7	6	5	4	3	2	

Type of Task	Tasks Performed	Assessor Comment								
6. Tools Inventory & Reporting	A) PRECHECK INVENTORY DOWNHOLE TOOLS EVERY 2 WEEK. B) UPDATE INVENTORY DOWNHOLE TOOL CHECKLIST BORROW AND LEND C) UPDATE AND REPORTING MISSING DOWNHOLE TOOLS.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
7. Equipment Operation	[Operator to rate TSA / SA / SSA competency in operating the equipment]									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Power Pack			✓						
	Air Compressor									
	GenSet									
	Control Panel				✓					
	Test Pump				✓					
	Pressure Control Equipment			✓						
	Mast				✓					
Weight & Measuring Devices					✓					
Downhole Tools				✓						
Total										
Comments by Operator [please specify competency gaps / area of improvement]										
EXECUTE THE WELL SERVICES OPERATION (IF ANY) (Operating Winch)										
Date / Location / Well No. / Job Type	Activity Summary	Toolstring Configuration								
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
Comments by Operator [please specify competency gaps / area of improvement]										

Type of Task		Tasks Performed	Assessor Comment
JOB DETAIL:			
DATE	WELL NO.	JOB TYPE	STATUS (COMPLETE / INCOMPLETE)
12-Feb-24	BT-101S	TCC, WAX CUT, SGS, FGS	COMPLETE
19-Feb-24	SJ-101L	TCC, WAX CUT	COMPLETE
22-Feb-24	SJ-105C	TCC, WAX CUT	COMPLETE
25-Feb-24	SJ-105B	TCC, WAX CUT	INCOMPLETE
26-Feb-24	SJ-105A		