

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	WAN MUHAMMAD HANIT BIN WAN MUEHAMMAD	COB Date	18/4/2022
Position	EQUIPMENT OPERATOR TRAINEE	RTB Date	8/10/2022.
Client	PETRONAS CARIGALI	Location	BEKOK
Platform	BEKOK AB	Well	A-07
Assessed By	Name: ENGGU NAZRI	Position:	GENERAL EQUIPMENT OPERATOR

**RATING LEGEND:**

**STRONG** Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

**ADEQUATE** Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good

**IMPROVEMENT NEEDED** Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please √ where appropriate)								
	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2

**Safety Awareness (20%)**

- a. Usage of Personal Protective Equipment
- b. Participation in UAUC
- c. Understanding of PTW System
- d. Worksite House Keeping

✓									
	✓								
✓									
			✓						

**Work Performance (20%)**

- e. Initiative and Creativity
- f. Decision Making Capability
- g. Understanding of Job Scope
- h. Tools Inventory and Reporting
- i. Work Quality
- j. Reporting
- k. Punctuality and Time Keeping
- l. Teamwork
- m. Communication
- n. Leadership Skills
- o. Adaptability to Work Environment/Surrounding
- p. Attitude
- q. Discipline

			✓						
				✓					
			✓						
			✓						
	✓								
	✓								
	✓								
					✓				
					✓				
			✓						
	✓								

**REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:**

- Can Stand Alone operate the Batch Mixer.

- Overall good -

Assessed By [Supervisor]	Enngu Nazri & Enngu Jaili'
Name	<i>[Signature]</i>
Date	7/10/2022

**DIMENSION BID**

**COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK**  
 PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
1. Pre-Job Preparation	1. Attend Meeting With WIS. 2. Prepare EPTW Before Do The Job.	-done																		
	Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
2. Surface Equipment Rig-up	1. Assist Crew Rig Up Surface Line From SPO3 TO wellbore By Tee Slickline (Crowell).	-done																		
	Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
3. Tools / Equipment Preparation	1. Connect Air Hose From Air Supply Platform To Equipment. 2. Top up Diesel On Equipment Before Do The Job.	-done																		
	Rating (by Operator) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
4. Equipment	4.1 Batch Mixer 1. Assist Crew Rig up 4" Hose to SPO3 And From FST. 2. Assist BMX operator Mixing 15% HCL And Neutralization Fluid (Soda Ash). 3. Do/Learn EMC 1 BMX.	-done																		
	Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
	Employee was able to OPERATE the equipment: <table border="1"> <tr> <td>Under Supervision</td> <td><input type="checkbox"/></td> </tr> <tr> <td>Standalone</td> <td><input type="checkbox"/></td> </tr> </table>	Under Supervision	<input type="checkbox"/>	Standalone	<input type="checkbox"/>															
Under Supervision	<input type="checkbox"/>																			
Standalone	<input type="checkbox"/>																			

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																				
4.2 Pump Unit	1. Assist Pump Operator Rig up Pumping Line. 2. Assist <del>Operator</del> Pump Operator Open/Close Bleed Out Valve.	done.																				
			Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
			STRONG			ADEQUATE			IMPROVEMENT NEEDED													
			10	9	8	7	6	5	4	3	2											
Employee was able to OPERATE the equipment:	<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone																		
Under Supervision																						
Standalone																						
4.3 Nitrogen Pump unit & Nitrogen Tank																						
			Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
			STRONG			ADEQUATE			IMPROVEMENT NEEDED													
			10	9	8	7	6	5	4	3	2											
Employee was able to OPERATE the equipment:	<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone																		
Under Supervision																						
Standalone																						
4.4 Power Pack																						
			Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
			STRONG			ADEQUATE			IMPROVEMENT NEEDED													
			10	9	8	7	6	5	4	3	2											
Employee was able to OPERATE the equipment:	<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone																		
Under Supervision																						
Standalone																						
4.5 Control Cabin																						
			Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
			STRONG			ADEQUATE			IMPROVEMENT NEEDED													
			10	9	8	7	6	5	4	3	2											
Employee was able to OPERATE the equipment:	<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone																		
Under Supervision																						
Standalone																						

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																					
	4.6 CT Reel																						
												Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
												10	9	8	7	6	5	4	3	2			
												Employee was able to OPERATE the equipment:						Under Supervision					
						Standalone																	
	4.7 Injector Head																						
												Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
												10	9	8	7	6	5	4	3	2			
												Employee was able to OPERATE the equipment:						Under Supervision					
						Standalone																	
	4.8 Pressure Control Equipment																						
												Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
												10	9	8	7	6	5	4	3	2			
												Employee was able to OPERATE the equipment:						Under Supervision					
						Standalone																	
	4.9 Basic BHA Components																						
												Rating (by SUPERVISOR)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
												10	9	8	7	6	5	4	3	2			
												Employee was able to OPERATE the tools:						Under Supervision					
						Standalone																	

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																											
5. Job Supervision (if applicable) <i>Please complete this section if you perform any supervisory role during operation</i>																													
<b>Rating (by SUPERVISOR)</b>																													
		<table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2									
STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
10	9	8	7	6	5	4	3	2																					
Please ✓ accordingly to confirm the role of the employee during operation		<table border="1"> <tr> <td>Full Supervisor</td> <td></td> </tr> <tr> <td>2nd / Night Supervisor</td> <td></td> </tr> </table>	Full Supervisor		2nd / Night Supervisor																								
Full Supervisor																													
2nd / Night Supervisor																													

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3: To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback <small>(Please indicate if employee is able to execute the job <u>UNDER SUPERVISION</u> or <u>STANDALONE</u>)</small>
18 Sept 2022.	Perform Pumping Activity On Well A07. ( Assist Geowell ) .	
8 Oct 2022	<p>- Mobilized From POST By FCB 18 September 2022 To Location Bekok AB . After Arrive , Start Lifting Equipment From Vessel To Main Deck Platform And SPOT Equipment For The Job .</p> <p>- Assist Crew To Rig Up Surface Line Equipment , Assist Crew Mixing 15% HCL And Neutralization Fluid ( soda ash ) . I Have Learned How To Operate Bux And Single Pump . I Assigned As A Helper And Support The Crew Run The Job Smoothly And Succeeded Without Any Problem . After Job Done , Back to POST 8 October 2022 .</p>	<p>- Good Job !</p> <p>- Successfully done Acid Stimulation for well A-07 .</p>

Please tick (✓) category of services performed:

<b>Standard Services:</b>	Wellbore Cleanout <input type="checkbox"/>	<b>Advanced Services</b>	CT Fishing <input type="checkbox"/>
	CT Cementing <input type="checkbox"/>		CT Milling <input type="checkbox"/>
	Nitrogen Operations <input type="checkbox"/>		CT Logging <input type="checkbox"/>
	Pumping Services <input checked="" type="checkbox"/>		CT Perforation <input type="checkbox"/>