

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment
	4.4 CP A)HOOK UP HOSES B)OPERATE THE CP C)FUNCTION TEST CP (PUMP) D)CHECK CP HOSES IF ANY DAMAGE E)TOP UP HYDRALIC IF NEEDED F)CHECK HOSES CONNECTION IF THERE ANY LEAK	
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input checked="" type="checkbox"/> Detail	
	4.5 TP A)HOOK UP THE HOSES B)OPERATE THE TEST PUMP C)FUNCTION TEST D)CHECK HOSES IF ANY DAMAGE E)CHECK TP HOSES IF THERE ANY LEAK DURING PRESSURE UP	
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input checked="" type="checkbox"/> Broad <input type="checkbox"/> Detail	
	4.6 PCE A)PERFORM HYDROTEST B)IDENTIFY TYPE OF CONNECTION & MAKE UP C)PUT GREASE ON ALL THREAD LUBRICATOR D)CHECK O-RING CONDITION E)OPERATE & FUNCTION TEST THE BOP F)MAKE SURE ALL PCE IS VALID G)FUNCTION TEST ALL PCE (BOP,QTS,BALL VALVE) IS IN GOOD CONDITION H)CHANGE SBX PACKING	
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input checked="" type="checkbox"/> Broad <input type="checkbox"/> Detail	
	4.7 Mast NIL	
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	4.8 WEIGHT & MEASURING DEVICES A)FLUSH HOSE AND PUMP W15 FLUID B)CHECK ODOMETER CONDITION C)SERVICE BEARING AT PRESSURE WHEEL, MEASURE WHEEL & TRAVERSE ASSEMBLY D)SPRAY ODOMETER CABLE WITH WD40 TO PREVENT FROM CORRISION	
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input checked="" type="checkbox"/> Broad <input type="checkbox"/> Detail	
	4.9 Downhole Tools A)SERVICE DHT B)PINNING & FUNCTION TEST DHT C)MAKE UP TOOLSTRING D)PERFORM PM ON DHT INSIDE TOOLBOX E)PREPARE AND CHANGE DAMAGE SPARE PART ON DAMAGE DHT F)CHECK ANY FAULTY ON DHT THAT BEING USED G)ENSURE ALL SHARP EDGES BEING FILE TO PREVENT FROM HAND CUT H)ENSURE ALL THREADED TOOLS BEING SECURE TIGHTLY	
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input checked="" type="checkbox"/> Broad <input type="checkbox"/> Detail	

JOB DETAIL:

DATE	WELL NO.	JOB TYPE	STATUS (COMPLETE / INCOMPLETE)
10/1/2023	SJ604S	Tubing casing communication investigation & GLVC	COMPLETED (27/1/2023)
27/1/2023		pack Equipment and standby lifting to SJT-H	INCOMPLETE (DUE TO BAD WEATHER) 30/1/2023