

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	ZAINUDDIN YAACOB	COB Date	7-10-23
Position	GEO	RTB Date	11-10-23
Client	PCSB	Location	DULANG C
Platform	DULANG C	Well	C045
Assessed By	Name: JOHARI JOHOR	Position:	CTS SUPV

RATING LEGEND:

STRONG Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

ADEQUATE Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good

IMPROVEMENT NEEDED Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
---------------------	-------------------------------------	--	--	--	--	--	--	--	--

Safety Awareness (20%)

- a. Usage of Personal Protective Equipment
- b. Participation in UAUC
- c. Understanding of PTW System
- d. Worksite House Keeping

	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
a.	✓								
b.		✓							
c.		✓							
d.		✓							


Work Performance (20%)

- e. Initiative and Creativity
- f. Decision Making Capability
- g. Understanding of Job Scope
- h. Tools Inventory and Reporting
- i. Work Quality
- j. Reporting
- k. Punctuality and Time Keeping
- l. Teamwork
- m. Communication
- n. Leadership Skills
- o. Adaptability to Work Environment/Surrounding
- p. Attitude
- q. Discipline

e.	✓								
f.	✓								
g.	✓								
h.	✓								
i.	✓								
j.	✓								
k.	✓								
l.	✓								
m.	✓								
n.	✓								
o.	✓								
p.	✓								
q.	✓								

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

perform task and follow job with successful.

Assessed By [Supervisor]	
Name	JOHARI JOHOR
Date	20-10-23

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment									
1. Pre-Job Preparation	<ul style="list-style-type: none"> - Attend morning and toolbox meeting - Attend pre job meeting - pre check / EMC 1 all CTU equipment prior CTU run 	- done									
		10	9	8	7	6	5	4	3	2	
2. Surface Equipment Rig-up	<ul style="list-style-type: none"> - Rig up surface line - Rig up 4" hose - Rig up water injection - Spot and arrange stand light, Tool Container, CC electric cable to junction box 	- done									
		10	9	8	7	6	5	4	3	2	
3. Tools / Equipment Preparation	<ul style="list-style-type: none"> - Perform EMC1 on CC, stripper, Bop's, CT Reel, injector, Jackup Frame and power pack for pre job - prepare downhole tools to be use during job 	- done									
		10	9	8	7	6	5	4	3	2	
4. Equipment	4.1 Batch Mixer <ul style="list-style-type: none"> - Clean batch mixer after completing job 	- done									
		10	9	8	7	6	5	4	3	2	
Employee was able to OPERATE the equipment:		Under Supervision									
		Standalone									

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
	4.2 Pump Unit - Redress pump after completed cement job	- done																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>(10)</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			(10)	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
(10)	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td>/</td> </tr> </table>	Under Supervision		Standalone	/														
Under Supervision																				
Standalone	/																			
	4.3 Nitrogen Pump unit & Nitrogen Tank - No unit standby if required to pump after cement completed	- done																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>(10)</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			(10)	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
(10)	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td>/</td> </tr> </table>	Under Supervision		Standalone	/														
Under Supervision																				
Standalone	/																			
	4.4 Power Pack - perform EMC I	- done																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>(10)</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			(10)	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
(10)	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td>/</td> </tr> </table>	Under Supervision		Standalone	/														
Under Supervision																				
Standalone	/																			
	4.5 Control Cabin - set up job file - perform EMC I - update job ticket - update chemical tracking	- done																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>(10)</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			(10)	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
(10)	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td>/</td> </tr> </table>	Under Supervision		Standalone	/														
Under Supervision																				
Standalone	/																			

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment
	4.6 CT Reel - Perform EMC 1	- done
Rating (by SUPERVISOR)	STRONG 10 9 8	ADEQUATE IMPROVEMENT NEEDED 7 6 5 4 3 2
Employee was able to OPERATE the equipment:		Under Supervision <input type="checkbox"/> Standalone <input checked="" type="checkbox"/>
	4.7 Injector Head - Top up injector lube oil - Top up gear oil - Perform EMC 1	- done
Rating (by SUPERVISOR)	STRONG 10 9 8	ADEQUATE IMPROVEMENT NEEDED 7 6 5 4 3 2
Employee was able to OPERATE the equipment:		Under Supervision <input type="checkbox"/> Standalone <input checked="" type="checkbox"/>
	4.8 Pressure Control Equipment - Function test single and combi BOP - Function test stripper - Redress BOPs after completed Cement job - Fill up EMC 1 form	- done
Rating (by SUPERVISOR)	STRONG 10 9 8	ADEQUATE IMPROVEMENT NEEDED 7 6 5 4 3 2
Employee was able to OPERATE the equipment:		Under Supervision <input type="checkbox"/> Standalone <input checked="" type="checkbox"/>
	4.9 Basic BHA Components - prepare and make up BHA for cementing - Redress after completing job	- done
Rating (by SUPERVISOR)	STRONG 10 9 8	ADEQUATE IMPROVEMENT NEEDED 7 6 5 4 3 2
Employee was able to OPERATE the tools:		Under Supervision <input type="checkbox"/> Standalone <input checked="" type="checkbox"/>

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																											
5. Job Supervision (if applicable) Please complete this section if you perform any supervisory role during operation		- Compliant job safety.																											
	Rating (by SUPERVISOR)	<table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td></td> <td style="text-align: center;">9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2		9							
	STRONG			ADEQUATE			IMPROVEMENT NEEDED																						
	10	9	8	7	6	5	4	3	2																				
	9																												
Please <input checked="" type="checkbox"/> accordingly to confirm the role of the employee during operation	<table border="1"> <tr> <td>Full Supervisor</td> <td style="text-align: center;">/</td> </tr> <tr> <td>2nd / Night Supervisor</td> <td></td> </tr> </table>	Full Supervisor	/	2nd / Night Supervisor																									
Full Supervisor	/																												
2nd / Night Supervisor																													

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3: To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback (Please indicate if employee is able to execute the job <u>UNDER SUPERVISION</u> or <u>STANDALONE</u>)
7/10/23	<p>I was assign as CT operator for cement job.</p> <p>Job completely successful</p>	<p>- Job Complete safely and follow procedure from job program</p>

Please tick (✓) category of services performed:

Standard Services:

- Wellbore Cleanout
- CT Cementing
- Nitrogen Operations
- Pumping Services

Advanced Services

- CT Fishing
- CT Milling
- CT Logging
- CT Perforation