

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor (WEIGHT: 40%)

Name	AHMAD SHAZMEER BIN MOHAMAD	COB Date	19.03.2023
Position	EQUIPMENT OPERATOR TRAINEE	RTB Date	06.4.2023
Client	PCSB	Location	ANDR-A
Platform	ANGSI	Well	A-12s
Assessed By	Name: ROSMAN	Position:	PUMPING SUPERVISOR

RATING LEGEND:

STRONG Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

ADEQUATE Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good

IMPROVEMENT NEEDED Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
Safety Awareness (20%)									
a. Usage of Personal Protective Equipment		/							
b. Participation in UAUC	/								
c. Understanding of PTW System	/								
d. Worksite House Keeping		/							
Work Performance (20%)									
e. Initiative and Creativity		/							
f. Decision Making Capability		/							
g. Understanding of Job Scope		/							
h. Tools Inventory and Reporting	/								
i. Work Quality		/							
j. Reporting		/							
k. Punctuality and Time Keeping		/							
l. Teamwork	/								
m. Communication	/								
n. Leadership Skills		/							
o. Adaptability to Work Environment/Surrounding		/							
p. Attitude		/							
q. Discipline		/							

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

- Personal able to operate Bmx independently and manage his work tasks effectively and delivers the results on time.

- He consistently deliver high quality work in safety manner which contributor to our job success.

Assessed By [Supervisor]	<i>[Signature]</i>
Name	ROSMAN BIN MAT DAN
Date	10 JANUARY 2025

Doc Ref.No : CTS-FORM-90
 Revision No : 01
 Effective Date : 21/08/2023
 (Rev.00, Dated: 22/09/19-OBSOLETE)

CONTROLLED COPY

Scanned with CamScanner

Scanned with CamScanner

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																	
1. Pre-Job Preparation	1) Prepare the document and submit permit to OIM. 2) Attend toolbox meeting with wireline supervisor. 3) Safety talk by safety officer before start job.	- Good understanding on job preparation																	
	Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3
STRONG			ADEQUATE			IMPROVEMENT NEEDED													
10	9	8	7	6	5	4	3	2											
2. Surface Equipment Rig-up	1) Assist crew to spot equipment from vessel to platform using heavy lifting. 2) Assist crew to rig up surface line and 4" hose from BMX to single pump. 3) Rig up wilden pump and spring hose from seadeck to maindeck.	- Able to rig-up surface equipment on safety and follow SOP.																	
	Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3
STRONG			ADEQUATE			IMPROVEMENT NEEDED													
10	9	8	7	6	5	4	3	2											
3. Tools / Equipment Preparation		- Good teamwork and housekeeping																	
	Rating (by Operator)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3
STRONG			ADEQUATE			IMPROVEMENT NEEDED													
10	9	8	7	6	5	4	3	2											
4. Equipment	4.1 Batch Mixer	- Able to operate without supervision																	
	1) Rig up hydraulic hose from BMX Power Pack to BMX Tank. 2) Rig up 4" hose for overboard. 3) Function test for BMX 01 agitator and C-pump working properly.																		
	Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3
STRONG			ADEQUATE			IMPROVEMENT NEEDED													
10	9	8	7	6	5	4	3	2											
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone														
Under Supervision																			
Standalone																			

Doc. Ref. No.: CTS-FORM-90
Revision No.: 01
Effective Date: 21/08/2023
(Rev.00, Dated: 22/09/19-OBSOLETE)

CONTROLLED COPY

2

Scanned with CamScanner

Scanned with CamScanner

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK
 PART 2 - To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
	4.2 Pump Unit 1) Rig up treating iron from SinglePump to bleed off and to CT Reel. 2) Assist Supervisor to connect fluidwell cable from pump to cabin for data reading and record. 3) Under supervisor to stand alone operator pump for CT Operation.	- Able to operate pump but need more training and guidance from senior																		
Rating (by SUPERVISOR)		<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Stand-alone</td> <td></td> </tr> </table>	Under Supervision		Stand-alone															
Under Supervision																				
Stand-alone																				
	4.3 Nitrogen Pump unit & Nitrogen Tank 1) Assist crew to rig up treating iron to CT Reel and include bleed off line.																			
Rating (by SUPERVISOR)		<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Stand-alone</td> <td></td> </tr> </table>	Under Supervision		Stand-alone															
Under Supervision																				
Stand-alone																				
	4.4 Power Pack																			
Rating (by SUPERVISOR)		<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Stand-alone</td> <td></td> </tr> </table>	Under Supervision		Stand-alone															
Under Supervision																				
Stand-alone																				
	4.5 Control Cabin 1) Assist crew to rig up hydraulic hose and connected to CT Reel, Injector Head and BOP.																			
Rating (by SUPERVISOR)		<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Stand-alone</td> <td></td> </tr> </table>	Under Supervision		Stand-alone															
Under Supervision																				
Stand-alone																				

Doc Ref No.: CTS-FORM-90
 Revision No.: 01
 Effective Date: 21/08/2023
 (Rev 00, Dated: 22/09/19-OBSOLETE)

CONTROLLED COPY

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
4.6 CT Reel	1) Assist crew install CT Drum into GIDF. 2) Assist crew to connect all hydraulic hose from control cabin.																			
	Rating (by SUPERVISOR)	<table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th><th>9</th><th>8</th> <th>7</th><th>6</th><th>5</th> <th>4</th><th>3</th><th>2</th> </tr> </thead> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
	STRONG			ADEQUATE			IMPROVEMENT NEEDED													
	10	9	8	7	6	5	4	3	2											
Employee was able to OPERATE the equipment:	<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone																
Under Supervision																				
Standalone																				
4.7 Injector Head																				
	Rating (by SUPERVISOR)	<table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th><th>9</th><th>8</th> <th>7</th><th>6</th><th>5</th> <th>4</th><th>3</th><th>2</th> </tr> </thead> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
	STRONG			ADEQUATE			IMPROVEMENT NEEDED													
	10	9	8	7	6	5	4	3	2											
Employee was able to OPERATE the equipment:	<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone																
Under Supervision																				
Standalone																				
4.8 Pressure Control Equipment	1) Assist crew function test BOP, Combi BOP and Stripper. 2) Assist crew rig up combi BOP and Riser (Wellhead Stackup)																			
	Rating (by SUPERVISOR)	<table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th><th>9</th><th>8</th> <th>7</th><th>6</th><th>5</th> <th>4</th><th>3</th><th>2</th> </tr> </thead> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
	STRONG			ADEQUATE			IMPROVEMENT NEEDED													
	10	9	8	7	6	5	4	3	2											
Employee was able to OPERATE the equipment:	<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone																
Under Supervision																				
Standalone																				
4.9 Basic BHA Components	1) Assist crew make up connector and BHA. 2) Assist crew pull test and pressure test CT connector.																			
	Rating (by SUPERVISOR)	<table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th><th>9</th><th>8</th> <th>7</th><th>6</th><th>5</th> <th>4</th><th>3</th><th>2</th> </tr> </thead> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
	STRONG			ADEQUATE			IMPROVEMENT NEEDED													
	10	9	8	7	6	5	4	3	2											
Employee was able to OPERATE the tool:	<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone																
Under Supervision																				
Standalone																				

Doc Ref No : CTS-FORM-90
 Revision No.: 01
 Effective Date: 21/08/2023
 (Rev.00,Dated.22/09/19-OBSOLETE)

CONTROLLED COPY

Scanned with CamScanner

Scanned with CamScanner

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor (WEIGHT: 60%)

Type of Task	Tasks Performed	Assessor Comment																		
5. Job Supervision (if applicable) Please complete this section if you perform any supervisory role during operation																				
	Rating (by SUPERVISOR)	<table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2
	STRONG			ADEQUATE			IMPROVEMENT NEEDED													
	10	9	8	7	6	5	4	3	2											
Please <input checked="" type="checkbox"/> accordingly to confirm the role of the employee during operation	<table border="1"> <tr> <td>Full Supervisor</td> <td></td> </tr> <tr> <td>2nd / Night Supervisor</td> <td></td> </tr> </table>	Full Supervisor		2nd / Night Supervisor																
Full Supervisor																				
2nd / Night Supervisor																				

Doc Ref No.: CTS FORM-90
 Revision No.: 01
 Effective Date: 21/08/2023
 (Rev.00, Dated: 22/09/19-OBSOLETE)

CONTROLLED COPY

5

Scanned with CamScanner

Scanned with CamScanner

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3 To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback <small>(Please indicate if employee is able to execute the job UNDER SUPERVISION or STANDALONE)</small>
19 MAR 2023 to 06 APR 2023	<ul style="list-style-type: none"> - Well Diagnosis with camera run (well A-12s) - Mob to angsi platform , Assist crew to rig up surface line on maindeck - Platform Heavy Lifting activities CTU equipment on maindeck and spot/arrange unit. - Operate BMX under supervision for SCO job until complete. 	

Please tick (✓) category of services performed:

Standard Services: Wellbore Cleanout <input type="checkbox"/> CT Cementing <input type="checkbox"/> Nitrogen Operations <input type="checkbox"/> Pumping Services <input checked="" type="checkbox"/>	Advanced Services CT Fishing <input type="checkbox"/> CT Milling <input type="checkbox"/> CT Logging <input type="checkbox"/> CT Perforation <input type="checkbox"/>
--	--

Doc Ref No : CTS-FORM-90
 Revision No.: 01
 Effective Date: 21/08/2023
 (Rev.00,Dated.22/09/19-OBSOLETE)

CONTROLLED COPY