

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	AHMAD SHAZMEER BIN MOHAMAD	COB Date	18.5.2023
Position	EQUIPMENT OPERATOR TRAINEE	RTB Date	10.6.2023
Client	PCSB	Location	ANGSI
Platform	ANDR-A	Well	A-125
Assessed By	Name: MUHAMMAD TAUFIQ BIN ISMAIL Position: COILED TUBING SUPERVISOR		

### RATING LEGEND:

STRONG	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
ADEQUATE	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
IMPROVEMENT NEEDED	Performance did not consistently meet expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
Safety Awareness (20%)	10	9	8	7	6	5	4	3	2
a. Usage of Personal Protective Equipment	/								
b. Participation in UAUC	/								
c. Understanding of PTW System	/								
d. Worksite House Keeping		/							
<u>Work Performance (20%)</u>									
e. Initiative and Creativity			/						
f. Decision Making Capability				/					
g. Understanding of Job Scope					/				
h. Tools Inventory and Reporting						/			
i. Work Quality							/		
j. Reporting								/	
k. Punctuality and Time Keeping									/
l. Teamwork									/
m. Communication									/
n. Leadership Skills									/
o. Adaptability to Work Environment/Surrounding									/
p. Attitude									/
q. Discipline									/

### REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

Assign as BMRX trainee and fit in applicant during working period.

Consistently demonstrates good team work, fast learner and continuous learning at work location.

Assessed By [Supervisor]	
Name:	TAUFIQ ISMAIL
Date:	1/6/2023

Doc Ref.No : CTS-FORM-90

Revision No.: 01

Effective Date 21/08/2023

(Rev.00,Dated:22/09/19-OBsolete)

CONTROLLED COPY

Scanned with CamScanner

Scanned with CamScanner

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2 To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																						
1. Pre-Job Preparation	1) Attend toolbox and morning meeting with CSR. 2) Assisted crew in lifting all CTU equipment and spot unit. 3) Pre-check/EMC1 all CTU equipment before run the job. 4) Prepare E-Ptw for each work to be performed.	Good job																						
		Rating (by SUPERVISOR) <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">STRONG</td> <td style="width: 15%;">10</td> <td style="width: 15%;">9</td> <td style="width: 15%;">8</td> <td style="width: 15%;">7</td> <td style="width: 15%;">6</td> <td style="width: 15%;">5</td> <td style="width: 15%;">4</td> <td style="width: 15%;">3</td> <td style="width: 15%;">2</td> </tr> </table>	STRONG	10	9	8	7	6	5	4	3	2	ADEQUATE <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">7</td> <td style="width: 15%;">6</td> <td style="width: 15%;">5</td> <td style="width: 15%;">4</td> <td style="width: 15%;">3</td> <td style="width: 15%;">2</td> </tr> </table>	7	6	5	4	3	2	IMPROVEMENT NEEDED <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">1</td> <td style="width: 15%;">2</td> <td style="width: 15%;">3</td> <td style="width: 15%;">4</td> <td style="width: 15%;">5</td> <td style="width: 15%;">6</td> </tr> </table>	1	2	3	4
STRONG	10	9	8	7	6	5	4	3	2															
7	6	5	4	3	2																			
1	2	3	4	5	6																			
2. Surface Equipment Rig-up	1) Assist crew to rig up pumping surface line from SP01 to coil reel and kill port to combi BOP. 2) Assist crew to rig up N2 line from NCV to CT Reel. 3) Rig up 4" hose from fluid storage tank to SP01. 4) Rig up 4" hose from BMX Tank to SP01. 5) Spot/arrange flood light, control cabin and tool container electric cable to junction box. 6) Rig up water injection line from well A-27s to fluid storage tank. 7) Rig up wilden pump, 2" spring hose and air hose from sea deck to main deck.	Good Ass't																						
		Rating (by SUPERVISOR) <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">STRONG</td> <td style="width: 15%;">10</td> <td style="width: 15%;">9</td> <td style="width: 15%;">8</td> <td style="width: 15%;">7</td> <td style="width: 15%;">6</td> <td style="width: 15%;">5</td> <td style="width: 15%;">4</td> <td style="width: 15%;">3</td> <td style="width: 15%;">2</td> </tr> </table>	STRONG	10	9	8	7	6	5	4	3	2	ADEQUATE <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">1</td> <td style="width: 15%;">2</td> <td style="width: 15%;">3</td> <td style="width: 15%;">4</td> <td style="width: 15%;">5</td> <td style="width: 15%;">6</td> </tr> </table>	1	2	3	4	5	6	IMPROVEMENT NEEDED <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">1</td> <td style="width: 15%;">2</td> <td style="width: 15%;">3</td> <td style="width: 15%;">4</td> <td style="width: 15%;">5</td> <td style="width: 15%;">6</td> </tr> </table>	1	2	3	4
STRONG	10	9	8	7	6	5	4	3	2															
1	2	3	4	5	6																			
1	2	3	4	5	6																			
3. Tools / Equipment Preparation	1) Installing air hose from compressor to SP02 and wilden pump. 2) Perform EMC1 on Air Compressor and Genset for pre job. 3) Fuel up all CTU equipment.	Good job																						
		Rating (by Operator) <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">STRONG</td> <td style="width: 15%;">10</td> <td style="width: 15%;">9</td> <td style="width: 15%;">8</td> <td style="width: 15%;">7</td> <td style="width: 15%;">6</td> <td style="width: 15%;">5</td> <td style="width: 15%;">4</td> <td style="width: 15%;">3</td> <td style="width: 15%;">2</td> </tr> </table>	STRONG	10	9	8	7	6	5	4	3	2	ADEQUATE <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">1</td> <td style="width: 15%;">2</td> <td style="width: 15%;">3</td> <td style="width: 15%;">4</td> <td style="width: 15%;">5</td> <td style="width: 15%;">6</td> </tr> </table>	1	2	3	4	5	6	IMPROVEMENT NEEDED <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">1</td> <td style="width: 15%;">2</td> <td style="width: 15%;">3</td> <td style="width: 15%;">4</td> <td style="width: 15%;">5</td> <td style="width: 15%;">6</td> </tr> </table>	1	2	3	4
STRONG	10	9	8	7	6	5	4	3	2															
1	2	3	4	5	6																			
1	2	3	4	5	6																			
4. Equipment	4.1 Batch Mixer 1) Assist Batch Mixer Operator to troubleshoot C-pump malfunction. Found piece of metal stuck at impeller during troubleshoot. 2) Assist Batch Mixer Operator to mix FRS. 3) Assist to mix TIW.	Good Ass't																						
		Rating (by SUPERVISOR) <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">STRONG</td> <td style="width: 15%;">10</td> <td style="width: 15%;">9</td> <td style="width: 15%;">8</td> <td style="width: 15%;">7</td> <td style="width: 15%;">6</td> <td style="width: 15%;">5</td> <td style="width: 15%;">4</td> <td style="width: 15%;">3</td> <td style="width: 15%;">2</td> </tr> </table>	STRONG	10	9	8	7	6	5	4	3	2	ADEQUATE <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">1</td> <td style="width: 15%;">2</td> <td style="width: 15%;">3</td> <td style="width: 15%;">4</td> <td style="width: 15%;">5</td> <td style="width: 15%;">6</td> </tr> </table>	1	2	3	4	5	6	IMPROVEMENT NEEDED <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 15%;">1</td> <td style="width: 15%;">2</td> <td style="width: 15%;">3</td> <td style="width: 15%;">4</td> <td style="width: 15%;">5</td> <td style="width: 15%;">6</td> </tr> </table>	1	2	3	4
STRONG	10	9	8	7	6	5	4	3	2															
1	2	3	4	5	6																			
1	2	3	4	5	6																			
	Employee was able to OPERATE the equipment: <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="width: 50%;">Under Supervision</td> <td style="width: 50%;">Standalone</td> </tr> </table>	Under Supervision	Standalone																					
Under Supervision	Standalone																							

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment		
<b>4.2 Pump Unit</b> 1) Assist crew to rig up surface pumping line	Good & Assist			
	Rating (by SUPERVISOR)	STRONG 10 9 8 7 6 5 4 3 2	ADEQUATE Under Supervision	IMPROVEMENT NEEDED Standalone
	Employee was able to OPERATE the equipment:			
	Good & Assist			
<b>4.3 Nitrogen Pump unit &amp; Nitrogen Tank</b> 1) Assist crew to rig up 2" HP Treating line to CT Reel and include bleed off line. 2) Assist crew to rig up cryogenic hose from N2 tank to inlet and outlet line on NCV.	Good & Assist			
	Rating (by SUPERVISOR)	STRONG 10 9 8 7 6 5 4 3 2	ADEQUATE Under Supervision	IMPROVEMENT NEEDED Standalone
	Employee was able to OPERATE the equipment:			
	Good & Assist			
<b>4.4 Power Pack</b> 1) Assist to rig up hydraulic power hose to injector head. 2) Assist to rig up hose from CTU Power Pack to Control Cabin.	Good & Assist			
	Rating (by SUPERVISOR)	STRONG 10 9 8 7 6 5 4 3 2	ADEQUATE Under Supervision	IMPROVEMENT NEEDED Standalone
	Employee was able to OPERATE the equipment:			
	Good & Assist			
<b>4.5 Control Cabin</b> 1) Assist crew to rig up hydraulic hose and connected to CT Reel, Injector Head and BOP.	Good & Assist			
	Rating (by SUPERVISOR)	STRONG 10 9 8 7 6 5 4 3 2	ADEQUATE Under Supervision	IMPROVEMENT NEEDED Standalone
	Employee was able to OPERATE the equipment:			
	Good & Assist			

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																				
<b>4.6 CT Reel</b> 1) Assist crew install CT Drum into CIDF. 2) Assist crew to connect all hydraulic hose from control cabin.	Rating (by SUPERVISOR) <table border="1" style="margin-bottom: 5px;"> <tr> <th style="text-align: center; padding: 2px;">STRONG</th> <th colspan="3" style="text-align: center; padding: 2px;">ADEQUATE</th> <th colspan="3" style="text-align: center; padding: 2px;">IMPROVEMENT NEEDED</th> </tr> <tr> <td style="text-align: center; padding: 2px;">10</td> <td style="text-align: center; padding: 2px;">9</td> <td style="text-align: center; padding: 2px;">8</td> <td style="text-align: center; padding: 2px;">7</td> <td style="text-align: center; padding: 2px;">6</td> <td style="text-align: center; padding: 2px;">5</td> <td style="text-align: center; padding: 2px;">4</td> <td style="text-align: center; padding: 2px;">3</td> <td style="text-align: center; padding: 2px;">2</td> </tr> </table> Employee was able to OPERATE the equipment: <table border="1" style="margin-top: 5px;"> <tr> <td style="text-align: center; padding: 2px;">Under Supervision</td> <td style="text-align: center; padding: 2px; border-left: 1px solid black;">/</td> </tr> <tr> <td style="text-align: center; padding: 2px;">Standalone</td> <td style="text-align: center; padding: 2px;"></td> </tr> </table>	STRONG	ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	Under Supervision	/	Standalone		<i>Good Assist</i>
	STRONG	ADEQUATE			IMPROVEMENT NEEDED																	
	10	9	8	7	6	5	4	3	2													
	Under Supervision	/																				
Standalone																						
<b>4.7 Injector Head</b> 1) Assist to slap in CT Injector Head	Rating (by SUPERVISOR) <table border="1" style="margin-bottom: 5px;"> <tr> <th style="text-align: center; padding: 2px;">STRONG</th> <th colspan="3" style="text-align: center; padding: 2px;">ADEQUATE</th> <th colspan="3" style="text-align: center; padding: 2px;">IMPROVEMENT NEEDED</th> </tr> <tr> <td style="text-align: center; padding: 2px;">10</td> <td style="text-align: center; padding: 2px;">9</td> <td style="text-align: center; padding: 2px;">8</td> <td style="text-align: center; padding: 2px;">7</td> <td style="text-align: center; padding: 2px;">6</td> <td style="text-align: center; padding: 2px;">5</td> <td style="text-align: center; padding: 2px;">4</td> <td style="text-align: center; padding: 2px;">3</td> <td style="text-align: center; padding: 2px;">2</td> </tr> </table> Employee was able to OPERATE the equipment: <table border="1" style="margin-top: 5px;"> <tr> <td style="text-align: center; padding: 2px;">Under Supervision</td> <td style="text-align: center; padding: 2px; border-left: 1px solid black;">/</td> </tr> <tr> <td style="text-align: center; padding: 2px;">Standalone</td> <td style="text-align: center; padding: 2px;"></td> </tr> </table>	STRONG	ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	Under Supervision	/	Standalone		<i>Good Assist</i>
STRONG	ADEQUATE			IMPROVEMENT NEEDED																		
10	9	8	7	6	5	4	3	2														
Under Supervision	/																					
Standalone																						
<b>4.8 Pressure Control Equipment</b> 1) Assist to connect hydraulic hose from Control Cabin to SBOP and Combi.	Rating (by SUPERVISOR) <table border="1" style="margin-bottom: 5px;"> <tr> <th style="text-align: center; padding: 2px;">STRONG</th> <th colspan="3" style="text-align: center; padding: 2px;">ADEQUATE</th> <th colspan="3" style="text-align: center; padding: 2px;">IMPROVEMENT NEEDED</th> </tr> <tr> <td style="text-align: center; padding: 2px;">10</td> <td style="text-align: center; padding: 2px;">9</td> <td style="text-align: center; padding: 2px;">8</td> <td style="text-align: center; padding: 2px;">7</td> <td style="text-align: center; padding: 2px;">6</td> <td style="text-align: center; padding: 2px;">5</td> <td style="text-align: center; padding: 2px;">4</td> <td style="text-align: center; padding: 2px;">3</td> <td style="text-align: center; padding: 2px;">2</td> </tr> </table> Employee was able to OPERATE the equipment: <table border="1" style="margin-top: 5px;"> <tr> <td style="text-align: center; padding: 2px;">Under Supervision</td> <td style="text-align: center; padding: 2px; border-left: 1px solid black;">/</td> </tr> <tr> <td style="text-align: center; padding: 2px;">Standalone</td> <td style="text-align: center; padding: 2px;"></td> </tr> </table>	STRONG	ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	Under Supervision	/	Standalone		<i>Good Assist</i>
STRONG	ADEQUATE			IMPROVEMENT NEEDED																		
10	9	8	7	6	5	4	3	2														
Under Supervision	/																					
Standalone																						
<b>4.9 Basic BHA Components</b> 1) Assist crew make up connector and BHA. 2) Assist crew pull test and pressure test CT connector. 3) Assist CT Supervisor to prepare BHA to be use during job.	Rating (by SUPERVISOR) <table border="1" style="margin-bottom: 5px;"> <tr> <th style="text-align: center; padding: 2px;">STRONG</th> <th colspan="3" style="text-align: center; padding: 2px;">ADEQUATE</th> <th colspan="3" style="text-align: center; padding: 2px;">IMPROVEMENT NEEDED</th> </tr> <tr> <td style="text-align: center; padding: 2px;">10</td> <td style="text-align: center; padding: 2px;">9</td> <td style="text-align: center; padding: 2px;">8</td> <td style="text-align: center; padding: 2px;">7</td> <td style="text-align: center; padding: 2px;">6</td> <td style="text-align: center; padding: 2px;">5</td> <td style="text-align: center; padding: 2px;">4</td> <td style="text-align: center; padding: 2px;">3</td> <td style="text-align: center; padding: 2px;">2</td> </tr> </table> Employee was able to OPERATE the tool: <table border="1" style="margin-top: 5px;"> <tr> <td style="text-align: center; padding: 2px;">Under Supervision</td> <td style="text-align: center; padding: 2px; border-left: 1px solid black;">/</td> </tr> <tr> <td style="text-align: center; padding: 2px;">Standalone</td> <td style="text-align: center; padding: 2px;"></td> </tr> </table>	STRONG	ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	Under Supervision	/	Standalone		<i>Good Assist</i>
STRONG	ADEQUATE			IMPROVEMENT NEEDED																		
10	9	8	7	6	5	4	3	2														
Under Supervision	/																					
Standalone																						

Doc Ref No : CTS-FORM-90

Revision No.: 01

Effective Date: 21/08/2023

(Rev.00,Dated:22/09/19-OBSOLETE)

CONTROLLED COPY

4

Scanned with CamScanner

Scanned with CamScanner

## DIMENSION BID

### COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed						Assessor Comment			
5. Job Supervision (if applicable) Please complete this section if you perform any supervisory role during operation										
	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
Please <input checked="" type="checkbox"/> accordingly to confirm the role of the employee during operation						Full Supervisor				
						2nd / Night Supervisor				

Doc.Ref No.: CTS-FORM-90

Revision No.: 01

Effective Date: 21/08/2023

(Rev.00,Dated:22/09/19-OBSOLETE)

CONTROLLED COPY

5

Scanned with CamScanner

Scanned with CamScanner

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3. To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback (Please indicate if employee is able to execute the job <u>UNDER SUPERVISION</u> or <u>STANDALONE</u> )
19 MAR 2023 to 06 APR 2023	<p>CTU Tubing Cutter via Mechanical Cutter on Well A-125</p> <p>- Mobilized from KSB to angsi A on 18 May 2023. When arrived at location, Start to offload all cargo from Setia Luhur. After completed, Proceed to start rig up CTU equipment and surface line on maindeck. Split crew after completed rig up. I was assigned as helper on night shift.</p> <p>- On well A-125, We are performing Tubing Cutter via Mechanical Cutter using Wellpro Downhole Tools. During this job, I was actively assist my colleague to make the job run smoothly. I assisted Batch Mixer Operator to mix FRS. During this hitch also I learn to operate Batch Mixe. I also learn on how to troubleshoot Batch Mixer C-Pump went back to KSB on 10 June 2023.</p>	<p>Able to execute the job under supervision.</p> <p><i>[Signature]</i> Taufiq Lewail</p>

Please tick (✓) category of services performed:

Standard Services:

Wellbore Cleanout   
CT Cementing   
Nitrogen Operations   
Pumping Services

Advanced Services

CT Fishing   
CT Milling   
CT Logging   
CT Perforation