

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	MUHAMMAD ABDUL HAZIQ BIN MOHD NOR	COB Date	22-Dec-23
Position	EQUIPMENT OPERATOR TRAINEE	RTB Date	4-Jan-24
Client	PCSB	Location	RESAK RDPA
Platform	RESAK	Well	A-17
Assessed By	MAT NOR HISSAM	Position:	COILED TUBING SUPERVISOR

Assessment Criteria	Rating (Please ✓ where appropriate)				
---------------------	-------------------------------------	--	--	--	--

Safety Awareness

- a. Usage of Personal Protective Equipment Excellent Very Good Good Satisfactory Poor
- b. Participation UAUC Excellent Very Good Good Satisfactory Poor
- c. Understanding of PTW System Excellent Very Good Good Satisfactory Poor
- d. Worksite House Keeping Excellent Very Good Good Satisfactory Poor

Work Competency

- a. Pre-job Preparation Excellent Very Good Good Satisfactory Poor
- b. Surface Equipment Rig-up Process Excellent Very Good Good Satisfactory Poor
- c. Tools/Equipment Preparation Excellent Very Good Good Satisfactory Poor
- d. Equipment Problem Trouble Shooting Capability Excellent Very Good Good Satisfactory Poor
- e. Downhole Tools Servicing/Redressing/Maintenance Excellent Very Good Good Satisfactory Poor
- f. Initiative and Creativity Excellent Very Good Good Satisfactory Poor
- g. Decision Making Capability Excellent Very Good Good Satisfactory Poor
- h. Understanding of Job Scope Excellent Very Good Good Satisfactory Poor
- i. Tools Inventory Preparation & Reporting Excellent Very Good Good Satisfactory Poor
- j. Work Quality Excellent Very Good Good Satisfactory Poor
- k. Reporting Excellent Very Good Good Satisfactory Poor

Others

- a. Punctuality and Time Keeping Excellent Very Good Good Satisfactory Poor
- b. Teamwork Excellent Very Good Good Satisfactory Poor
- c. Communication Excellent Very Good Good Satisfactory Poor
- d. Leadership Skills Excellent Very Good Good Satisfactory Poor
- e. Adaptability to Work Environment/Surrounding Excellent Very Good Good Satisfactory Poor
- f. Attitude Excellent Very Good Good Satisfactory Poor
- g. Discipline Excellent Very Good Good Satisfactory Poor

OVERALL PERFORMANCE

- Excellent Very Good Good Satisfactory Poor

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

Can be promote as BMT operator. Im comfortable and believe in him to operate BMT.

Assessed By : MAT NOR HISSAM
 Name : MAT NOR HISSAM
 Date : 6/1/124

Agreed By : RIDHWAH A212A2
 Name : RIDHWAH A212A2
 Date : 5/3/24

ON BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment
1. Job Preparation	<ol style="list-style-type: none"> 1. Attend platform coordination meeting. 2. Meeting with WSS and all crew discuss for next planning . Safety sharing by crew 3. Revalidate PTW 4. Do EMC1 for pre-job 	done
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input checked="" type="checkbox"/> Basic <input checked="" type="checkbox"/> Broad <input type="checkbox"/> Detail	
2. Surface Equipment Rig-up	<ol style="list-style-type: none"> 1. Assist crew to skid well from A-09 to A-17 2. Assist crew to rig up pumping surface line from SPO1 to coil reel and kill port to combi BOP. 3. Assist crew to rig up N2 line from NCV to CT reel. 4. Rig up 4" hose from fluid storage tank to SPO1. 5. Rig up 4" hose from BMX tank to SPO1. 6. Open hatch cover , rig up well head X-over , Single BOP . 	Good job.
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input checked="" type="checkbox"/> Broad <input type="checkbox"/> Detail	
3. Tools / Equipment Preparation	<ol style="list-style-type: none"> 1. Installing air hose from compressor to SPO1, BMX01 and wilden pump. 2. Perform EMC1 on Air Compressor and Genset for pre job. 3. Function test spin cat nozzle and break BHA 4. Break surface filter line and clean surface filter 	Good job
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input checked="" type="checkbox"/> Broad <input type="checkbox"/> Detail	
4. Equipment	<ol style="list-style-type: none"> 4.1 Batch Mixer <ol style="list-style-type: none"> 1. Mix 100 TSW inside FST. 2. Spot chemical basket on maindeck 3. Assist to mix TIW 4. Mix GEL 300bbl into BMX tank 5. Mix 20bbl pre flush solven. 6. Mix 40bbl main treatment 15% HCL 	done
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input type="checkbox"/> Basic <input checked="" type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<ol style="list-style-type: none"> 4.2 Pump Unit <ol style="list-style-type: none"> 1. Assist crew to rig up surface pumping line. 2. Assist crew to change spring and rubber seal fluid end . 3. Pressure test pumping line at 5000psi for 3minutes. 4. Flushing coil with 26bbl 	on job training.
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input checked="" type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	

ON BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment
	<p>4.3 Nitrogen Pump unit & Nitrogen Tank</p> <ol style="list-style-type: none">1. Assist crew to rig up 2" HP treating line to CT reel and include bleed off line.2. Assist crew to rig up cryogenic hose from N2 tank to inlet and outlet line on NCV.	Good Assist -
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input checked="" type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<p>4.4 Power Pack</p> <ol style="list-style-type: none">1. Assist to rig up hydraulic power hose to Injector Head.2. Assist to rig up hose from CTU Power Pack to Control Cabin.3. Disconnect CBOP and SBOP hoses and roll into control cabin	Good Assist -
Assessor's Evaluation:	Level of Skill & Knowledge <input checked="" type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<p>4.5 Control Cabin</p> <ol style="list-style-type: none">1. Assist to rig up hydraulic hose and connected to CT Reel, Injector Head and BOP.	Good Assist -
Assessor's Evaluation:	Level of Skill & Knowledge <input checked="" type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<p>4.6 CT Reel</p> <ol style="list-style-type: none">2. Assist to connect hydraulic hose from control cabin.3. Assist crew to install horse head at CIDF.4. Mixing corroded inhibitor with diesel and pour into the tank of CIDF.5. Spray CI at coil to avoid from rusty	Good Assist -
Assessor's Evaluation:	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input checked="" type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
	<p>4.7 Injector Head</p> <ol style="list-style-type: none">1. Assist to stab in CT to Injector Head	Good Assist -
Assessor's Evaluation:	Level of Skill & Knowledge <input checked="" type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK
 (PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment
Assessor's Evaluation:	4.8 Pressure Control Equipment 1. Assist to connect hydraulic hose from Control Cabin to SBOP and Combi.	Good Assist -
	Level of Skill & Knowledge <input type="checkbox"/> Awareness <input checked="" type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	
Assessor's Evaluation:	4.9 Basic BHA Components 1. Assist crew to make up BHA. 2. Assist CT Supervisor to prepare BHA to be use during job.	Good Assist -
	Level of Skill & Knowledge <input checked="" type="checkbox"/> Awareness <input type="checkbox"/> Basic <input type="checkbox"/> Broad <input type="checkbox"/> Detail	

DATE	Assignment/Summary Job/Duration
24 DEC 2023 to 4 JAN 2024	CTU activitie : Scale Cleanout. -To perform CT scale cleanout from slickline HUD - Pressure test SPIN CAT NOZZLE - Pull test connector BHA