

# DIMENSION BID

## SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	AUBREY ANDREW BERNARD	COB Date	7/5/2024
Position	SENIOR ASSISSTANT 1	RTB Date	28/5/2024
Client	SEAH 2	Location	NORTH SABAH (SOUTH FURIOUS)
Platform	SFJT-B, SFDP-A	Well	SF- 36, SF-15, SF-9L, SF-17L
Assessed By	Name: KELLEY NANTA Position: General Operator		

### RATING LEGEND:

STRONG	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
ADEQUATE	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
IMPROVEMENT NEEDED	Performance did not consistently meet expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please <input checked="" type="checkbox"/> where appropriate)								
	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
Safety Awareness (20%)	10	9	8	7	6	5	4	3	2
a. Usage of Personal Protective Equipment	<input checked="" type="checkbox"/>								
b. Participation in ACT	<input checked="" type="checkbox"/>								
c. Understanding of PTW System	<input checked="" type="checkbox"/>								
d. Worksite House Keeping		<input checked="" type="checkbox"/>							
Work Performance (20%)									
e. Initiative and Creativity			<input checked="" type="checkbox"/>						
f. Decision Making Capability				<input checked="" type="checkbox"/>					
g. Understanding of Job Scope				<input checked="" type="checkbox"/>					
h. Tools Inventory and Reporting					<input checked="" type="checkbox"/>				
i. Work Quality					<input checked="" type="checkbox"/>				
j. Reporting						<input checked="" type="checkbox"/>			
k. Punctuality and Time Keeping							<input checked="" type="checkbox"/>		
l. Teamwork							<input checked="" type="checkbox"/>		
m. Communication								<input checked="" type="checkbox"/>	
n. Leadership Skills									<input checked="" type="checkbox"/>
o. Adaptability to Work Environment/Surrounding									<input checked="" type="checkbox"/>
p. Attitude									<input checked="" type="checkbox"/>
q. Discipline									<input checked="" type="checkbox"/>

### REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

He comply procedure and task given by client and fully understand wire line program.

He able operate whinch, job survey, TCC and retrieved GL catcher. but still under supervision onsite.

In my observation you have a lot improvement, Good team work and give hand when crew need help.

Keep it up and wish you keep performing.

Assessed By [Operator]	Name: KELLEY NANTA
Name	AUBREY ANDREW BERNARD
Date	27/5/2024

# DIMENSION BID

## SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment							
1. Pre-Job Preparation	A) perform check list equipment B) check due date equipment C) ensure all tool string at worksite D) ensure all pressure hose PP to RSU at worksite E) make sure PTW sign by authorizer before approval sign F) toolbox talk before start the job G) make sure hand tools are complete at worksite								
		Rating (by Operator)		STRONG		ADEQUATE		IMPROVEMENT NEEDED	
2. Surface Equipment Rig-up	<b>Above of BOP:-</b> 3" ( stuffing box, 8f lubricator, 8f lubricator, 8f lubricator, QTS) <b>Below BOP:-</b> 3" (4F/8F lubricator, Ball valve, 2F lubricator - prepare manifold for bleed pressure at lubricator	10	9	8	7	6	5	4	3
		Rating (by Operator)		STRONG		ADEQUATE		IMPROVEMENT NEEDED	
3. Tools / Equipment Preparation	A) 1 7/8 rope socket, 1 7/8 swivel joint, 1 7/8 normal, 1 7/8 hyd jar, 1 7/8 link jar B) ready BRASS pin, STEEL pin, aluminium pin C) CHECK THE ROLL PIN IF STILL IN GOOD CONDITION D) tighten TADB tool connection and double all allen key screw F) 1-1/4" rope socket, 1-1/4" swivel joint, 1-1/4" 5F mallory stem, 1-1/4" 5F stem, 1-1/4" knuckle joint, 1-1/4" 20stroke link jar, 1-1/4" mallory stem	10	9	8	7	6	5	4	3
		Rating (by Operator)		STRONG		ADEQUATE		IMPROVEMENT NEEDED	
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>		10	9	8	7	6	5	4	3
		Rating (by Operator)		STRONG		ADEQUATE		IMPROVEMENT NEEDED	
5. Downhole Tools Servicing/Redressing/Maintenance	A) SERVICE DHT BEFORE USED B) PINNING & FUNCTION TEST DHT C) MAKE UP TOOLSTRING D) INVENTORY TOOLS E) MAKE SURE SIZE TOOLS A CORRECT F) CHECK ANY FAULTY ON DHT THAT BEING USED G) ENSURE ALL SHARP EDGES BEING FILE TO PREVENT FROM HAND INJURED H) TIGHTEN ALL TOOLS CONNECTION BEFORE RIH	10	9	8	7	6	5	4	3
		Rating (by Operator)		STRONG		ADEQUATE		IMPROVEMENT NEEDED	

Type of Task	Tasks Performed						Assessor Comment					
6. Tools Inventory & Reporting	A) Done check B) soft copy already give to operator for hand over next incoming crew C) print hard copy list											
	Rating (by Operator)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
10				9	8	7	6	5	4	3	2	
7. Equipment Operation	[Operator to rate TSA / SA / SSA competency in operating the equipment]											
	Rating (by Operator)			STRONG			ADEQUATE			IMPROVEMENT NEEDED		
				10	9	8	7	6	5	4	3	2
	Power Pack				√							
	Air Compressor											
	GenSet											
	Control Panel				√							
	Test Pump							√				
	Pressure Control Equipment				√							
	Mast				√							
Weight & Measuring Devices							√					
Downhole Tools							√					
	Total	0	0	0	0	0	0	0	0	0	0	
Comments by Operator [please specify competency gaps / area of improvement]												
<b>EXECUTE THE WELL SERVICES OPERATION (IF ANY)</b> (Operating Winch)												
Date / Location / Well No. / Job Type	Activity Summary						Toolstring Configuration					
Rating (by Operator)			STRONG			ADEQUATE			IMPROVEMENT NEEDED			
			10	9	8	7	6	5	4	3	2	
Comments by Operator [please specify competency gaps / area of improvement]												

To be completed by verifier (FSM)

## SUMMARY OF OVERALL PERFORMANCE

		Score		
		Weight	Total	%
A	Safety Awareness	20	#REF!	#REF!
B	Work Performance	20	#REF!	#REF!
C	Technical Skills	60	52	44.571
	1. Pre-Job Preparation	8		
	2. Surface Equipment Rig-up	7		
	3. Tools / Equipment Preparation	8		
	4. Equipment Problem Troubleshooting	9		
	5. Downhole Tools Servicing/Redressing/Maintenance	6		
	6. Tools Inventory & Reporting	7		
	7. Equipment Operation	7		
D	TOTAL (A+B+C)	100		#REF!

# DIMENSION BID

## SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	AUBREY ANDREW BERNARD	COB Date	2/4/2024
Position	SENIOR ASSISSTANT 1	RTB Date	30/4/2024
Client	SEAH 3 / IWS	Location	NORTH SABAH SOUTH
Platform	SFJT-B / E	Well	SF- 31 / 515,507
Assessed By	Name: YUZIE / ADON Position: OPERATOR		

### RATING LEGEND:

STRONG	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
ADEQUATE	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
IMPROVEMENT NEEDED	Performance did not consistently meet expectations - performance failed to meet expectations in one or more essential areas of responsibility


Assessment Criteria	Rating (Please ✓ where appropriate)								
	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
Safety Awareness (20%)	10	9	8	7	6	5	4	3	2
a. Usage of Personal Protective Equipment	X								
b. Participation in ACT	X								
c. Understanding of PTW System	X								
d. Worksite House Keeping	X								
Work Performance (20%)									
e. Initiative and Creativity		X							
f. Decision Making Capability		X							
g. Understanding of Job Scope		X							
h. Tools Inventory and Reporting		X							
i. Work Quality		X							
j. Reporting		X							
k. Punctuality and Time Keeping		X							
l. Teamwork		X							
m. Communication		X							
n. Leadership Skills			X						
o. Adaptability to Work Environment/Surrounding			X						
p. Attitude				X					
q. Discipline				X					

### REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

wiling and ready to take instruction from leader and supervisor

excellent attitude , time keeping and good team player

understand about wireline operation and proactive in tool preparation service and maintenance.

Assessed By [Operator]	Name: ADON KASU	
Name	AUBREY ANDREW BERNARD	
Date	29/4/2024	

# DIMENSION BID

## SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment																																						
<b>1. Pre-Job Preparation</b>	A) perform check list equipment B) check due date equipment C) ensure all tool string at worksite D) ensure all pressure hose PP to RSU at worksite E) make sure PTW sign by authorizer before approval sign F) toolbox talk before start the job G) make sure hand tools are complete at worksite																																							
	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2" style="width: 15%;">Rating (by Operator)</th> <th colspan="3" style="width: 30%;">STRONG</th> <th colspan="3" style="width: 20%;">ADEQUATE</th> <th colspan="4" style="width: 30%;">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2	9																		
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																																	
	10	9	8	7	6	5	4	3	2																															
9																																								
<b>2. Surface Equipment Rig-up</b>	Above of BOP:- 3"( stuffing box, 8f lubricator, 8f lubricator, 8f lubricator, QTS) Below BOP:- 3" (4F/8F lubricator, Ball valve, 2F lubricator - prepare manifold for bleed pressure at lubricator																																							
	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2" style="width: 15%;">Rating (by Operator)</th> <th colspan="3" style="width: 30%;">STRONG</th> <th colspan="3" style="width: 20%;">ADEQUATE</th> <th colspan="4" style="width: 30%;">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2	9																		
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																																	
	10	9	8	7	6	5	4	3	2																															
9																																								
<b>3. Tools / Equipment Preparation</b>	A) 1 7/8" rope socket, 1 7/8" swivel joint, 1 7/8" normal, 1 7/8" hyd jar, 1 7/8" link jar B) ready BRASS pin, STEEL pin, aluminium pin C) CHECK THE ROLL PIN IF STILL IN GOOD CONDITION D) tighten TADS tool connection and double all allen key screw E) 1-1/4" rope socket, 1-1/4" swivel joint, 1-1/4" 5F mallowy stem, 1-1/4" 5F stem, 1-1/4" knuckle joint, 1-1/4" 20stroke link jar, 1-1/4" mallowy stem																																							
	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2" style="width: 15%;">Rating (by Operator)</th> <th colspan="3" style="width: 30%;">STRONG</th> <th colspan="3" style="width: 20%;">ADEQUATE</th> <th colspan="4" style="width: 30%;">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2	9																		
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																																	
	10	9	8	7	6	5	4	3	2																															
9																																								
<b>4. Equipment Problem Troubleshooting</b> <i>[Please state type of equipment and describe troubleshooting job performed]</i>																																								
	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2" style="width: 15%;">Rating (by Operator)</th> <th colspan="3" style="width: 30%;">STRONG</th> <th colspan="3" style="width: 20%;">ADEQUATE</th> <th colspan="4" style="width: 30%;">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2	9																		
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																																	
	10	9	8	7	6	5	4	3	2																															
9																																								
<b>5. Downhole Tools Servicing/Redressing/Maintenance</b>	A) SERVICE DHT BEFORE USED B) PINNING & FUNCTION TEST DHT C) MAKE UP TOOLSTRING D) INVENTORY TOOLS E) MAKE SURE SIZE TOOLS A CORRECT F) CHECK ANY FAULTY ON DHT THAT BEING USED G) ENSURE ALL SHARP EDGES BEING FILE TO PREVENT FROM HAND INJURED H) TIGHTEN ALL TOOLS CONNECTION BEFORE RIH																																							
	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2" style="width: 15%;">Rating (by Operator)</th> <th colspan="3" style="width: 30%;">STRONG</th> <th colspan="3" style="width: 20%;">ADEQUATE</th> <th colspan="4" style="width: 30%;">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2	9																		
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																																	
	10	9	8	7	6	5	4	3	2																															
9																																								

Type of Task	Tasks Performed			Assessor Comment							
6. Tools Inventory & Reporting	A) Done check copy already give to operator for hand over next incoming crew B) soft copy list C) print hard										
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
	10	9	8	7	6	5	4	3	2		
7. Equipment Operation	[Operator to rate TSA / SA / SSA competency in operating the equipment]										
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			
	10	9	8	7	6	5	4	3	2		
	Power Pack		X								
	Air Compressor										
	GenSet										
	Control Panel	X									
	Test Pump	X									
	Pressure Control Equipment	X									
Mast											
Weight & Measuring Devices	X										
Downhole Tools	X										
Total	0	0	0	0	0	0	0	0	0		
Comments by Operator [please specify competency gaps / area of improvement]											
EXECUTE THE WELL SERVICES OPERATION (IF ANY) (Operating Winch)											
Date / Location / Well No. / Job Type	Activity Summary				Toolstring Configuration						
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				
	10	9	8	7	6	5	4	3	2		
Comments by Operator [please specify competency gaps / area of improvement]											

To be completed by verifier (FSM)

## SUMMARY OF OVERALL PERFORMANCE

			Score		
	Weight	Total	%		
A	Safety Awareness	20	#REF!	#REF!	
B	Work Performance	20	#REF!	#REF!	
C	Technical Skills	60	52	44.571	
	1. Pre-Job Preparation	8			
	2. Surface Equipment Rig-up	7			
	3. Tools / Equipment Preparation	8			
	4. Equipment Problem Troubleshooting	9			
	5. Downhole Tools Servicing/Redressing/Maintenance	6			
	6. Tools Inventory & Reporting	7			
	7. Equipment Operation	7			
D	TOTAL (A+B+C)	100			#REF!