

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	SHAHRI IZHAM BIN ALIAS	COB Date	17/7/2024
Position	EQUIPMENT OPERATOR TRAINEE	RTB Date	14/8/2024
Client	PCSB	Location	ANGSI
Platform	ANGSI BRAVO	Well	B-175
Assessed By	Name: <u>MUHAMMAD BIN MOHAMMAD</u> Position: <u>- GEO -</u>		

RATING LEGEND:	
STRONG	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
ADEQUATE	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
IMPROVEMENT NEEDED	Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
---------------------	-------------------------------------	--	--	--	--	--	--	--	--

Safety Awareness (20%)

- Usage of Personal Protective Equipment
- Participation in UAUC
- Understanding of PTW System
- Worksite House Keeping

STRONG			ADEQUATE			IMPROVEMENT NEEDED		
10	9	8	7	6	5	4	3	2
✓								
	✓							
	✓							
		✓						


Work Performance (20%)

- Initiative and Creativity
- Decision Making Capability
- Understanding of Job Scope
- Tools Inventory and Reporting
- Work Quality
- Reporting
- Punctuality and Time Keeping
- Teamwork
- Communication
- Leadership Skills
- Adaptability to Work Environment/Surrounding
- Attitude
- Discipline

	✓							
		✓						
	✓							
✓								
	✓							
	✓							
	✓							
	✓							
	✓							
	✓							

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

- Assign as PTW applicant and operator during working period.
- Able to stand alone operate BUX without supervisor.

Assessed By [Supervisor]	
Name	<u>Muhammad Bin Mohamed</u>
Date	<u>17-7-2024, 13/8/2024</u>

Doc.Ref.No.: CTS-FORM-90

Revision No.: 01

Effective Date: 21/08/2023

(Rev.00,Dated:22/09/19-OBSOLETE)

CONTROLLED COPY

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
1. Pre-Job Preparation	1. Attend pre-job meeting before mob 2. Prepare e-ptw 3. Attend toolbox meeting conduct by wss and all intervention crew on board	- Done -																		
Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
2. Surface Equipment Rig-up	1. Assist crew for heavy lifting to spot the equipment according to space availability 2. Assist crew to spot single pump at available space with sufficient 3. Assist crew to rig-up 4" LP hoses from fst to batch mixer and single pump unit	Good job.																		
Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
3. Tools / Equipment Preparation	1. Perfome emc1 on all equipment 2. Connect air hose from air compressor to all equipment 3. Top up diesel to all equipment everyday before start operation	- Done -																		
Rating (by Operator) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
4. Equipment	4.1 Batch Mixer 1. Connect hydraulic hose from batch mixer power pack to batch mixer tank 2. Rearrange chemicals and put some on the tank batch mixer. 3. Rig-up 4" LP hose from batch mixer to single pump 4. Perfome mixing 7.5% HCL for 100 barrels under supervision.	- Good job -																		
Rating (by SUPERVISOR) <table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		Under Supervision <input checked="" type="checkbox"/> Standalone <input type="checkbox"/>																		

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor (WEIGHT: 60%)

Type of Task	Tasks Performed	Assessor Comment																											
4.2 Pump Unit	1. Assist pump operator to rig-up single pump 2. Assist pump operator to connect hydraulic hose 3. Assist pump operator to install universal shaft 4. Assist pump operator to rig-up 2" pumping line from single pump unit line to wellhead.	Good job																											
Rating (by SUPERVISOR) <table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td>7</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2				7						
STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
10	9	8	7	6	5	4	3	2																					
			7																										
Employee was able to OPERATE the equipment:		Under Supervision Standalone																											
4.3 Nitrogen Pump unit & Nitrogen Tank																													
Rating (by SUPERVISOR) <table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td>7</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2				7						
STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
10	9	8	7	6	5	4	3	2																					
			7																										
Employee was able to OPERATE the equipment:		Under Supervision Standalone																											
4.4 Power Pack																													
Rating (by SUPERVISOR) <table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2										
STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
10	9	8	7	6	5	4	3	2																					
Employee was able to OPERATE the equipment:		Under Supervision Standalone																											
4.5 Control Cabin																													
Rating (by SUPERVISOR) <table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2										
STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
10	9	8	7	6	5	4	3	2																					
Employee was able to OPERATE the equipment:		Under Supervision Standalone																											

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																											
	4.6 CT Reel																												
	<table border="1"> <tr> <td rowspan="2">Rating (by SUPERVISOR)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2									
Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																						
	10	9	8	7	6	5	4	3	2																				
	Employee was able to OPERATE the equipment:				Under Supervision																								
					Standalone																								
	4.7 Injector Head																												
	<table border="1"> <tr> <td rowspan="2">Rating (by SUPERVISOR)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2									
Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																						
	10	9	8	7	6	5	4	3	2																				
	Employee was able to OPERATE the equipment:				Under Supervision																								
					Standalone																								
	4.8 Pressure Control Equipment																												
	<table border="1"> <tr> <td rowspan="2">Rating (by SUPERVISOR)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2									
Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																						
	10	9	8	7	6	5	4	3	2																				
	Employee was able to OPERATE the equipment:				Under Supervision																								
					Standalone																								
	4.9 Basic BHA Components																												
	<table border="1"> <tr> <td rowspan="2">Rating (by SUPERVISOR)</td> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2									
Rating (by SUPERVISOR)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																						
	10	9	8	7	6	5	4	3	2																				
	Employee was able to OPERATE the tools:				Under Supervision																								
					Standalone																								

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																											
5. Job Supervision (if applicable) <i>Please complete this section if you perform any supervisory role during operation</i>																													
	<table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> </tr> </thead> <tbody> <tr> <td colspan="3"></td> <td colspan="3"></td> <td colspan="3"></td> </tr> </tbody> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2										
STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
10	9	8	7	6	5	4	3	2																					
	Rating (by SUPERVISOR)																												
	Please ✓ accordingly to confirm the role of the employee during operation	<table border="1"> <tr> <td>Full Supervisor</td> <td></td> </tr> <tr> <td>2nd / Night Supervisor</td> <td></td> </tr> </table>	Full Supervisor		2nd / Night Supervisor																								
Full Supervisor																													
2nd / Night Supervisor																													

DIMENSION BID

COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3: To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback (Please indicate if employee is able to execute the job <u>UNDER SUPERVISION</u> or <u>STANDALONE</u>)
	<ul style="list-style-type: none"> -Mobilized from KSB to ANGSI BRAVO on 17 July 2024. -Start heavy lifting upon obtaining permission from OIM -Rig-up equipment and surface rigup after finish spot the equipment to space availability. -Install correct wellhead crossover on the wellhead.Ensure well is fully secured and record the MV and CV turns. -Perfome EMC1 for all equipment -Start up and run all equipment for few minutes. -Fill and pressure test the treating line with water to 500 psi for 5 minutes and 3000 psi for 10 minutes. -To increase soaking period from 2 hours to 4 hours for tubing pickling stage and 15% HCL treatment. -To perform 2 hours soaking after completion of SAS treatment pumping prior continue with post flush -To perform over-flush for all stage with water injection module at max ITHP and continous over-night pumping. 	Keep it and Good job

Please tick (✓) category of services performed:

Standard Services:

Wellbore Cleanout	<input type="checkbox"/>
CT Cementing	<input type="checkbox"/>
Nitrogen Operations	<input type="checkbox"/>
Pumping Services	<input type="checkbox"/>

Advanced Services

CT Fishing	<input type="checkbox"/>
CT Milling	<input type="checkbox"/>
CT Logging	<input type="checkbox"/>
CT Perforation	<input type="checkbox"/>