

# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 1: To be completed by Assessor [WEIGHT: 40%]

Name	JUAN MUHAMMAD HANIT bin WAN MUKHTAR.	COB Date	17/10/2023
Position	EQUIPMENT OPERATOR TRAINEE	RTB Date	14/11/2023
Client	PETRONAS CARIGALI	Location	DULANG.
Platform	DULANG CHARLIE	Well	C-24L
Assessed By	Name:	Position:	

**RATING LEGEND:**

**STRONG** Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

**ADEQUATE** Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good

**IMPROVEMENT NEEDED** Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
---------------------	-------------------------------------	--	--	--	--	--	--	--	--

### Safety Awareness (20%)

- a. Usage of Personal Protective Equipment
- b. Participation in UAUC
- c. Understanding of PTW System
- d. Worksite House Keeping

STRONG			ADEQUATE			IMPROVEMENT NEEDED		
10	9	8	7	6	5	4	3	2
✓								
	✓							
		✓						
		✓						


### Work Performance (20%)

- e. Initiative and Creativity
- f. Decision Making Capability
- g. Understanding of Job Scope
- h. Tools Inventory and Reporting
- i. Work Quality
- j. Reporting
- k. Punctuality and Time Keeping
- l. Teamwork
- m. Communication
- n. Leadership Skills
- o. Adaptability to Work Environment/Surrounding
- p. Attitude
- q. Discipline

		✓						
		✓						
			✓					
			✓					
			✓					
			✓					
	✓							
	✓							
		✓						
			✓					
		✓						
	✓							

### REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

\* Overall Good

Assessed By [Supervisor]	
Name	Muhammad Syukri B Samudra
Date	13/11/2023

## DIMENSION BID

### COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2. To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
1. Pre-Job Preparation	1. Pack/Prepare Chemical From Base To Dulong Chartre. 2. Attend Toolbox And Morning Meeting With CSR. 3. Prepare EPIW Before Do The Job.	* Done																		
	Rating (by SUPERVISOR) <table border="1"> <tr> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
2. Surface Equipment Rig-up	1. Assist Crew Pumping Surface Line From SPO2 To Ctu Reel And Kill Port Line To COMBI.	* Done																		
	Rating (by SUPERVISOR) <table border="1"> <tr> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
3. Tools / Equipment Preparation	1. Perform EMI Before Start The Job. 2. Top Up Dress On Equipment	* Done																		
	Rating (by Operator) <table border="1"> <tr> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
4. Equipment	4.1 Batch Mixer 1. MIXING Pre Flush solvent with specialist Chemical On Board 117 Bbls. 2. Assist chemical specialist mixing Acid Descaler 15% HCL 117 Bbls. 3. Assist chemical specialist mixing Post Flush with Finess Control Agent 117 Bbls.	* Done																		
	Rating (by SUPERVISOR) <table border="1"> <tr> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
	Employee was able to OPERATE the equipment:	<table border="1"> <tr> <td>Under Supervision</td> <td></td> </tr> <tr> <td>Standalone</td> <td></td> </tr> </table>	Under Supervision		Standalone															
Under Supervision																				
Standalone																				

## DIMENSION BID

### COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
4.2 Pump Unit	1. Assist Pump Man Rig up Pumping line.	* Done																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td><td></td> </tr> <tr> <td>Standalone</td><td></td> </tr> </table>	Under Supervision		Standalone															
Under Supervision																				
Standalone																				
4.3 Nitrogen Pump unit & Nitrogen Tank	1. Assist crew Rig up NCU line to CE Reel. 2. Assist crew open/close valve. 3. Assist crew Transfer Nitrogen.	* Done																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td><td></td> </tr> <tr> <td>Standalone</td><td></td> </tr> </table>	Under Supervision		Standalone															
Under Supervision																				
Standalone																				
4.4 Power Pack																				
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td><td></td> </tr> <tr> <td>Standalone</td><td></td> </tr> </table>	Under Supervision		Standalone															
Under Supervision																				
Standalone																				
4.5 Control Cabin																				
Rating (by SUPERVISOR)	<table border="1"> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td><td></td> </tr> <tr> <td>Standalone</td><td></td> </tr> </table>	Under Supervision		Standalone															
Under Supervision																				
Standalone																				



# DIMENSION BID

## COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																		
4.6 CT Reel	<p>1. Assist CT Operator To spool In Or Out Coil During Running The Job.</p> <p>2. Lubricant CT string with Corrosion Inhibitor And Diesel.</p>	* Done																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td><td></td> </tr> <tr> <td>Standalone</td><td></td> </tr> </table>	Under Supervision		Standalone															
Under Supervision																				
Standalone																				
4.7 Injector Head																				
Rating (by SUPERVISOR)	<table border="1"> <tr> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td><td></td> </tr> <tr> <td>Standalone</td><td></td> </tr> </table>	Under Supervision		Standalone															
Under Supervision																				
Standalone																				
4.8 Pressure Control Equipment																				
Rating (by SUPERVISOR)	<table border="1"> <tr> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the equipment:		<table border="1"> <tr> <td>Under Supervision</td><td></td> </tr> <tr> <td>Standalone</td><td></td> </tr> </table>	Under Supervision		Standalone															
Under Supervision																				
Standalone																				
4.9 Basic BHA Components	<p>1. Assist Crew Make up BHA Tools for The Job.</p>	* Done																		
Rating (by SUPERVISOR)	<table border="1"> <tr> <td colspan="3">STRONG</td> <td colspan="3">ADEQUATE</td> <td colspan="3">IMPROVEMENT NEEDED</td> </tr> <tr> <td>10</td><td>9</td><td>8</td> <td>7</td><td>6</td><td>5</td> <td>4</td><td>3</td><td>2</td> </tr> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2	
STRONG			ADEQUATE			IMPROVEMENT NEEDED														
10	9	8	7	6	5	4	3	2												
Employee was able to OPERATE the tools:		<table border="1"> <tr> <td>Under Supervision</td><td></td> </tr> <tr> <td>Standalone</td><td></td> </tr> </table>	Under Supervision		Standalone															
Under Supervision																				
Standalone																				

## DIMENSION BID

### COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 2: To be completed by Employee and Assessor [WEIGHT: 60%]

Type of Task	Tasks Performed	Assessor Comment																											
<p>5. Job Supervision (if applicable) Please complete this section if you perform any supervisory role during operation</p>	<p>1. I have Completed Operate Batch Mixer Until The Job Run Successfully. Done Perform Mixing Chemical with Chemical Specialist PIC Flush, Acid Des Ciler And Post Flush.</p>	<p>Done</p>																											
Rating (by SUPERVISOR)	<table border="1"> <thead> <tr> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <th>10</th><th>9</th><th>8</th><th>7</th><th>6</th><th>5</th><th>4</th><th>3</th><th>2</th></tr> </thead> <tbody> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table>	STRONG			ADEQUATE			IMPROVEMENT NEEDED			10	9	8	7	6	5	4	3	2										
STRONG			ADEQUATE			IMPROVEMENT NEEDED																							
10	9	8	7	6	5	4	3	2																					
Please ✓ accordingly to confirm the role of the employee during operation		<table border="1"> <tr> <td>Full Supervisor</td><td></td></tr> <tr> <td>2nd / Night Supervisor</td><td></td></tr> </table>	Full Supervisor		2nd / Night Supervisor																								
Full Supervisor																													
2nd / Night Supervisor																													

## DIMENSION BID

### COILED TUBING PERFORMANCE ASSESSMENT FEEDBACK

PART 3: To be completed by Employee and Assessor

DATE	Assignment/Summary Job/Duration	Supervisor's Feedback (Please indicate if employee is able to execute the job <u>UNDER SUPERVISION</u> or <u>STANDALONE</u> )
OCT 17 <del>14</del> 2023	- CTU Proceed with CT Acid Wash with current Condition without CT Packer Due To severity of Tubing Condition.	* Done * good job.
14 Nov 2023.	- Crew change with Crew On board At Charlie 17 October 2023. Start Assist crew rig up surface line. Perform Misting Pre Flush Solvent, Acid Descaler 15% HCL And Post Flush with Finess Control Agent. Back to PDST 14 November 2023 Already Completed 4 weeks On board.	

Please tick (✓) category of services performed:

**Standard Services:**

Wellbore Cleanout ☒  
 CT Cementing ☐  
 Nitrogen Operations ☐  
 Pumping Services ☐

**Advanced Services**

CT Fishing ☐  
 CT Milling ☐  
 CT Logging ☐  
 CT Perforation ☐