

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	BENNYLOVE BENJAMIN	COB Date	25/4/2023'
Position	SLICKLINE ASSISTANT II	RTB Date	24/5/2023'
Client	SEA HIBISCUS	Location	BARTON & ST. JOSEPH
Platform	BTMP-B & SJJT-H	Well	BT-203S, BT-203L & SJ-807
Assessed By	Name:YUZIE Position:SLICKLINE OPERATOR		

RATING LEGEND:

STRONG Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

ADEQUATE Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good

IMPROVEMENT NEEDED Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility


Assessment Criteria	Rating (Please v where appropriate)
---------------------	-------------------------------------

	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
Safety Awareness (20%)									
a. Usage of Personal Protective Equipment	✓								
b. Participation in ACT	✓								
c. Understanding of PTW System	✓								
d. Worksite House Keeping	✓								

Work Performance (20%)									
e. Initiative and Creativity			✓						
f. Decision Making Capability			✓	✓					
g. Understanding of Job Scope		✓							
h. Tools Inventory and Reporting		✓							
i. Work Quality		✓							
j. Reporting			✓						
k. Punctuality and Time Keeping		✓							
l. Teamwork	✓								
m. Communication	✓								
n. Leadership Skills				✓					
o. Adaptability to Work Environment/Surrounding			✓						
p. Attitude		✓							
q. Discipline		✓							

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

KEEP IT UP

Assessed By [Operator]		
Name		YUZIE
Date		8/5/2023

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment								
1. Pre-Job Preparation	1) Performed pre start checklist onequipment. 2)To verify all hoses was tight,put whip check and no leak. 3) Check diesel,coolant ,engine oil and hydraulic level on PP. 4) Check onRSU condition. 5) Walk the line to ensure hose fit to use and no creak and leak.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
2. Surface Equipment Rig-up	A). 3"stuffing box B). 3" 8ft lubractor (3pcs) C). 3" 4ft lubractor pup (3pcs) D). 3" dual BOP E). 3"ball valve F). 3" QTS Note: Check O-ring and clean up the thread before rig up.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
3. Tools / Equipment Preparation	Wax Cut - Toolstring Configuration as follow: 1.7/8" BDK R/Socket QLS (1ft 1ins) + 1.7/8" swivel joint (1ft 2ins) + 1.7/8" x 5ft Normal Roller stem + 1.7/8"KJ + 1.7/8 Hyd Jar + Link jar (5ft 3") Total length of tool string: 20ft. + 2.5" Wire Scratcher & 3" Wire Scratcher.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>										
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
5. Downhole Tools Servicing/Redressing/Maintenance	1). Wire Scratcher - Change to new braided line 3/16" for 3" and 2.5" wire scratcher. 2). 1-7/8" Hydraulic Jar - Service 3). 2.5" RS Pulling tools- Redress, change pin and do surface function test. 4). 2.5" SB Pulling tools - Resdress, chance pin and do surface function test.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2

Type of Task	Tasks Performed	Assessor Comment									
6. Tools Inventory & Reporting	1. Reinventory all tools inside the DHT toolbox to identify if there is any tool need to request or to locate any tools that have been borrowed by other location and borrowed tools from other location.										
		Rating (by Operator)			STRONG			ADEQUATE			IMPROVEMENT NEEDED
		10	9	8	7	6	5	4	3	2	
7. Equipment Operation	[Operator to rate TSA / SA / SSA competency in operating the equipment]										
	Rating (by Operator)										
	STRONG										
	ADEQUATE										
	IMPROVEMENT NEEDED										
	10 9 8 7 6 5 4 3 2										
	Power Pack										
	Air Compressor										
	GenSet										
	Control Panel										
Test Pump											
Pressure Control Equipment											
Mast											
Weight & Measuring Devices											
Downhole Tools											
Total 0 0 0 0 0 0 0 0 0 0											
Comments by Operator [please specify competency gaps / area of improvement]											
EXECUTE THE WELL SERVICES OPERATION (IF ANY) (Operating Winch)											
Date / Location / Well No. / Job Type	Activity Summary					Toolstring Configuration					
Rating (by Operator)											
STRONG											
ADEQUATE											
IMPROVEMENT NEEDED											
10 9 8 7 6 5 4 3 2											
Comments by Operator [please specify competency gaps / area of improvement]											

Type of Task		Tasks Performed	Assessor Comment
JOB DETAIL:			
DATE	WELL NO.	JOB TYPE	STATUS (COMPLETE / INCOMPLETE)
06/04/2023	BT-2035	TCC	INCOMPLETE
28/04/2023	BT-2034	TCC, S4S, GLVC.	COMPLETE
08/05/2023	SJ-907	WAX CUT	COMPLETE

To be completed by verifier (FSM)

SUMMARY OF OVERALL PERFORMANCE

		Weight	Score	
			Total	%
A	Safety Awareness	20	#REF!	#REF!
B	Work Performance	20	#REF!	#REF!
C	Technical Skills	60	52	44.571
	1. Pre-Job Preparation	8		
	2. Surface Equipment Rig-up	7		
	3. Tools / Equipment Preparation	8		
	4. Equipment Problem Troubleshooting	9		
	5. Downhole Tools Servicing/Redressing/Maintenance	6		
	6. Tools Inventory & Reporting	7		
	7. Equipment Operation	7		
D	TOTAL (A+B+C)	100		#REF!