

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	MUHAMMAD SYAFIQ BIN ARIFFIN	COB Date	25/6/2024
Position	ACTING SNR SLICKLINE ASSISTANT	RTB Date	23/7/2024
Client	VESTIGO	Location	LARUT , BERANTAI
Platform	LARUT-A , BERANTAI WELLHEAD	Well.	LRA-30, BRWA-19 , BRWA-13
Assessed By	Name: MUHAMMAD ASYRAF BIN BASRI Position: SNR SLICKLINE OPERATOR		

RATING LEGEND:

STRONG	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
ADEQUATE	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
IMPROVEMENT NEEDED	Performance did not consistently meet expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)								
---------------------	-------------------------------------	--	--	--	--	--	--	--	--

Safety Awareness (20%)

- a. Usage of Personal Protective Equipment
- b. Participation in ACT
- c. Understanding of PTW System
- d. Worksite House Keeping

	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
a. Usage of Personal Protective Equipment	/								
b. Participation in ACT			/						
c. Understanding of PTW System			/						
d. Worksite House Keeping		/							


Work Performance (20%)

- e. Initiative and Creativity
- f. Decision Making Capability
- g. Understanding of Job Scope
- h. Tools Inventory and Reporting
- i. Work Quality
- j. Reporting
- k. Punctuality and Time Keeping
- l. Teamwork
- m. Communication
- n. Leadership Skills
- o. Adaptability to Work Environment/Surrounding
- p. Attitude
- q. Discipline

	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2
e. Initiative and Creativity			/						
f. Decision Making Capability			/						
g. Understanding of Job Scope	/								
h. Tools Inventory and Reporting	/								
i. Work Quality	/								
j. Reporting	/								
k. Punctuality and Time Keeping	/								
l. Teamwork	/								
m. Communication	/								
n. Leadership Skills	/								
o. Adaptability to Work Environment/Surrounding	/								
p. Attitude	/								
q. Discipline	/								

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

Good Job .

Assessed By [Operator]	
Name	MUHAMMAD ASYRAF BIN BASRI
Revision No.: 03	CONTROLLED COPY
Date	
Effective Date: 22/05/2023	

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment																			
1. Pre-Job Preparation	TBT WITH WIS AND WAITING PERMIT APPROVAL , REVIEW JHA, SAFETY SHARING , REVIEW JOB PROGRAM AND WELL HISTORY	Good																			
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Rating (by Operator)</td> <td colspan="3" style="text-align: center;">STRONG</td> <td colspan="3" style="text-align: center;">ADEQUATE</td> <td colspan="3" style="text-align: center;">IMPROVEMENT NEEDED</td> </tr> <tr> <td></td> <td style="text-align: center;">10</td> <td style="text-align: center;">9</td> <td style="text-align: center; border: 2px solid black;">8</td> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												
2. Surface Equipment Rig-up	*ARRANGE AND SPOT EQUIPMENT ON MAIN DECK, *ASSIST CRANE OPERATOR LIFTING EQUIPMENT *MAKE UP LUBRICATOR SECTION, OPEN TREE CAP , RIG UP RISER + PUMP IN TEE + BOP + QTS + LUBRICATOR + STUFFING BOX AND REHEAD ROPE SOCKET. *HOOK UP CONTROL LINE. *PERFORM STANDART WELL ENTRY AND EXIT PROCEDURE	Good.																			
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Rating (by Operator)</td> <td colspan="3" style="text-align: center;">STRONG</td> <td colspan="3" style="text-align: center;">ADEQUATE</td> <td colspan="3" style="text-align: center;">IMPROVEMENT NEEDED</td> </tr> <tr> <td></td> <td style="text-align: center;">10</td> <td style="text-align: center; border: 2px solid black;">9</td> <td style="text-align: center;">8</td> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												
3. Tools / Equipment Preparation	*PREPARE TOOL STRING CONFIGURATION FOR NEXT RUN *UPDATE DAILY CHECKLIST FOR SLIMLINE UNIT, CONTROL PANEL, TEST PUMP , POWER PACK AND MAST 70FT AND 40FT.	Good																			
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Rating (by Operator)</td> <td colspan="3" style="text-align: center;">STRONG</td> <td colspan="3" style="text-align: center;">ADEQUATE</td> <td colspan="3" style="text-align: center;">IMPROVEMENT NEEDED</td> </tr> <tr> <td></td> <td style="text-align: center;">10</td> <td style="text-align: center;">9</td> <td style="text-align: center; border: 2px solid black;">8</td> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>	NA																				
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Rating (by Operator)</td> <td colspan="3" style="text-align: center;">STRONG</td> <td colspan="3" style="text-align: center;">ADEQUATE</td> <td colspan="3" style="text-align: center;">IMPROVEMENT NEEDED</td> </tr> <tr> <td></td> <td style="text-align: center;">10</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												
5. Downhole Tools Servicing/Redressing/Maintenance	*SERVICE TOOL ,REDRESS AND RE-PIN, PULLING TOOL, SB PULLING TOOL , RB PULLING TOOL *MAKE NEW ROPE SOCKET WIRE 0.140" & 0.160" *SETTING SPRING JAR WITH CALIBRATION SUB *PREPARE SB P/TOOL, JUC P/TOOL, GS P/TOOL, *PREPARE FLUTE CENTRALIZER , WIRE BRUSH, 3 PRONG GRAB, 2 PRONG GRAB, BOWEN FINDER, COMBINATION FINDER GRAB,	need to learn more details on compartment DHT .																			
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Rating (by Operator)</td> <td colspan="3" style="text-align: center;">STRONG</td> <td colspan="3" style="text-align: center;">ADEQUATE</td> <td colspan="3" style="text-align: center;">IMPROVEMENT NEEDED</td> </tr> <tr> <td></td> <td style="text-align: center;">10</td> <td style="text-align: center;">9</td> <td style="text-align: center; border: 2px solid black;">8</td> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												

Type of Task	Tasks Performed	Assessor Comment																											
6. Tools Inventory & Reporting	DAILY CHECKLIST, DOR, CSS, TMS, INVENTORY, LOADOUT LIST, MANIFEST	<i>Good</i>																											
	<table border="1"> <tr> <th>Rating (by Operator)</th> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td></td> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2								
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																						
	10	9	8	7	6	5	4	3	2																				
7. Equipment Operation	[Operator to rate TSA / SA / SSA competency in operating the equipment]																												
	<table border="1"> <tr> <th>Rating (by Operator)</th> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td></td> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2								
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																					
		10	9	8	7	6	5	4	3	2																			
	Power Pack																												
Air Compressor																													
GenSet																													
Control Panel																													
Test Pump																													
Pressure Control Equipment																													
Mast																													
Weight & Measuring Devices																													
Downhole Tools																													
Total		0	0	0	0	0	0	0	0																				
Comments by Operator (please specify competency gaps / area of improvement)																													
EXECUTE THE WELL SERVICES OPERATION (IF ANY) (Operating Winch)																													
Date / Location / Well No. / Job Type	Activity Summary	Toolstring Configuration																											
27/6/2024 LARUT-A A-30 FISHING JOB	RUN#01 RIH 2.50" PCE P/TOOL (3/16) AND LATCHED WITH TANDEM COMBINATION FINDER GRAB @10213FT-THF (3127M-MDDF). FLAGED WIRE, PICKUP EAJ ACTIVATED AT 1500LBS, TENSION WIRE 2200LBS. WOOL 13 TIMES AND TOOL FREE. POOH. ON SURFACE RECOVER 14" FISH WIRE.	1-7/8" RS + SWJ + 5' MRTS + KJ + 5' MRTS + EAJ 400PSI + MR SUB + KJ + 3' MRTS + TB/JAR + 2' MRTS. TOTAL LENGTH 30FT IN LUB.																											
10/7/2024 BERANTAI WELLHEAD BRWA-19 SET PXX PLUG	RUN#01 RIH 2.80" DRIFT UNTIL TRSCSSV @487FT-THF (174.9M-MDDF) AND POOH. TOOL ON SURFACE. RECOVER 2.80" DRIFT (NO FLUID LEVEL WAS DETECTED) RUN#02 RIH 2.81" X-LINE + PXX PLUG AND SET @487FT-THF (174.9M-MDDF). JAR DOWN SEVERAL TIMES AND SET. PERFORM PULL TEST 500LBS. POOH. RECOVER X-LINE AND PIN SHEARED OFF.	1-7/8" RS + SWJ + 5' N/STEM + KJ + 3' N/STEM + 20" SSI + QLS. TOTAL LENGTH 17FT IN LUB.																											
	<table border="1"> <tr> <th>Rating (by Operator)</th> <th colspan="3">STRONG</th> <th colspan="3">ADEQUATE</th> <th colspan="3">IMPROVEMENT NEEDED</th> </tr> <tr> <td></td> <td>10</td> <td>9</td> <td>8</td> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> </tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2								
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED																						
	10	9	8	7	6	5	4	3	2																				
Comments by Operator (please specify competency gaps / area of improvement)																													

Type of Task		Tasks Performed	Assessor Comment
JOB DETAIL:			
DATE	WELL NO.	JOB TYPE	STATUS (COMPLETE / INCOMPLETE)
25/7/2024 27.6.24	LRA-30	FISHING JOB	COMPLETE
7/7/2024			
8/7/2024	BRWA-19	SET PXX PLUG AT TRSCSSV.	COMPLETE
23/7/2024		SET BPV/TWCV T TUBING HANGER	
		LEAK DIAGNOSTIC FOR WELLHEAD CONNECTION	

To be completed by verifier (FSM)

SUMMARY OF OVERALL PERFORMANCE

		Weight	Score	
			Total	%
A	Safety Awareness	20	#REF!	#REF!
B	Work Performance	20	#REF!	#REF!
C	Technical Skills	60	52	44.571
	1. Pre-Job Preparation	8		
	2. Surface Equipment Rig-up	7		
	3. Tools / Equipment Preparation	8		
	4. Equipment Problem Troubleshooting	9		
	5. Downhole Tools Servicing/Redressing/Maintenance	6		
	6. Tools Inventory & Reporting	7		
	7. Equipment Operation	7		
D	TOTAL (A+B+C)	100		#REF!