

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	SAIDED EVES	COB Date	13/6/2023
Position	SLICKLINE ASSISTANT	RTB Date	11/7/2023
Client	SEAH	Location	NORTH SABAH
Platform	NORTHS SABAH	Well	SJ-610A, SJ-609A, SJ-601L & SF-506
Assessed By	Name: YUZIE YUSSOF		Position: SLICKLINE OPERATOR

RATING LEGEND:

STRONG Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent

ADEQUATE Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good

IMPROVEMENT NEEDED Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)
---------------------	-------------------------------------

	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
	10	9	8	7	6	5	4	3	2

Safety Awareness (20%)

- a. Usage of Personal Protective Equipment
- b. Participation in ACT
- c. Understanding of PTW System
- d. Worksite House Keeping

✓									
✓									
✓									
✓									


Work Performance (20%)

- e. Initiative and Creativity
- f. Decision Making Capability
- g. Understanding of Job Scope
- h. Tools Inventory and Reporting
- i. Work Quality
- j. Reporting
- k. Punctuality and Time Keeping
- l. Teamwork
- m. Communication
- n. Leadership Skills
- o. Adaptability to Work Environment/Surrounding
- p. Attitude
- q. Discipline

	✓								
		✓							
	✓								
✓									
✓									
✓									
✓									
✓									
			✓						
✓	✓								
✓									

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

KEEP IT UP

Assessed By [Operator]	
Name	YUZIE YUSSOF
Date	30/10/2023

Type of Task	Tasks Performed	Assessor Comment	
JOB DETAIL:			
DATE	WELL NO.	JOB TYPE	STATUS (COMPLETE / INCOMPLETE)
12/10/2023	SJ-610A	WAX CUT	COMPLETED
16/10/2023	SJ-609A	WAX CUT	COMPLETED
24/10/2023	SJ-601L	STROM CHOKE CHANGE OUT	COMPLETED
30/10/2023	SF-506	WAX CUT	COMPLETED

To be completed by verifier (FSM)

SUMMARY OF OVERALL PERFORMANCE

		Weight	Score	
			Total	%
A	Safety Awareness	20	#REF!	#REF!
B	Work Performance	20	#REF!	#REF!
C	Technical Skills	60	52	44.571
	1. Pre-Job Preparation	8		
	2. Surface Equipment Rig-up	7		
	3. Tools / Equipment Preparation	8		
	4. Equipment Problem Troubleshooting	9		
	5. Downhole Tools Servicing/Redressing/Maintenance	6		
	6. Tools Inventory & Reporting	7		
	7. Equipment Operation	7		
D	TOTAL (A+B+C)	100		#REF!

Type of Task	Tasks Performed	Assessor Comment								
6. Tools Inventory & Reporting	Reinventory tools and record movement tools to any package.									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
7. Equipment Operation	[Operator to rate TSA / SA / SSA competency in operating the equipment]									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
	Power Pack									
	Air Compressor									
	GenSet									
	Control Panel									
	Test Pump									
	Pressure Control Equipment									
	Mast									
Weight & Measuring Devices										
Downhole Tools										
Total		0	0	0	0	0	0	0	0	0
Comments by Operator [please specify competency gaps / area of improvement]										
EXECUTE THE WELL SERVICES OPERATION (IF ANY) (Operating Winch)										
Date / Location / Well No. / Job Type	Activity Summary	Toolstring Configuration								
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
Comments by Operator [please specify competency gaps / area of improvement]										

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment								
1. Pre-Job Preparation	A) perform check list equipment B) check due date equipment C) ensure all tool string at worksite D) ensure all pressure hose PP to RSU at worksite E) make sure PTW sign by authorizer before approval sign F) toolbox talk before start the job G) make sure hand tools are complete at worksite									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
2. Surface Equipment Rig-up	Above of BOP:- 3" (stuffing box, 8f lubricator, 8f lubricator, 8f lubricator, QTS) Below BOP:- 3" (4F/8F lubricator, Ball valve, 2F lubricator - prepare manifold for bleed pressure at lubricator									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
3. Tools / Equipment Preparation	A) 1 7/8 rope socket, 1 7/8 swivel joint, 1 7/8 normal, 1 7/8 hyd jar, 1 7/8 link jar B) ready BRASS pin, STEEL pin, aluminium pin C) CHECK THE ROLL PIN IF STILL IN GOOD CONDITION									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>	N/A									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2
5. Downhole Tools Servicing/Redressing/Maintenance	4.9 Downhole Tools A) SERVICE DHT BEFORE USED B) PINNING & FUNCTION TEST DHT C) MAKE UP TOOLSTRING D) IVENTORY TOOLS E) MAKE SURE SIZE TOOLS A CORRECT F) CHECK ANY FAULTY ON DHT THAT BEING USED G) ENSURE ALL SHARP EDGES BEING FILE TO PREVENT FROM HAND INJURIED H) TIGHTEN ALL TOOLS CONNECTION BEFORE RIH									
	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED		
		10	9	8	7	6	5	4	3	2