



### CUSTOMER SATISFACTION SURVEY

Client : PCSB SKA - ROCOIL Location (Platform) : D35DP-A  
 Service(s) : GRCCCL, & MPLT Date : 16/11/23 - 8/12/23  
 Well : 119, 117, 108 Package : EMITE  
 Personnel on Board  
 Field Engineer/Supervisor/Wireline Operator : M ARIFIN  
 Crew/Wireline Assistants :  
 Others (Please specify) :  
 :

Description	Rating*	Remarks/Comment
<b><u>Safety</u></b>		
Personnel Protective Equipment (PPE)	4	
Safety Awareness	4	
Housekeeping	4	
<b><u>Service Quality</u></b>		
Job Planning & Preparation	4	
Operation Efficiency	4	
Quality of Job Execution	4	
<b><u>Personnel</u></b>		
Professionalism of Personnel	4	
Performance & Efficiency	4	
Communication	4	
Technical Knowledge	4	
Time Keeping (Punctuality)	4	
<b><u>Equipment</u></b>		
Equipment & Tool Compatibility	4	
Inventories System	4	
<b><u>Technical Support</u></b>		
Response / Feedback from Town Field	4	
Technical Advice	4	
Delivery of Spares and Back-ups	4	
<b><u>Reporting</u></b>		
Daily Report	4	
QA/QC Data	4	
<b><u>Overall Service Performance</u></b>		
Does The Service Objective(s) Met?	4	
<b><u>Areas of Improvement (if any)</u></b>		
: Good keep it up your good works.		

**Assessed by**  
 Client Representative  
 Name : CHRU BIT  
 Date : 8/12/23  
 Signature :

**Agreed by**  
 Dimension's Bid Field Engineer/Wireline Operator/Supervisor  
 Name : M ARIFIN  
 Date : 8/12/23  
 Signature :

(This section below to fill up by Management)

**Comment / Action Taken / Follow Up**

**CSS Running Number :**

**Action By**  
 DB Technical Engineer :  
 Name :  
 Date :  
 Signature :

**Reviewed & Approved by**  
 DB Field Service Manager :  
 Name :  
 Date :  
 Signature :

**Rating\* 1 - Poor, 2 - Unsatisfactory, 3 - Satisfactory, 4 - Very Satisfactory, 5 - Outstanding**

**Note : Please refer to OP-REF/CSS-01 : CSS Rating Level & Description for evaluation**