

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 1: To be completed by Assessor)

Name	SAIDED BIN EVES	COB Date	30/07/2024
Position	SLICKLINE ASSISTANT III	RTB Date	27/08/2024
Client	NORTH SABAH	Location	SJIT-B
Platform	HML	Well	SJ-206A, SJ-204L, SJ-203L, SJ-201L & SJ-202A
Assessed By	Name: SUPARDI Position: SENIOR OPERATOR		

RATING LEGEND:

STRONG	Performance consistently exceeded expectations in all essential areas of responsibility, and the quality of work overall was excellent
ADEQUATE	Performance consistently met expectations in all areas of responsibility, at times possibly exceeding expectations, and the quality of work overall was very good
IMPROVEMENT NEEDED	Performance did not consistently met expectations - performance failed to meet expectations in one or more essential areas of responsibility

Assessment Criteria	Rating (Please ✓ where appropriate)
---------------------	-------------------------------------

Safety Awareness (20%)

- Usage of Personal Protective Equipment
- Participation in ACT
- Understanding of PTW System
- Worksite House Keeping

STRONG			ADEQUATE			IMPROVEMENT NEEDED		
10	9	8	7	6	5	4	3	2
✓								
✓								
✓								
✓								


Work Performance (20%)

- Initiative and Creativity
- Decision Making Capability
- Understanding of Job Scope
- Tools Inventory and Reporting
- Work Quality
- Reporting
- Punctuality and Time Keeping
- Teamwork
- Communication
- Leadership Skills
- Adaptability to Work Environment/Surrounding
- Attitude
- Discipline

		✓						
		✓						
		✓						
		✓						
	✓							
		✓						
	✓							
✓								
✓								
	✓							
	✓							
	✓							
	✓							

REMARKS/COMMENTS/FEEDBACK ON PERFORMANCE OR AREAS OF IMPROVEMENT:

- Have strong ability in Rigging up/down surface equipment.
- minimal supervision on selecting proper tool string.
- Must improve knowledge on completion
- Ready to go next level.

Assessed By [Operator]	
Name	SUPARDI
Date	27/8/2024

DIMENSION BID

SLICKLINE ASSISTANT PERFORMANCE ASSESSMENT FEEDBACK

(PART 2: To be completed by Employee and Assessor)

Type of Task	Tasks Performed	Assessor Comment																			
1. Pre-Job Preparation	1) Performed pre start checklist on Equipment. 2) To verify all hose was tight and no leak. 3) Ensure all tools that needed to be run on that day prepared. 4) Check diesel, coolant, engine oil, and hydraulic oil on PP. 5) Check on RSU condition. 6) Walk the line to ensure hose fit for use and no crack/lea																				
	<table border="1"> <tr> <th>Rating (by Operator)</th><th colspan="3">STRONG</th><th colspan="3">ADEQUATE</th><th colspan="3">IMPROVEMENT NEEDED</th></tr> <tr> <td></td><td>10</td><td>9</td><td>8</td><td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td></tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												
2. Surface Equipment Rig-up	1) Reposition wireline equipment such as power pack, Reel skid unit, Swcp, PTU and gantry crane 2) Make up PCE. 3) Discard slickline wire. 4) Make up new Rope socket. 5) Hook up all hoses. 6) Make up tools string. 7) Pressure test PCE.																				
	<table border="1"> <tr> <th>Rating (by Operator)</th><th colspan="3">STRONG</th><th colspan="3">ADEQUATE</th><th colspan="3">IMPROVEMENT NEEDED</th></tr> <tr> <td></td><td>10</td><td>9</td><td>8</td><td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td></tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												
3. Tools / Equipment Preparation	1) Service and function test tools on surface before RIH. 2) Pinning and function test down hole tools. 3) Make up tools string and double check all connection. 4) Perform preventive maintenance on down hole tools inside tools box.																				
	<table border="1"> <tr> <th>Rating (by Operator)</th><th colspan="3">STRONG</th><th colspan="3">ADEQUATE</th><th colspan="3">IMPROVEMENT NEEDED</th></tr> <tr> <td></td><td>10</td><td>9</td><td>8</td><td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td></tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												
4. Equipment Problem Troubleshooting <i>[Please state type of equipment and describe troubleshooting job performed]</i>	N/A																				
	<table border="1"> <tr> <th>Rating (by Operator)</th><th colspan="3">STRONG</th><th colspan="3">ADEQUATE</th><th colspan="3">IMPROVEMENT NEEDED</th></tr> <tr> <td></td><td>10</td><td>9</td><td>8</td><td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td></tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												
5. Downhole Tools Servicing/Redressing/Maintenance	1) Service down hole tools. 2) Check GS 3" share pin with prong and function test on surface before pull FXE INSERT VALVE. 3) Check drift 2.867" and 2.735" and check all connection. 4) Check and Repln 2.813" x-line with prong and funtion test on surface before make up on FXE INSERT VALVE 5) Prepare gauge ring 2.72" 6) Prepare wire scratcher 2.5" - 3.0"																				
	<table border="1"> <tr> <th>Rating (by Operator)</th><th colspan="3">STRONG</th><th colspan="3">ADEQUATE</th><th colspan="3">IMPROVEMENT NEEDED</th></tr> <tr> <td></td><td>10</td><td>9</td><td>8</td><td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td></tr> </table>	Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED				10	9	8	7	6	5	4	3	2
Rating (by Operator)	STRONG			ADEQUATE			IMPROVEMENT NEEDED														
	10	9	8	7	6	5	4	3	2												

Type of Task		Tasks Performed	Assessor Comment
JOB DETAIL:			
DATE	WELL NO.	JOB TYPE	STATUS (COMPLETE / INCOMPLETE)
5/8/2024	SJ-206A	TCC & WAX CUT	COMPLETED
16/8/2024	SJ-203L	WAX CUT	SUSPENDED
18/8/2024	SJ-204L	B7 CHANGE OUT	COMPLETED
22/8/2024	SJ-201L	TCC & GLVC	COMPLETED
24/8/2024	SJ-202A	TCC, SET PLUG & GLVC	IN PROGRESS

To be completed by verifier (FSM)

SUMMARY OF OVERALL PERFORMANCE

		Weight	Score	
			Total	%
A	Safety Awareness	20	#REF!	#REF!
B	Work Performance	20	#REF!	#REF!
C	Technical Skills	60	52	44.571
	1. Pre-Job Preparation	8		
	2. Surface Equipment Rig-up	7		
	3. Tools / Equipment Preparation	8		
	4. Equipment Problem Troubleshooting	9		
	5. Downhole Tools Servicing/Redressing/Maintenance	6		
	6. Tools Inventory & Reporting	7		
	7. Equipment Operation	7		
D	TOTAL (A+B+C)	100		#REF!